

	<p>A2043 NO. 8200105502 - 8200105503 - 8200105504 - 8200105505</p> <p>APOIO ESCAPE PARTE CENTRO</p> <p>DACIA DUSTER (HS_): 2.0 02.2012/>>> 98KW 133CV 1998CC</p> <p>47x50x29mm 2f-17x7mm</p>		<p>A2101 NO. 6001548160 - 8200014932 - 8200297939 - 8200358147 - 8200395661</p> <p>APOIO CAIXA VELOCIDADES</p> <p>DACIA DUSTER (HS_): 1.6 16V 04.2010/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_): 1.6 16V 4x4 06.2010/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_): 1.6 16V LPG 04.2011/01.2018 77K2 105CV 1598CC - DACIA DUSTER (HS_): 1.6 16V Hi-Flex 08.2010/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_): 1.5 dCi 04.2010/01.2018 63KW 86CV 1461CC - DACIA DUSTER (HS_): 1.5 dCi 10.2010/01.2018 66KW 90CV 1461CC - DA...</p> <p>152x70x57mm 1f-d11mm 2f-d17mm</p>
	<p>A2310 NO. 112100024R - 112102118R - 112845638R - 113756731R</p> <p>APOIO DO MOTOR FRENTE LADO DIREITO</p> <p>DACIA DUSTER (HS_): 1.5 dCi 04.2010/01.2018 63KW 86CV 1461CC - DACIA DUSTER (HS_): 1.5 dCi 10.2010/01.2018 66KW 90CV 1461CC - DACIA DUSTER (HS_): 1.5 dCi 06.2010/01.2018 79KW 107CV 1461CC - DACIA DUSTER (HS_): 1.5 dCi 08.2013/01.2018 80KW 109CV 1461CC - DACIA DUSTER (HS_): 1.5 dCi 08.2013/01.2018 81KW 110CV 1461CC</p> <p>232x129x206mm 3f-d16mm 4f-d12mm 1f-d10mm</p>		<p>A2355 NO. 1f-d10mm 1f-d12mm 3f-d13mm 3f-d16mm</p> <p>APOIO DO MOTOR LADO DIREITO</p> <p>DACIA DUSTER (HS_): 1.5 dCi 04.2010/01.2018 63KW 86CV 1461CC - DACIA DUSTER (HS_): 1.5 dCi 10.2010/01.2018 66KW 90CV 1461CC - DACIA DUSTER (HS_): 1.5 dCi 06.2010/01.2018 79KW 107CV 1461CC - DACIA DUSTER (HS_): 1.5 dCi 08.2013/01.2018 80KW 109CV 1461CC - DACIA DUSTER (HS_): 1.5 dCi 08.2013/01.2018 81KW 110CV 1461CC</p> <p>200x222x127mm 1f-d10mm 1f-d12mm 3f-d13mm 3f-d16mm</p>
	<p>A2706 NO. 55419JD60C</p> <p>APOIO DIFERENCIAL EIXO TRASEIRO</p> <p>DACIA DUSTER Caixa/SUV 1.2 TCe 125 4x4 (HSAU) desde 10.2013 92KW 125CV 1197CC H5F 410 8212AEF - DACIA DUSTER Caixa/SUV 1.5 dCi 4x4 desde 04.2011 66KW 90CV 1461CC K9K 884 K9K 894 8212ACM</p> <p>335x84x86mm 2f-d14mm</p>		<p>A32744 NO. 543A06915R - 6001547499 - 6001548403 - 8200275528 - 8200307941 - 8200651172 - 8200723741 - 820087629...</p> <p>APOIO SUPORTE AMORTECEDOR FRENTE (GASTA 2 UNIDADES)</p> <p>DACIA DUSTER (HS_) 1.2 TCe 125 10.2013/01.2018 92KW 125CV 1197CC H5F 404 H5F 408 8212ADK 8212ADM - DACIA DUSTER (HS_) 1.5 dCi 04.2010/01.2018 63KW 86CV 1461CC K9K 830 K9K 796 8212AAI 8212AAJ 8212ABU - DACIA DUSTER (HS_) 1.5 dCi (HSAJ) 10.2010/01.2018 66KW 90CV 1461CC K9K 884 K9K 612 K9K 892 K9K 626 8212ACK 8212ACF - DACIA DUSTER (HS_) 1.5 dCi (HSMC) 06.2010/01.2018 79KW 107CV 1461CC K9K 896 K9K 89...</p> <p>d104x45mm d79x20mm d56x27mm 1f-d15mm 1f-d16mm 1r-d12mm</p>
	<p>E0267-M NO. 112381035R - 112383905R</p> <p>ESTICADOR SUPORTE APOIO MOTOR TRAS</p> <p>DACIA DUSTER (HS_): 1.2 TCe 125 10.2013/01.2018 92KW 125CV 1197CC</p> <p>170x60x55mm 1f-d12mm 1f-d14mm</p>		<p>F4145 NO. 6001548402 - 6001549290 - 8200499414 - 8200814709</p> <p>FOLE CAPA PROTEÇÃO AMORTECEDOR FRENTE (GASTA 2 UNIDADES)</p> <p>DACIA DUSTER (HS_) 1.2 TCe 125 10.2013/01.2018 92KW 125CV 1197CC - DACIA DUSTER (HS_) 1.2 TCe 125 4x4 06.2015/01.2018 92KW 125CV 1197CC - DACIA DUSTER (HS_) 1.6 16V 04.2010/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_) 1.6 16V 4x4 06.2010/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_) 1.6 16V LPG 04.2011/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_) 1.6 16V Hi-Flex 08.2010/01.2018 77KW 105...</p> <p>d75x220mm 1f-d55mm 1f-d18mm</p>
	<p>F4289 NO. 8201108358</p> <p>FOLE DIREÇÃO (GASTA 2 UNIDADES)</p> <p>DACIA DUSTER (HS_) 1.2 TCe 125 10.2013/01.2018 92KW 125CV 1197CC H5F 404 H5F 408 8212ADK 8212ADM - DACIA DUSTER (HS_) 1.5 dCi 04.2010/01.2018 63KW 86CV 1461CC K9K 830 K9K 796 8212AAI 8212AAJ 8212ABU - DACIA DUSTER (HS_) 1.5 dCi 08.2013-01.2018 80KW 109CV 1461CC K9K 658 K9K 666 K9K 858 K9K 856 K9K 667 8212ADG - DACIA DUSTER (HS_) 1.5 dCi (HSAJ) 10.2010/01.2018 66KW 90CV 1461CC K9K 884 K9K 612 K9K...</p> <p>d68x152mm 1f-d12mm 1f-d50mm</p>		<p>F4290 NO. 8201108358</p> <p>FOLE DIREÇÃO (GASTA 2 UNIDADES)</p> <p>DACIA DUSTER (HM_) 1.2 TCe 125 (HMMA) desde 10.2017 92KW 125CV 1197CC H5F 408 3333BIP - DACIA DUSTER (HM_) 1.2 TCe 125 4x4 (HMMA) desde 10.2017 92KW 125CV 1197CC H5F 410 8212ADO 3333BIQ - DACIA DUSTER (HM_) 1.5 dCi 110 (HMAB) desde 10.2017 80KW 109CV 1461CC K9K 667 K9K 656 3333BIN - DACIA DUSTER (HM_) 1.5 dCi 110 4x4 (HMAB) desde 10.2017 80KW 109CV 1461CC K9K 658 3333BIO - DACIA DUSTER (HM_) 1.5 d...</p> <p>d72x210mm 1f-d13mm 1f-d51mm</p>
	<p>F9066H-I NO. 392413815R - 7701209990</p> <p>FOLE TRANSMISSÃO JUNTO RODA</p> <p>DACIA DUSTER (HS_) 1.2 TCe 125 10.2013/01.2018 92KW 125CV 1197CC - DACIA DUSTER (HS_) 1.5 dCi 04.2010/01.2018 63KW 86CV 1461CC - DACIA DUSTER (HS_) 1.5 dCi 10.2010/01.2018 66KW 90CV 1461CC - DACIA DUSTER (HS_) 1.5 dCi 4x4 10.2010/01.2018 66KW 90CV 1461CC - DACIA DUSTER (HS_) 1.5 dCi 06.2010/01.2018 79KW 107CV 1461CC - DACIA DUSTER (HS_) 1.5 dCi 08.2013/01.2018 80KW 109CV 1461CC - DACIA DUSTER (HS_) 1.5 dCi 08.2013/01.2018 80KW 109CV 1461CC - DACIA DUSTER...</p> <p>d94x120mm 1f-d28mm 1f-d84mm</p>		<p>KN96019 NO. 7701475118</p> <p>KIT ORINGS DO RADIADOR DO ÓLEO</p> <p>DACIA DUSTER (HM_) 1.2 TCe 125 (HMMA) desde 10.2017 92KW 125CV 1197CC H5F 408 3333BIP - DACIA DUSTER (HM_) 1.2 TCe 125 4x4 (HMMA) desde 10.2017 92KW 125CV 1197CC H5F 410 8212ADO 3333BIQ - DACIA DUSTER (HM_) 1.5 dCi 110 (HMAB) desde 10.2017 80KW 109CV 1461CC K9K 667 K9K 656 3333BIN - DACIA DUSTER (HM_) 1.5 dCi 110 4x4 (HMAB) desde 10.2017 80KW 109CV 1461CC K9K 658 3333BIO - DACIA DUSTER (HM_) 1.5 d...</p> <p>d70x5mm d30x5mm d25x3mm d16mm 1f-d20mm 1f-d18mm</p>
	<p>L25623 NO. 8200059575 - 8200059578 - 8200079112 - 8200079113 - 8200379950 - 8200596157</p> <p>CASQUILHO INTERIOR MANETE VELOCIDADES</p> <p>DACIA DUSTER (HS_): 2.0 02.2012/>>> 98KW 133CV 1998CC - DACIA DUSTER (HS_): 2.0 4x4 02.2012/>>> 99KW 135CV 1998CC</p> <p>d16x65mm 1f-d11mm</p>		<p>L81653 NO. 7701056972 - 7701060158</p> <p>CASQUILHO COBERTURA TAMPA DO MOTOR</p> <p>LANCIA DUSTER (HS_): 1.5 dCi 04.2010/01.2018 63KW 86CV 1461CC</p> <p>d37/31mm d17/11mm 1f-d15mm</p>
	<p>P1129 NO. 465310981R - 6001551783</p> <p>CAPA DE PEDAL DO TRAVÃO</p> <p>DACIA DUSTER (HM_) 1.3 TCe 150 (HMM3) desde 01.2019 110KW 150CV 1332CC H5H 480 H5H 470 H5H 490 3333BKZ - DACIA DUSTER (HS_) 1.2 TCe 125 10.2013/01.2018 92KW 125CV 1197CC H5F 404 H5F 408 8212ADK 8212ADM - DACIA DUSTER (HS_) 1.2 TCe 125 4x4 06.2015/01.2018 92KW 125CV 1197CC H5F 410 8212ADO - DACIA DUSTER (HS_) 1.5 dCi 08.2013/01.2018 80KW 109CV 1461CC K9K 658 K9K 666 K9K 858 K9K 856 K9K 667 8212ADG ...</p> <p>75x53x10mm 1f-d-52x33mm</p>		<p>Q2009 NO.</p> <p>UNIÃO DE ESCAPE 47/52,5x90mm</p> <p>DACIA - DUSTER - 1.6 16V (APÓS 04.10) 105cv 1598cc Veículo todo-terreno fechado - DACIA - DUSTER - 1.5 dCi (APÓS 04.10) 86cv 1461cc Veículo todo-terreno fechado</p> <p>90x58x78mm 1f-d47mm</p>

	<p>R080330 NO. 14875-00QAB - 7700101229 - 8200035903 - 8200134513</p> <p>TUBO RIGIDO REFRIGERAÇÃO</p> <p>DACIA DUSTER (HS_) 1.6 16V 04.2010/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_) 1.6 16V 4x4 06.2010/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_) 1.6 16V LPG 04.2011/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_) 1.6 16V Hi-Flex 08.2010/01.2018 77KW 105CV 1598CC</p> <p>B365-26/26mm 76-320mm 1p-d20x45mm 1f-6x13</p>		<p>R085226 NO. 1404200Q0C - 8200934107</p> <p>TUBO EXTRACTOR COMBUSTIVEL</p> <p>DACIA DUSTER (HS_) 1.5 dCi (04.2010 - 01.2018) 63kw 86cv 1461cm3 SUV DACIA DUSTER (HS_) 1.5 dCi (08.2013 - 01.2018) 80kw 109cv 1461cm3 SUV DACIA DUSTER (HS_) 1.5 dCi (08.2013 - 01.2018) 81kw 110cv 1461cm3 SUV DACIA DUSTER (HS_) 1.5 dCi (HSAJ) (10.2010 - 01.2018) 66kw 90cv 1461cm3 SUV DACIA DUSTER (HS_) 1.5 dCi (HSMC) (06.2010 - 01.2018) 79kw 107cv 1461cm3 SUV DACIA DUSTER (HS_) 1.5 dCi 4x4 (10.2010)...</p> <p>B325-5/5mm 66x340x60x66mm</p>
	<p>R085226 NO. 1404200Q0C - 8200934107</p> <p>TUBO EXTRACTOR COMBUSTIVEL</p> <p>DACIA LODGY (JS_) 1.5 Blue dCi 115 (JSJT) (08.2018 -) 85kw 116cv 1461cm3 Veículo multiuso DACIA LODGY (JS_) 1.5 Blue dCi 95 (JSJL, JSN7) (08.2018 -) 70kw 95cv 1461cm3 Veículo multiuso DACIA LODGY (JS_) 1.5 dCi (03.2012 -) 66kw 90cv 1461cm3 Veículo multiuso DACIA LODGY (JS_) 1.5 dCi (01.2013 -) 79kw 107cv 1461cm3 Veículo multiuso DACIA LODGY (JS_) 1.5 dCi (06.2015 -) 80kw 109cv 1461cm3 Veículo mult...</p> <p>B325-5/5mm 66x340x60x66mm</p>		<p>R223276 NO. 7701061051</p> <p>TUBO LIGAÇÃO TERMOSTATO</p> <p>DACIA DUSTER (HS_) 1.5 dCi 04.2010/01.2018 63KW 86CV 1461CC - DACIA DUSTER (HS_) 1.5 dCi 10.2010/01.2018 66KW 90CV 1461CC</p> <p>B117-15/19mm 78-73mm ch-d20-50mm</p>
	<p>R224078 NO. 1655600QAM - 8200331958</p> <p>TUBO ADMISSÃO FILTRO DE AR</p> <p>DACIA DUSTER (HM_) 1.3 TcE 150 (HMM3) desde 01.2019 110KW 1332CC H5H 480 H5H 470 H5H 490 3333BKZ - DACIA DUSTER (HS_) 1.5 dCi 04.2010/01.2018 63KW 86CV 1461CC K9K 830 K9K 796 8212AAI 8212AAY 8212ABU - DACIA DUSTER (HS_) 1.5 dCi 08.2013/01.2018 80KW 109CV 1461CC K9K 658 K9K 666 K9K 858 K9K 856 K9K 667 8212ADG - DACIA DUSTER (HS_) 1.5 dCi 08.2013/01.2018 81KW 110CV 1461CC K9K 858 K9K 856 K9K 6...</p> <p>260x40x61mm 45x140x113x71mm ch-d22x33mm</p>		<p>R224548 NO. 8200469423 - 8200598010</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA DUSTER (HS_) 1.5 dCi 04.2010/01.2018 63K2 86CV 1461CC K9K 830 K9K 796 8212AAI 8212AAY 8212ABU</p> <p>B710-48/57mm 140-99-84-190-160-72-164mm</p>
	<p>R224723 NO. 1446000Q1D - 144600835R - 144601524R - 144602760R - 144606171R - 144606189R - 144606515R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA DUSTER (HM_) 1.5 dCi 110 (HMAB) desde 10.2017 80KW 109CV 1461CC K9K 667 K9K 656 3333BIN - DACIA DUSTER (HM_) 1.5 dCi 110 4x4 (HMAB) desde 10.2017 80KW 109CV 1461CC K9K 658 3333BIO - DACIA DUSTER (HM_) 1.5 dCi 90 (HMAA) desde 10.2017 66KW 90CV 1461CC K9K 656 3333BIM - DACIA DUSTER (HS_) 1.5 dCi 08.2013/01.2018 80KW 109CV 1461CC K9K 658 K9K 666 K9K 858 K9K 856 K9K 667 8212ADG - DACIA DUSTER (H...</p> <p>B115-49/52mm</p>		<p>R224759 NO. 144604599R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA DUSTER (HM_) 1.5 dCi 110 (HMAB) desde 10.2017 80KW 109CV 1461CC K9K 667 K9K 656 3333BIN - DACIA DUSTER (HM_) 1.5 dCi 110 4x4 (HMAB) desde 10.2017 80KW 109CV 1461CC K9K 658 3333BIO - DACIA DUSTER (HM_) 1.5 dCi 90 (HMAA) desde 10.2017 66KW 90CV 1461CC K9K 656 3333BIM - DACIA DUSTER (HS_) 1.5 dCi 08.2013/01.2018 80KW 109CV 1461CC K9K 658 K9K 666 K9K 858 K9K 856 K9K 667 8212ADG - DACIA DUSTER (H...</p> <p>B650-50/52mm 56-92-108-156-185-77-46-45mm</p>
	<p>R224764 NO. 144606189R - 144600835R - 144601524R - 144602760R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA DUSTER (HM_) 1.5 dCi 110 (HMAB) desde 10.2017 80KW 109CV 1461CC K9K 667 K9K 656 3333BIN - DACIA DUSTER (HM_) 1.5 dCi 110 4x4 (HMAB) desde 10.2017 80KW 109CV 1461CC K9K 658 3333BIO - DACIA DUSTER (HM_) 1.5 dCi 90 (HMAA) desde 10.2017 66KW 90CV 1461CC K9K 656 3333BIM - DACIA DUSTER (HS_) 1.5 dCi 08.2013/01.2018 80KW 109CV 1461CC K9K 658 K9K 666 K9K 858 K9K 856 K9K 667 8212ADG - DACIA DUSTER (H...</p> <p>B270-46/47mm 86-89-78mm</p>		<p>R224773 NO. 144609116R - 144609369R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA DUSTER (HM_) 1.5 dCi 110 (HMAB) desde 10.2017 80KW 109CV 1461CC K9K 667 K9K 656 3333BIN - DACIA DUSTER (HM_) 1.5 dCi 110 4x4 (HMAB) desde 10.2017 80KW 109CV 1461CC K9K 658 3333BIO - DACIA DUSTER (HM_) 1.5 dCi 90 (HMAA) desde 10.2017 66KW 90CV 1461CC K9K 656 3333BIM - DACIA DUSTER (HS_) 1.5 dCi 08.2013/01.2018 80KW 109CV 1461CC K9K 658 K9K 666 K9K 858 K9K 856 K9K 667 8212ADG - DACIA DUSTER (H...</p> <p>B650-41/41mm 70-82-101-156-1244-64-81-80mm</p>
	<p>R224819 NO. 1412000Q0J - 1412000Q1E - 1412000Q1G - 223211229R - 223211568R - 223211824R - 223214402R - 820091250</p> <p>TUBO VALVULA REGULADOR DE VELOCIDADE</p> <p>DACIA DUSTER (HS_) 1.5 dCi 08.2013/01.2018 81KW 110CV 1461CC K9K 858 K9K 856 K9K 658 K9K 898 - DACIA DUSTER (HS_) 1.5 dCi (HSMC) 06.2010/01.2018 79KW 107CV 1461CC K9K 896 K9K 898 8212ABE 8212ABG 8212ABZ - DACIA DUSTER (HS_) 1.5 dCi 4x4 (HSMC, HSMC) 10.2010/01.2018 81KW 110CV 1461CC K9K 856 K9K 898 K9K 858 K9K 896 8212ABD 8212ABI 8212ABY</p> <p>B67-6/6mm</p>		<p>R230055 NO.</p> <p>TUBO ADMISSÃO FILTRO DE AR</p> <p>DACIA DUSTER (HM_) 1.3 TcE 130 (HMMF) desde 01.2019 96KW 131CV 1332CC H5H 480 H5H 470 3333BKZ - DACIA DUSTER (HM_) 1.3 TcE 130 4x4 (HMMF) desde 01.2019 96KW 131CV 1332CC H5H 470 H5H 480 H5H494 3333BMB - DACIA DUSTER (HM_) 1.3 TcE 150 (HMM3) desde 01.2019 110KW 150CV 1332CC H5H 480 H5H 470 H5H 490 3333BKZ - DACIA DUSTER (HM_) 1.3 TcE 150 4x4 (HMM3) desde 01.2019 110KW 150CV 1332CC H5H 470 H5H 480 H...</p> <p>B505-62/82x41mm 100-190-158-56mm</p>
	<p>R8210 NO. 223211229R - 223214402R</p> <p>TUBO DA VALVULA DO REGULADOR DE VELOCIDADE</p> <p>DACIA DUSTER (HS_) 1.5 dCi 08.2013/01.2018 81KW 110CV 1461CC K9K 858 K9K 856 K9K 658 K9K 898 - DACIA DUSTER (HS_) 1.5 dCi (HSMC) 06.2010/01.2018 79KW 107CV 1461CC K9K 896 K9K 898 8212ABE 8212ABG 8212ABZ - DACIA DUSTER (HS_) 1.5 dCi 4x4 (HSMC, HSMC) 10.2010/01.2018 81KW 110CV 1461CC K9K 856 K9K 898 K9K 858 K9K 896 8212ABD 8212ABI 8212ABY</p> <p>222x82x16mm 1f-d6mm 1f-d11mm</p>		<p>R8219 NO. 1446000Q1H - 144600492R - 144605243R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA DUSTER (HS_) 1.2 TcE 125 10.2013/01.2018 92KW 125CV 1197CF H5F 404 H5F 408 8212ADM - DACIA DUSTER (HS_) 1.2 TcE 125 4x4 06.2015/01.2018 92KW 125CV 1197CC H5F 410 8212ADO - DACIA DUSTER Caixa/SUV 1.2 TcE 125 4x4 (HSAU) desde 10.2013 92KW 125CV 1197CC H5F 410 8212AEF</p> <p>B560-31/39mm 110-53-230-105-58mm</p>
	<p>RFL19610 NO. 8200140155 - 8200231833 - 8200714635</p> <p>TUBO FLEXIVEL DO ÓLEO DO TURBO</p> <p>DACIA DUSTER (HM_) 1.5 dCi 115 4x4 (HMAD) desde 10.2017 85KW 116CV 1461CC K9K 874 K9K 872 K9K 878 3333BKJ - DACIA DUSTER (HS_) 1.5 dCi 04.2010/01.2018 63KW 86CV 1461CC K9K 830 K9K 796 8212AAI 8212AAY 8212ABU - DACIA DUSTER (HS_) 1.5 dCi 08.2013/01.2018 80KW 109CV 1461CC K9K 658 K9K 666 K9K 858 K9K 856 K9K 667 8212ADG - DACIA DUSTER (HS_) 1.5 dCi 08.2013/01.2018 81KW 110CV 1461CC K9K 858 K9K 856 K9...</p> <p>B222-14/14mm 129x67x30mm 1f-d6mm 1f-6x8mm</p>		<p>RFL61319 NO. 8200310122 - 8200376094 - 8200575489 - 8200714635</p> <p>TUBO FLEXIVEL DO OLEO</p> <p>DACIA DUSTER (HM_) 1.5 dCi 110 (HMAB) desde 10.2017 80KW 109CV 1461CC K9K 667 K9K 656 3333BIN - DACIA DUSTER (HM_) 1.5 dCi 110 4x4 (HMAB) desde 10.2017 80KW 109CV 1461CC K9K 658 3333BIO - DACIA DUSTER (HM_) 1.5 dCi 115 4x4 (HMAD) desde 10.2017 85KW 116CV 1461CC K9K 874 K9K 872 K9K 878 3333BKJ - DACIA DUSTER (HM_) 1.5 dCi 90 (HMAA) desde 10.2017 66KW 90CV 1461CC K9K 656 3333BIM - DACIA DUSTER (HS_)...</p> <p>B236-11/12mm 1f-d6mm 71x96x51x31mm</p>

	<p>UAP81637 NO. 7703062072 - 8200014894</p> <p>ANILHA PROTEÇÃO TÉRMICA INJECTORES</p> <p>DACIA DUSTER (HS_) 1.5 dCi 04.2010/01.2018 63KW 86CV 1461CC K9K 830 K9K 796 8212AAI 8212AAZ 8212ABU - DACIA DUSTER (HS_) 1.5 dCi (HSAJ) 10.2010/01.2018 66KW 90CV 1461CC K9K 884 K9K 612 K9K 892 K9K 626 8212ACK 8212ACF - DACIA DUSTER (HS_) 1.5 dCi (HSMC) 06.2010/01.2018 79KW 107CV 1461CC K9K 896 K9K 898 8212ABE 8212ABG 8212ABZ - DACIA DUSTER (HS_) 1.5 dCi 4x4 (HSMC, HSMC) 10.2010/01.2018 81KW 110CV ...</p> <p>d15x3mm 1f-d7mm</p>		<p>UCRZ1068 NO. 320003602R - 320007974R - 37000-00Q0B - 370002820R - 8200945335</p> <p>CRUZETA VEIO TRANSMISSÃO LONGITUDINAL D19X56MM</p> <p>DACIA DUSTER (HM_) 1.2 TCe 125 4x4 (HMMA) desde 10.2017 92KW 125CV 1197CC H5F 410 8212ADO 3333BIQ - DACIA DUSTER (HM_) 1.5 dCi 110 4x4 (HMAB) desde 10.2017 80KW 109CV 1461CC K9K 658 3333BIO - DACIA DUSTER (HM_) 1.5 dCi 115 4x4 (HMAD) desde 10.2017 85KW 116CV 1461CC K9K 874 K9K 872 K9K 878 3333BKJ - DACIA DUSTER (HM_) 1.6 S Ce 115 4x4 (HMM1) desde 10.2017 84KW 115CV 1598CC H4M 738 H4M 730 3333BJE - ...</p> <p>d19x59x40mm</p>
	<p>UCRZ1096 NO. 391009309R</p> <p>CRUZETA TRANSMISSÃO TRIPOIDE D40MM23 DENTES</p> <p>DACIA DUSTER (HM_) 1.6 S Ce 115 (HMM1) desde 10.2017 84KW 115CV 1598CC H4M 738 3333BFI - DACIA DUSTER (HM_) 1.6 S Ce 115 4x4 (HMM1) desde 10.2017 84KW 115CV 1598CC H4M 738 H4M 730 3333BJE - DACIA DUSTER (HM_) 1.6 S Ce 115 LPG (HMM1) desde 10.2017 80KW 109CV 1598CC H4M 740 3333BHZ - DACIA DUSTER (HS_) 1.2 TCe 125 10.2013/01.2018 92KW 125CV 1197CC H5F 404 H5F 408 8212ADK 8212ADM - DACIA DUSTER (HS_) 1....</p> <p>d40mm (23 dentes)</p>		<p>UMB80660 NO. 7700106271 - 7700106383</p> <p>TAMPÃO BLOCO MOTOR</p> <p>DACIA DUSTER (HS_) 1.6 16V 04.2010/01.2018 77KW 105CV 1598CC K4M 696 K4M 690 K4M 694 K4M 842 K4M 896 8212AAE 8212AAZ 8212ACA - DACIA DUSTER (HS_) 1.6 16V 4x4 06.2010/01.2018 77KW 105CV 1598CC K4M 606 8212ABF - DACIA DUSTER (HS_) 1.6 16V Hi-Flex 08.2010/01.2018 77KW 105CV 1598CC K4M 696 8212ACJ - DACIA DUSTER (HS_) 1.6 16V LPG 04.2011/01.2018 77KW 105CV 1598CC K4M 616 K4M 642 8212ACS</p> <p>d-57,3x10mm di-52,7mm</p>
	<p>UMB80661 NO. 6001543014 - 7700274026 - 8200058022</p> <p>TAMPÃO BLOCO MOTOR</p> <p>DACIA DUSTER (HS_) 1.6 16V 04.2010/01.2018 77KW 105CV 1598CC K4M 696 K4M 690 K4M 694 K4M 842 K4M 896 8212AAE 8212AAZ 8212ACA - DACIA DUSTER (HS_) 1.6 16V 4x4 06.2010/01.2018 77KW 105CV 1598CC K4M 606 8212ABF - DACIA DUSTER (HS_) 1.6 16V Hi-Flex 08.2010/01.2018 77KW 105CV 1598CC K4M 696 8212ACJ - DACIA DUSTER (HS_) 1.6 16V LPG 04.2011/01.2018 77KW 105CV 1598CC K4M 616 K4M 642 8212ACS</p> <p>d42x8mm di-38x7mm</p>		<p>UMV25601 NO. 8200059575 - 8200059578 - 8200079112 - 8200079113 - 8200379950 - 8200596157</p> <p>MANETE PUNHO TOPO ALAVANCA MUDANÇAS 5 VELOCIDADES F18MM</p> <p>DACIA DUSTER (HS_) : 2.0 02.2012/>>> 98KW 133CV 1998CC - DACIA DUSTER (HS_) : 2.0 4x4 02.2012/>>> 99KW 135CV 1998CC</p> <p>d47x110mm 1f-d18mm</p>
	<p>UMV25611 NO. 8200059575 - 8200059578 - 8200079112 - 8200079113 - 8200379950 - 8200596157</p> <p>MANETE PUNHO TOPO ALAVANCA MUDANÇAS 5 VELOCIDADES F18MM</p> <p>DACIA DUSTER (HS_) : 2.0 02.2012/>>> 98KW 133CV 1998CC - DACIA DUSTER (HS_) : 2.0 4x4 02.2012/>>> 99KW 135CV 1998CC</p> <p>d48x110mm 1f-d18mm</p>		<p>UMV25612 NO. 8200059575 - 8200059578 - 8200079112 - 8200079113 - 8200379950 - 8200596157</p> <p>MANETE PUNHO TOPO ALAVANCA MUDANÇAS 5 VELOCIDADES F18MM</p> <p>DACIA DUSTER (HS_) : 2.0 02.2012/>>> 98KW 133CV 1998CC - DACIA DUSTER (HS_) : 2.0 4x4 02.2012/>>> 99KW 135CV 1998CC</p> <p>d49x110mm 1f-d18mm</p>
	<p>UMV25615 NO. 8200059575 - 8200059578 - 8200079112 - 8200079113 - 8200379950 - 8200596157</p> <p>MANETE PUNHO TOPO ALAVANCA MUDANÇAS 5 VELOCIDADES F18MM</p> <p>DACIA DUSTER (HS_) : 2.0 02.2012/>>> 98KW 133CV 1998CC - DACIA DUSTER (HS_) : 2.0 4x4 02.2012/>>> 99KW 135CV 1998CC</p> <p>d49x110mm 1f-d18mm</p>		<p>UMV25616 NO. 328650005R - 328650024R - 328650047R</p> <p>MANETE PUNHO TOPO ALAVANCA MUDANÇAS 6 VELOCIDADES F13MM</p> <p>DACIA DUSTER (HS_) 2.0 desde 02.2012 98KW 133CV 1998CC F4R 405 F4R 403 - DACIA DUSTER (HS_) 2.0 4x4 desde 02.2012 99KW 135CV 1998CC F4R 400 F4R 410 F4R 402</p> <p>d49x63mm 1f-d13mm</p>
	<p>UMV25617 NO. 328650005R - 328650024R - 328650047R - 328659469R - 8200021391</p> <p>MANETE PUNHO TOPO ALAVANCA MUDANÇAS 6 VELOCIDADES F14MM</p> <p>DACIA DUSTER (HS_) : 2.0 02.2012/>>> 98KW 133CV 1998CC - DACIA DUSTER (HS_) : 2.0 4x4 02.2012/>>> 99KW 135CV 1998CC</p> <p>d50x62mm 1f-d14mm</p>		<p>URL36540 NO. 12371-64130 - 12371-64140 - 12371-64141 - 8200651172</p> <p>ROLAMENTO DO APOIO SUPORTE AMORTECEDOR FRENTE COMPEMENTA A1479-C (GASTA 2 UNIDADES)</p> <p>DACIA DUSTER (HM_) 1.0 LPG (HMMT) desde 01.2019 74KW 101CV 999CC H4D 460 H4D 450 H4D 480 3333BND - DACIA DUSTER (HM_) 1.0 TCe 100 (HMMT) desde 01.2019 74KW 101CV 999CC H4D 450 H4D 460 3333BMJ - DACIA DUSTER (HM_) 1.3 TCe 130 (HMFF) desde 01.2019 96KW 131CV 1332CC H5H 480 H5H 470 3333BKY - DACIA DUSTER (HM_) 1.3 TCe 130 4x4 (HMFF) desde 01.2019 96KW 131CV 1332CC H5H 470 H5H 480 3333BMB - DACIA DUSTER...</p> <p>d56x9mm 1f-d16mm</p>
	<p>URTE6017 NO. 144652865R</p> <p>RETENTOR TUBO AR SOBREALIMENTAÇÃO D45,5X49X4,8MM</p> <p>DACIA DUSTER (HM_) 1.2 TCe 125 (HMMA) desde 10.2017 92KW 125CV 1197CC H5F 408 3333BIP - DACIA DUSTER (HM_) 1.2 TCe 125 4x4 (HMMA) desde 10.2017 92KW 125CV 1197CC H5F 410 8212ADO 3333BIQ - DACIA DUSTER (HS_) 1.2 TCe 125 10.2013/01.2018 92KW 125CV 1197CC H5F 404 H5F 408 8212ADK 8212ADM - DACIA DUSTER (HS_) 1.2 TCe 125 4x4 06.2015/01.2018 92KW 125CV 1197CC H5F 410 8212ADO - DACIA DUSTER Caixa/SUV 1.2...</p> <p>d48x5mm 1f-d45mm</p>		<p>URTE6018 NO. 140797120R</p> <p>RETENTOR TUBO AR SOBREALIMENTAÇÃO</p> <p>DACIA DUSTER (HS_) 1.5 dCi 08.2013/01.2018 80KW 109CV 1461CC K9K 658 K9K 666 K9K 858 K9K 856 K9K 667 8212ADG - DACIA DUSTER (HS_) 1.5 dCi (HSAJ) 10.2010/01.2018 66KW 90CV 1461CC K9K 884 K9K 612 K9K 892 K9K 626 8212ACK 8212ACF - DACIA DUSTER (HS_) 1.5 dCi 4x4 08.2013/01.2018 80KW 109CV 1461CC K9K 856 K9K 898 K9K 658 K9K 858 8212ADI 8212ADJ - DACIA DUSTER Caixa/SUV 1.5 dCi desde 04.2013 80KW 109CV 1...</p> <p>d46x5mm d42mm</p>
	<p>UTR1403 NO. 7701470950 - 7701471585</p> <p>TAMPÃO DEPÓSITO COMBUSTIVEL</p> <p>DACIA DUSTER (HS_) 1.5 dCi 04.2010/01.2018 63KW 86CV 1461CC K9K 830 K9K 796 8212AAI 8212AAZ 8212ABU - DACIA DUSTER (HS_) 1.5 dCi (HSAJ) 10.2010/01.2018 66KW 90CV 1461CC K9K 884 K9K 612 K9K 892 K9K 626 8212ACK 8212ACF - DACIA DUSTER (HS_) 1.5 dCi (HSMC) 06.2010/01.2018 79KW 107CV 1461CC K9K 896 K9K 898 8212ABE 8212ABG 8212ABZ - DACIA DUSTER (HS_) 1.5 dCi 4x4 10.2010/01.2018 81KW 110CV 1461CC K9K 884...</p> <p>d73x67mm d37mm</p>		<p>W5106 NO. 8200184103 - 8200185800 - 8200477938 - 8200511194</p> <p>POLIE DA CABBOTA (6 PISTAS)</p> <p>DACIA DUSTER (HS_) : 1.6 16V 04.2010/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_) : 1.6 16V 4x4 06.2010/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_) : 1.6 16V LPG 04.2011/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_) : 1.5 dCi 04.2010/01.2018 63KW 86CV 1461CC - DACIA DUSTER (HS_) : 1.5 dCi 10.2010/01.2018 66KW 90CV 1461CC - DACIA DUSTER (HS_) : 1.5 dCi 4x4 10.2010/01.2018 66KW 90CV 1461CC - DACIA D...</p> <p>d155/151mm d26mm</p>

DACIA DUSTER

	<p>W5108 NO. 12201-00QAW - 12303-00QJ - 12303-00QH - 12303-00QK - 12303-00QAY - 12303-00QBA - 12303-BN700-12...</p> <p>POLIE DA CAMBOTA (5 PISTAS)</p> <p>DACIA DUSTER (HS_): 1.6 16V 04.2010/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_): 1.6 16V 4x4 06.2010/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_): 1.6 16V LPG 04.2011/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_): 1.6 16V Hi-Flex 08.2010/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_): 1.5 dCi 04.2010/01.2018 63KW 86CV 1461CC - DACIA DUSTER (HS_): 1.5 dCi 10.2010/01.2018 66KW 90CV 1461CC - DA...</p> <p>d153.4mm 1f-d26mm</p>		<p>W5137 NO. 7700105788 - 7700107122 - 8200044050 - 8200352613 - 8200395313 - 8200544135 - 8200552236 - 82005...</p> <p>POLIE DA CAMBOTA 6 PISTAS</p> <p>DACIA DUSTER (HS_): 1.6 16V 04.2010/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_): 1.6 16V 4x4 06.2010/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_): 1.6 16V LPG 04.2011/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_): 1.6 16V Hi-Flex 08.2010/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_): 1.5 dCi 04.2010/01.2018 63KW 86CV 1461CC - DACIA DUSTER (HS_): 1.5 dCi 10.2010/01.2018 66KW 90CV 1461CC - DA...</p> <p>d155mm d26mm</p>
	<p>W5216 NO. 8200758088</p> <p>POLIE DA CAMBOTA RODA DENTADA (19 DENTES)</p> <p>DACIA DUSTER (HS_) 1.6 16V 04.2010/01.2018 77KW 105CV 1598CC K4M 696 K4M 690 K4M 694 K4M 842 K4M 896 8212AAE 8212AAZ 8212ACA - DACIA DUSTER (HS_) 1.6 16V 4x4 06.2010/01.2018 77KW 105CV 1598CC K4M 606 8212ABF - DACIA DUSTER (HS_) 1.6 16V Hi-Flex 08.2010/01.2018 77KW 105CV 1598CC K4M 696 8212ACJ - DACIA DUSTER (HS_) 1.6 16V LPG 04.2011/01.2018 77KW 105CV 1598CC K4M 616 K4M 642 8212ACS - DACIA DUSTER...</p> <p>d56x32mm 1f-26mm</p>		<p>Y3239 NO. 8200473313 - 8200610460</p> <p>PARAFUSO PERNO RODA CHAVE 17 M12x1,50x50MM (BASE CONICA)</p> <p>DACIA DUSTER (HS_) 1.2 Tce 125 10.2013/01.2018 92KW 125CV 1197CC H5F 404 H5F 408 8212ADK 8212ADM - DACIA DUSTER (HS_) 1.5 dCi 04.2010/01.2018 63KW 86CV 1461CC K9K 830 K9K 796 8212AAI 8212AAJ 8212ABU - DACIA DUSTER (HS_) 1.5 dCi (HSAJ) 10.2010/01.2018 66KW 90CV 1461CC K9K 884 K9K 612 K9K 892 K9K 626 8212ACK 8212ACF - DACIA DUSTER (HS_) 1.5 dCi (HSMC) 06.2010/01.2018 79KW 107CV 1461CC K9K 896 K9K ...</p> <p>c51mm (ch-17mm) M12x1x24mm</p>
	<p>Z57184 NO. 7703081056</p> <p>MOLAS FIXAÇÃO REV. CAVA RODA RENAULT/DACIA</p> <p>DACIA DUSTER (HS_) 1.2 Tce 125 10.2013/01.2018 92KW 125CV 1197CC - DACIA DUSTER (HS_) 1.2 Tce 125 4x4 06.2015/01.2018 92KW 125CV 1197CC - DACIA DUSTER (HS_) 1.6 16V 04.2010/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_) 1.6 16V 4x4 06.2010/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_) 1.6 16V LPG 04.2011/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_) 1.6 16V LPG 04.2011/01.2018 77KW 105CV 1598CC - DACIA DUSTER (HS_) 1.6 16V Hi-Flex 08.2010/01.2018 77KW 105...</p> <p>d30x14mm 1f-5x12mm</p>		<p>Z80633 NO. 7703081054 - 7703081127 - 7703081227 - 7703081237</p> <p>Mola de painel</p> <p>DACIA DUSTER (HM_) 1.3 Tce 130 (HMMF) desde 01.2019 96KW 131CV 1332CC H5H 480 H5H 470 3333BKJ - DACIA DUSTER (HM_) 1.5 dCi 115 (HMAD) desde 10.2017 85KW 116CV 1461CC K9K 872 K9K 874 K9K 876 3333BJX - DACIA DUSTER (HM_) 1.5 dCi 115 4x4 (HMAD) desde 10.2017 85KW 116CV 1461CC K9K 874 K9K 872 K9K 878 3333BKJ - DACIA DUSTER (HM_) 1.5 dCi 95 (HMAF) desde 10.2017 70KW 95CV 1461CC K9K 872 3333BJY - DACIA ...</p> <p>d30x17mm 1p-d9.7-15mm</p>

DACIA LODGY-DOKKER

















	<p>A2310 NO. 112100024R - 112102118R - 112845638R - 113756731R</p> <p>APOIO DO MOTOR FRENTE LADO DIREITO</p> <p>DACIA DOKKER Veiculo multiuso (KE_): 1.5 dCi / Blue dCi 75 (KEAJ, KEAH, KEJW) 11.2012/»» 55KW 75CV 1461CC - DACIA DOKKER Veiculo multiuso (KE_): 1.5 dCi (KEAJ, KEAH) 11.2012/»» 66KW 90CV 1461CC - DACIA DOKKER Express Caixa/monovolume: 1.5 dCi 75 / Blue dCi 75 (FEJW, FEAH) 12.2012/»» 55KW 75CV 1461CC - DACIA DOKKER Express Caixa/monovolume: 1.5 dCi (FEAJ) 12.2012/»» 66KW 90CV 1461CC</p> <p>232x129x206mm 3f-d16mm 4f-d12mm 1f-d10mm</p>		<p>A2310 NO. 112100024R - 112102118R - 112845638R - 113756731R</p> <p>APOIO DO MOTOR FRENTE LADO DIREITO</p> <p>DACIA LODGY (JS_): 1.5 dCi 03.2012/»» 66KW 90CV 1461CC - DACIA LODGY (JS_): 1.5 dCi 01.2013/»» 79KW 107CV 1461CC - DACIA LODGY (JS_): 1.5 dCi 06.2015/»» 80KW 109CV 1461CC - DACIA LODGY (JS_): 1.5 dCi 03.2012/»» 81KW 110CV 1461CC</p> <p>232x129x206mm 3f-d16mm 4f-d12mm 1f-d10mm</p>
	<p>A2355 NO. 1f-d10mm 1f-d12mm 3f-d13mm 3f-d16m</p> <p>APOIO DO MOTOR LADO DIREITO</p> <p>DACIA DOKKER Veiculo multiuso (KE_): 1.5 dCi / Blue dCi 75 (KEAJ, KEAH, KEJW) 11.2012/»» 55KW 75CV 1461CC - DACIA DOKKER Veiculo multiuso (KE_): 1.5 dCi (KEAJ, KEAH) 11.2012/»» 66KW 90CV 1461CC - DACIA DOKKER Express Caixa/monovolume: 1.5 dCi 75 / Blue dCi 75 (FEJW, FEAH) 12.2012/»» 55KW 75CV 1461CC - DACIA DOKKER Express Caixa/monovolume: 1.5 dCi (FEAJ) 12.2012/»» 66KW 90CV 1461CC</p> <p>200x222x127mm 1f-d10mm 1f-d12mm 3f-d13mm 3f-d16mm</p>		<p>A2355 NO. 1f-d10mm 1f-d12mm 3f-d13mm 3f-d16m</p> <p>APOIO DO MOTOR LADO DIREITO</p> <p>DACIA LODGY (JS_): 1.5 dCi 03.2012/»» 66KW 90CV 1461CC - DACIA LODGY (JS_): 1.5 dCi 01.2013/»» 79KW 107CV 1461CC - DACIA LODGY (JS_): 1.5 dCi 06.2015/»» 80KW 109CV 1461CC - DACIA LODGY (JS_): 1.5 dCi 03.2012/»» 81KW 110CV 1461CC</p> <p>200x222x127mm 1f-d10mm 1f-d12mm 3f-d13mm 3f-d16mm</p>
	<p>A32744 NO. 543A06915R - 6001547499 - 6001548403 - 8200275528 - 8200307941 - 8200651172 - 8200723741 - 820087629...</p> <p>APOIO SUPORTE AMORTECEDOR FRENTE (GASTA 2 UNIDADES)</p> <p>DACIA DOKKER Express Caixa/monovolume 1.5 dCi (FEAJ) desde 12.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACK - DACIA DOKKER Express Caixa/monovolume 1.5 dCi 75 / Blue dCi 75 (FEJW, FEAH) desde 12.2012 55KW 75CV 1461CC K9K 626 K9K 872 K9K 612 8212ABW - DACIA DOKKER Express Caixa/monovolume 1.6 desde 12.2012 61KW 83CV 1598CC K7M 828 K7M 812 8212ACW - DACIA DOKKER Express Caixa/monovolume 1.6 LPG desd...</p> <p>d104x45mm d79x20mm d56x27mm 1f-d15mm 1f-d16mm 1r-d12mm</p>		<p>A32744 NO. 543A06915R - 6001547499 - 6001548403 - 8200275528 - 8200307941 - 8200651172 - 8200723741 - 820087629...</p> <p>APOIO SUPORTE AMORTECEDOR FRENTE (GASTA 2 UNIDADES)</p> <p>DACIA LODGY (JS_) 1.2 Tce (JSAY, JSMO) desde 03.2012 85KW 115CV 1197CC H5F 408 H5F 402 8212ACX - DACIA LODGY (JS_) 1.5 dCi desde 03.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA LODGY (JS_) 1.5 dCi desde 01.2013 79KW 107CV 1461CC K9K 846 8212ABE - DACIA LODGY (JS_) 1.6 desde 03.2012 61KW 83CV 1598CC K7M 828 K7M 812 8212ACV - DACIA LODGY (JS_) 1.6 LPG desde 11.2013 61KW 83CV 1598CC K7M 828 ...</p> <p>d104x45mm d79x20mm d56x27mm 1f-d15mm 1f-d16mm 1r-d12mm</p>
	<p>E0267-M NO. 112381035R - 112383905R</p> <p>ESTICADOR SUPORTE APOIO MOTOR TRAS</p> <p>DACIA DOKKER Veiculo multiuso (KE_): 1.2 Tce (KEMO, KEAY) 11.2012/»» 85KW 115CV 1197CC - DACIA DOKKER Veiculo multiuso (KE_): 1.6 11.2012/»» 61KW 83CV 1598CC - DACIA DOKKER Veiculo multiuso (KE_): 1.6 LPG 11.2013/»» 61KW 83CV 1598CC - DACIA DOKKER Veiculo multiuso (KE_): 1.5 dCi / Blue dCi 75 (KEAJ, KEAH, KEJW) 11.2012/»» 55KW 75CV 1461CC - DACIA DOKKER Express Caixa/monovolume: 1.2 Tce 115 (F...</p> <p>170x60x55mm 1f-d12mm 1f-d14mm</p>		<p>E0267-M NO. 112381035R - 112383905R</p> <p>ESTICADOR SUPORTE APOIO MOTOR TRAS</p> <p>DACIA LODGY (JS_) 1.2 Tce (JSAY, JSMO) 03.2012/»» 85KW 115CV 1197CC - DACIA LODGY (JS_) 1.6 03.2012/»» 61KW 83CV 1598CC - DACIA LODGY (JS_) 1.6 LPG 11.2013/»» 61KW 83CV 1598CC - DACIA LODGY (JS_) 1.5 dCi 03.2012/»» 66KW 90CV 1461CC - DACIA LODGY (JS_) 1.5 dCi 01.2013/»» 79KW 107CV 1461CC</p> <p>170x60x55mm 1f-d12mm 1f-d14mm</p>

	<p>F1898A3-I NO. 392414459R - 6001547767 - 6001550339 - 6001551490 - 7701473830 - 8200017057</p> <p>FOLE TRANSMISSÃO JUNTO CAIXA</p> <p>DACIA LODGY (JS_) 1.6 desde 03.2012 61KW 83CV 1598CC K7M 828 K7M 812 8212ACV - DACIA LODGY (JS_) 1.6 LPG desde 11.2013 61KW 83CV 1598CC K7M 828 K7M 812 8212ADL</p> <p>d107x89mm 1f-d25.8mm 1f-d78mm</p>		<p>F9530H-I NO. 482034581R</p> <p>FOLE DA DIREÇÃO LADO DIREITO E ESQUERDO</p> <p>DACIA DOKKER Express Caixa/monovolume 1.2 TCe 115 (FEAY) desde 07.2015 85KW 116CV 1197CC H5F 408 8212AEB - DACIA DOKKER Express Caixa/monovolume 1.2 TCe 115 (FEMO) desde 12.2012 84KW 114CV 1198CC H5F 402 8212ADC - DACIA DOKKER Express Caixa/monovolume 1.5 dCi (FEAJ) desde 12.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACK - DACIA DOKKER Express Caixa/monovolume 1.5 dCi 75 / Blue dCi 75 (FEJW, FEAH) ...</p> <p>d60x166mm 1f-d12mm 1f-d15mm</p>
	<p>F9530H-I NO. 482034581R</p> <p>FOLE DA DIREÇÃO LADO DIREITO E ESQUERDO</p> <p>DACIA LODGY (JS_) 1.2 TCe (JSAY, JSM0) desde 03.2012 85KW 115CV 1197CC H5F 408 H5F 402 8212ACX - DACIA LODGY (JS_) 1.5 dCi desde 03.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA LODGY (JS_) 1.5 dCi desde 03.2012 81KW 110CV 1461CC K9K 846 K9K 666 - DACIA LODGY (JS_) 1.5 dCi desde 01.2013 79KW 107CV 1461CC K9K 846 8212ABE - DACIA LODGY (JS_) 1.5 dCi desde 06.2015 80KW 109CV 1461CC K9K 846 K9...</p> <p>d60x166mm 1f-d12mm 1f-d15mm</p>		<p>KF1898A3-I NO. 7701473830</p> <p>KIT FOLE TRANSMISSÃO JUNTO CAIXA</p> <p>DACIA LODGY (JS_) 1.6 desde 03.2012 61KW 83CV 1598CC K7M 828 K7M 812 8212ACV - DACIA LODGY (JS_) 1.6 LPG desde 11.2013 61KW 83CV 1598CC K7M 828 K7M 812 8212ADL</p> <p>d107x89mm 1f-d25.8mm 1f-d78mm</p>
	<p>KF3760-T NO. 322413336R</p> <p>KIT DE FOLE DO CARDAN JUNTO À RODA</p> <p>DACIA DOKKER Veículo multiuso (KE_) 1.2 TCe (KEM0, KEAY) 11.2012>>> 85KW 115CV 1197CC - DACIA DOKKER Veículo multiuso (KE_) 1.6 11.2012>>> 61KW 83CV 1598CC - DACIA DOKKER Veículo multiuso (KE_) 1.6 LPG 11.2013>>> 61KW 83CV 1598CC - DACIA DOKKER Veículo multiuso (KE_) 1.6 04.2015>>> 75KW 102CV 1598CC - DACIA DOKKER Veículo multiuso (KE_) 1.6 LPG 04.2015>>> 75KW 102CV 1598CC - DACIA DOKKER...</p> <p>d106x122mm 1f-d82mm 1f-d24mm</p>		<p>KF3760-T NO. 322413336R</p> <p>KIT DE FOLE DO CARDAN JUNTO À RODA</p> <p>DACIA LODGY (JS_) 1.2 TCe (JSAY, JSM0) 03.2012>>> 85KW 115CV 1197CC - DACIA LODGY (JS_) 1.6 03.2012>>> 61KW 83CV 1598CC - DACIA LODGY (JS_) 1.6 LPG 11.2013>>> 61KW 83CV 1598CC - DACIA LODGY (JS_) 1.6 SCe 100 06.2015>>> 75KW 102CV 1598CC - DACIA LODGY (JS_) 1.6 LPG 04.2015>>> 75KW 102CV 1598CC - DACIA LODGY (JS_) 1.5 dCi 03.2012>>> 66KW 90CV 1461CC - DACIA LODGY (JS_) 1.5 dCi 01.2013>...</p> <p>d106x122mm 1f-d82mm 1f-d24mm</p>
	<p>KN96019 NO. 7701475118</p> <p>KIT ORINGS DO RADIADOR DO ÓLEO</p> <p>DACIA DOKKER Express Caixa/monovolume 1.2 TCe 115 (FEAY) desde 07.2015 85KW 116CV 1197CC H5F 408 8212AEB - DACIA DOKKER Express Caixa/monovolume 1.2 TCe 115 (FEMO) desde 12.2012 84KW 114CV 1198CC H5F 402 8212ADC - DACIA DOKKER Express Caixa/monovolume 1.5 dCi (FEAJ) desde 12.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACK - DACIA DOKKER Express Caixa/monovolume 1.5 dCi 75 / Blue dCi 75 (FEJW, FEAH) ...</p> <p>d70x5mm d30x5mm d25x3mm d66mm 1f-d20mm 1f-d18mm</p>		<p>KN96019 NO. 7701475118</p> <p>KIT ORINGS DO RADIADOR DO ÓLEO</p> <p>DACIA LODGY (JS_) 1.2 TCe (JSAY, JSM0) desde 03.2012 85KW 115CV 1197CC H5F 408 H5F 402 8212ACX - DACIA LODGY (JS_) 1.5 Blue dCi 115 (JSJT) desde 08.2018 85KW 116CV 1461CC K9K 872 K9K 876 8212AEQ - DACIA LODGY (JS_) 1.5 Blue dCi 95 (JSJL) desde 08.2018 70KW 95CV 1461CC K9K 872 8212AEP - DACIA LODGY (JS_) 1.5 dCi desde 03.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA LODGY (JS_) 1.5 dCi desde...</p> <p>d70x5mm d30x5mm d25x3mm d66mm 1f-d20mm 1f-d18mm</p>
	<p>KT0502 NO. 540502745R</p> <p>KIT DE BATENTE DA SUSPENSÃO DA FRENTE</p> <p>DACIA DOKKER Express Caixa/monovolume 1.2 TCe 115 (FEAY) desde 07.2015 85KW 116CV 1197CC H5F 408 8212AEB - DACIA DOKKER Express Caixa/monovolume 1.2 TCe 115 (FEMO) desde 12.2012 84KW 114CV 1198CC H5F 402 8212ADC - DACIA DOKKER Express Caixa/monovolume 1.3 TCe 100 (FENU) desde 08.2019 75KW 102CV 1332CC H5H 470 8212AEX - DACIA DOKKER Express Caixa/monovolume 1.3 TCe 130 (FENE) desde 08.2019 96KW 131...</p> <p>d75x210mm 1f-d18mm 1f-d49mm</p>		<p>P1129 NO. 465310981R - 6001551783</p> <p>CAPA DE PEDAL DO TRAVÃO</p> <p>DACIA DOKKER Express Caixa/monovolume 1.2 TCe 115 (FEMO) desde 12.2012 84KW 114CV 1198CC H5F 402 8212ADC - DACIA DOKKER Express Caixa/monovolume 1.5 dCi (FEAJ) desde 12.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACK - DACIA DOKKER Express Caixa/monovolume 1.5 dCi 75 / Blue dCi 75 (FEJW, FEAH) desde 12.2012 55KW 75CV 1461CC K9K 626 K9K 872 K9K 612 8212ABW - DACIA DOKKER Express Caixa/monovolume 1.6 ...</p> <p>75x53x10mm 1f-d-52x33mm</p>
	<p>P1129 NO. 465310981R - 6001551783</p> <p>CAPA DE PEDAL DO TRAVÃO</p> <p>DACIA LODGY (JS_) 1.2 TCe (JSAY, JSM0) desde 03.2012 85KW 115CV 1197CC H5F 408 H5F 402 8212ACX - DACIA LODGY (JS_) 1.5 Blue dCi 115 (JSJT) desde 08.2018 85KW 116CV 1461CC K9K 872 8212AEQ - DACIA LODGY (JS_) 1.5 Blue dCi 95 (JSJL, JSN7) desde 08.2018 70K2 95CV 1461CC K9K 872 K9K 876 8212AEP - DACIA LODGY (JS_) 1.5 dCi desde 03.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA LODGY (JS_) 1.5 dCi...</p> <p>75x53x10mm 1f-d-52x33mm</p>		<p>R224723 NO. 1446000Q1D - 144600835R - 144601524R - 144602760R - 144606171R - 144606189R - 144606515R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA DOKKER Express Caixa/monovolume 1.5 dCi (FEAJ) desde 12.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACK - DACIA DOKKER Express Caixa/monovolume 1.5 dCi 75 / Blue dCi 75 (FEJW, FEAH) desde 12.2012 55KW 75CV 1461CC K9K 626 K9K 872 K9K 612 8212ABW - DACIA DOKKER Veículo multiuso (KE_) 1.5 dCi (KEAJ, KEAH) desde 11.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA DOKKER Veículo multiuso (KE_)...</p> <p>B115-49/52mm</p>
	<p>R224723 NO. 1446000Q1D - 144600835R - 144601524R - 144602760R - 144606171R - 144606189R - 144606515R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA LODGY (JS_) 1.5 dCi desde 03.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA LODGY (JS_) 1.5 dCi desde 06.2015 80KW 109CV 1461CC K9K 846 K9K 666 8212ADG</p> <p>B115-49/52mm</p>		<p>R224759 NO. 144604599R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA DOKKER Express Caixa/monovolume 1.5 dCi (FEAJ) desde 12.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACK - DACIA DOKKER Express Caixa/monovolume 1.5 dCi 75 / Blue dCi 75 (FEJW, FEAH) desde 12.2012 55KW 75CV 1461CC K9K 626 K9K 872 K9K 612 8212ABW - DACIA DOKKER Veículo multiuso (KE_) 1.5 dCi (KEAJ, KEAH) desde 11.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA DOKKER Veículo multiuso (KE_)...</p> <p>B650-50/52mm 56-92-108-156-185-77-46-45mm</p>

	<p>R224759 NO. 144604599R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DUSTER (HM_) INFORMAÇÕES TIPO ANO DE CONSTRUÇÃO KW HP CC CÓDIGO(S) DO MOTOR NÚMERO KBA (ALEMANHA) 1.5 dCi 110 (HMAB) desde 10.2017 80 109 1461 K9K 667 K9K</p>
------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

656 3333BIN
 1.5 dCi 110 4x4 (HMAB) desde 10.2017 80 109 1461 K9K 658 3333BIO
 1.5 dCi 90 (HMAA) desde 10.2017 66 90 1461 K9K 656 3333BIM
 DUSTER (HS_)
 INFORMAÇÕES
 TIPO
 ANO DE CONSTRUÇÃO
 KW
 HP
 CC
 CÓDIGO(S) DO MOTOR
 NÚM...

		<p>R224764 NO. 144606189R - 144600835R - 144601524R - 144602760R - 144604343R - 8201313260 - 8201316998</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA DOKKER Express Caixa/monovolume 1.5 dCi (FEAJ) desde 12.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACK - DACIA DOKKER Express Caixa/monovolume 1.5 dCi 75 / Blue dCi 75 (FEJW, FEAH) desde 12.2012 55KW 75CV 1461CC K9K 626 K9K 872 K9K 612 8212ABW - DACIA DOKKER Veiculo multiuso (KE_) 1.5 dCi (KEAJ, KEAH) desde 11.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA DOKKER Veiculo multiuso (KE_)...</p>
B650-50/52mm	56-92-108-156-185-77-46-45mm	B270-46/47mm 86-89-78mm

	<p>R224764 NO. 144606189R - 144600835R - 144601524R - 144602760R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA LODGY (JS_) 1.5 dCi desde 03.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA LODGY (JS_) 1.5 dCi desde 06.2015 80KW 109CV 1461CC K9K 846 K9K 666 8212ADG</p> <p>B270-46/47mm 86-89-78mm</p>		<p>R224773 NO. 144609116R - 144609369R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA DOKKER Express Caixa/monovolume 1.5 dCi (FEAJ) desde 12.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACK - DACIA DOKKER Express Caixa/monovolume 1.5 dCi 75 / Blue dCi 75 (FEJW, FEAH) desde 12.2012 55KW 75CV 1461CC K9K 626 K9K 872 K9K 612 8212ABW - DACIA DOKKER Veiculo multiuso (KE_) 1.5 dCi (KEAJ, KEAH) desde 11.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA DOKKER Veiculo multiuso (KE_)...</p> <p>B650-41/41mm 70-82-101-156-1244-64-81-80mm</p>
	<p>R224773 NO. 144609116R - 144609369R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA LODGY (JS_) 1.5 dCi desde 03.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA LODGY (JS_) 1.5 dCi desde 06.2015 80KW 109CV 1461CC K9K 846 K9K 666 8212ADG</p> <p>B650-41/41mm 70-82-101-156-1244-64-81-80mm</p>		<p>R224774 NO. 144608527R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA DOKKER Veiculo multiuso (KE_) 1.5 dCi (KEAJ, KEAH) desde 11.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA DOKKER Veiculo multiuso (KE_) 1.5 dCi / Blue dCi 75 (KEAJ, KEAH, KEJW) desde 11.2012 55KW 75CV 1461CC K9K 872 K9K 626 K9K 612 8212ABO</p> <p>B690-40/40mm 63-78-102-147-127-71-8298mm</p>
	<p>R224819 NO. 1412000Q0J - 1412000Q1E - 1412000Q1G - 223211229R - 223211568R - 223211824R - 223214402R - 920091256</p> <p>TUBO VALVULA REGULADORA DE VELOCIDADE</p> <p>DACIA LODGY (JS_) 1.5 dCi desde 03.2012 81KW 110CV 1461CC K9K 846 K9K 666 - DACIA LODGY (JS_) 1.5 dCi desde 01.2013 79KW 107CV 1461CC K9K 846 8212ABE</p> <p>B67-6/6mm</p>		<p>R230055 NO.</p> <p>TUBO ADMISSÃO FILTRO DE AR</p> <p>DACIA DOKKER Express Caixa/monovolume 1.3 TCe 100 (FENU) desde 08.2019 75KW 102CV 1332CC H5H 470 8212AEX - DACIA DOKKER Express Caixa/monovolume 1.3 TCe 130 (FENE) desde 08.2019 96KW 131CV 1332CC H5H 470 8212AEW - DACIA DOKKER Express Caixa/monovolume 1.5 dCi (FEAJ) desde 12.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACK - DACIA DOKKER Express Caixa/monovolume 1.5 dCi 75 / Blue dCi 75 (FEJW, FEAH) ...</p> <p>B505-62/82x41mm 100-190-158-56mm</p>
	<p>R230055 NO.</p> <p>TUBO ADMISSÃO FILTRO DE AR</p> <p>DACIA DOKKER Veiculo multiuso (KE_) 1.2 TCe (KEM0, KEAY) desde 11.2012 85KW 115CV 1197CC H5F 408 H5F 402 8212ACX - DACIA DOKKER Veiculo multiuso (KE_) 1.3 TCe 100 (KENU) desde 08.2019 75KW 102CV 1332CC H5H 470 H5H 490 8212AET - DACIA DOKKER Veiculo multiuso (KE_) 1.3 TCe 130 (KENE) desde 03.2019 96KW 131CV 1332CC H5H 470 H5H 490 8212AEU - DACIA DOKKER Veiculo multiuso (KE_) 1.5 Blue dCi 95 (KEJL) ...</p> <p>B505-62/82x41mm 100-190-158-56mm</p>		<p>R230055 NO.</p> <p>TUBO ADMISSÃO FILTRO DE AR</p> <p>DACIA LODGY (JS_) 1.2 TCe (JSAY, JSM0) desde 03.2012 85KW 115CV 1197CC H5F 408 H5F 402 8212ACX - DACIA LODGY (JS_) 1.5 Blue dCi 115 (JSJT) desde 08.2018 85KW 116CV 1461CC K9K 872 8212AEQ - DACIA LODGY (JS_) 1.5 Blue dCi 95 (JSJL, JSN7) desde 08.2018 70KW 95CV 1461CC K9K 872 K9K 876 8212AEP - DACIA LODGY (JS_) 1.5 dCi desde 03.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA LODGY (JS_) 1.5 dC...</p> <p>B505-62/82x41mm 100-190-158-56mm</p>
	<p>R8210 NO. 223211229R - 223214402R</p> <p>TUBO DA VALVULA DO REGULADOR DE VELOCIDADE</p> <p>DACIA LODGY (JS_) 1.5 dCi desde 03.2012 81KW 110CV 1461CC K9K 846 K9K 666 - DACIA LODGY (JS_) 1.5 dCi desde 01.2013 79KW 107CV 1461CC K9K 846 8212ABE</p> <p>222x82x16mm 1f-d6mm 1f-d11mm</p>		<p>R8219 NO. 1446000Q1H - 144600492R - 144605243R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA DOKKER Express Caixa/monovolume 1.2 TCe 115 (FEM0) desde 12.2012 84KW 114CV 1198CC H5F 402 8212ADC</p> <p>B560-31/39mm 110-53-230-105-58mm</p>
	<p>R8219 NO. 1446000Q1H - 144600492R - 144605243R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA LODGY (JS_) 1.2 TCe (JSAY, JSM0) desde 03.2012 85KW 115CV 1197CC H5F 408 H5F 402 8212ACX</p> <p>B560-31/39mm 110-53-230-105-58mm</p>		<p>S1674 NO. 54500-00Q1G - 545004269R - 54501-00Q1G - 545011362R - 6001547519 - 6001547520 - 6001550909 - 60015560</p> <p>SILENT-BLOC DO BRAÇO DA SUSPENSÃO DA FRENTE PARTE INFERIOR</p> <p>DACIA DOKKER Express Caixa/monovolume INFORMAÇÕES TIPO ANO DE CONSTRUÇÃO 1.2 TCe 115 (FEAY) desde 07.2015 85KW 116CV 1197CC H5F 408 8212AEB - DACIA DOKKER Express Caixa/monovolume 1.2 TCe 115 (FEM0) desde 12.2012 84KW 114CV 1198CC H5F 402 8212ADC - DACIA DOKKER Express Caixa/monovolume 1.5 dCi (FEAJ) desde 12.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACK - DACIA DOKKER Express Caixa/monovolume 1.5...</p> <p>d50x46mm c30mm d37mm 1f-d12mm</p>
	<p>S1689 NO. 545004529R - 545007106R - 545010294R - 545011727R - 6640096299</p> <p>SILENT-BLOC DO BRAÇO SUSPENSÃO DA FRENTE</p> <p>DACIA DOKKER Express Caixa/monovolume 1.2 TCe 115 (FEAY) desde 07.2015 85KW 116CV 1197CC H5F 408 8212AEB - DACIA DOKKER Express Caixa/monovolume 1.2 TCe 115 (FEM0) desde 12.2012 84KW 114CV 1198CC H5F 402 8212ADC - DACIA DOKKER Express Caixa/monovolume 1.5 dCi (FEAJ) desde 12.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACK - DACIA DOKKER Express Caixa/monovolume 1.5 dCi 75 / Blue dCi 75 (FEJW, FEAH) ...</p> <p>d50x46mm c29mm d37mm 1f-d12mm</p>		<p>S1689 NO. 545004529R - 545007106R - 545010294R - 545011727R - 6640096299</p> <p>SILENT-BLOC DO BRAÇO SUSPENSÃO DA FRENTE</p> <p>DACIA LODGY (JS_) 1.2 TCe (JSAY, JSM0) desde 03.2012 85KW 115CV 1197CC H5F 408 H5F 402 8212ACX - DACIA LODGY (JS_) 1.5 dCi desde 03.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA LODGY (JS_) 1.5 dCi desde 06.2015 80KW 109CV 1461CC K9K 846 K9K 666 8212ADG - DACIA LODGY (JS_) 1.6 desde 03.2012 61KW 83CV 1598CC K7M 828...</p> <p>d50x46mm c29mm d37mm 1f-d12mm</p>
	<p>T1184 NO. 546134AA0B - 6001549311</p> <p>BATENTE DA BARRA ESTABILIZADORA DA FRENTE</p> <p>DACIA DOKKER Express Caixa/monovolume 1.2 TCe 115 (FEAY) desde 07.2015 85KW 116CV 1197CC H5F 408 8212AEB - DACIA DOKKER Express Caixa/monovolume 1.2 TCe 115 (FEM0) desde 12.2012 84KW 114CV 1198CC H5F 402 8212ADC - DACIA DOKKER Express Caixa/monovolume 1.5 dCi (FEAJ) desde 12.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACK - DACIA DOKKER Express Caixa/monovolume 1.5 dCi 75 / Blue dCi 75 (FEJW, FEAH) ...</p> <p>35x40x36mm 1f-d23mm</p>		<p>T1184 NO. 546134AA0B - 6001549311</p> <p>BATENTE DA BARRA ESTABILIZADORA DA FRENTE</p> <p>DACIA LODGY (JS_) 1.2 TCe (JSAY, JSM0) desde 03.2012 85KW 115CV 1197CC H5F 408 H5F 402 8212ACX - DACIA LODGY (JS_) 1.5 Blue dCi 115 (JSJT) desde 08.2018 85KW 116CV 1461CC K9K 872 K9K 876 8212AEQ - DACIA LODGY (JS_) 1.5 Blue dCi 95 (JSJL) desde 08.2018 70KW 95CV 1461CC K9K 872 8212AEP - DACIA LODGY (JS_) 1.5 dCi desde 03.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA LODGY (JS_) 1.5 dCi desde...</p> <p>35x40x36mm 1f-d23mm</p>

	<p>UAP81637 NO. 7703062072 - 8200014894</p> <p>ANILHA PROTEÇÃO TÉRMICA INJECTORES</p> <p>DACIA DOKKER Express Caixa/monovolume 1.5 dCi (FEAJ) desde 12.2012 66kw 90CV 1461CC K9K 626 K9K 612 8212ACK - DACIA DOKKER Express Caixa/monovolume 1.5 dCi 75 / Blue dCi 75 (FEJW, FEAH) desde 12.2012 55KW 75CV 1461CC K9K 626 K9K 872 K9K 612 8212ABW - DACIA DOKKER Veiculo multiuso (KE_) 1.5 dCi / Blue dCi 75 (KEAJ, KEAH, KEJW) desde 11.2012 55KW 75CV 1461CC K9K 872 K9K 626 K9K 612 8212ABO</p> <p>d15x3mm 1f-d7mm</p>		<p>UFQ12818 NO. 7700112818</p> <p>FORQUILHA DA EMBRAIAGEM</p> <p>DACIA LODGY (JS_) 1.2 Tce (JSAY, JSM0) desde 03.2012 85KW 115CV 1197CC H5F 408 H5F 402 8212ACX - DACIA LODGY (JS_) 1.5 Blue dCi 115 (JSJT) desde 08.2018 85KW 116CV 1461CC K9K 872 K9K 876 8212AEQ - DACIA LODGY (JS_) 1.5 Blue dCi 95 (JSJL) desde 08.2018 70KW 95CV 1461CC K9K 872 8212AEP - DACIA LODGY (JS_) 1.5 dCi desde 03.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA LODGY (JS_) 1.5 dCi desde...</p> <p>235x61x29mm 1f-d8mm</p>
	<p>UFQ12818 NO. 7700112818</p> <p>FORQUILHA DA EMBRAIAGEM</p> <p>DACIA LOGAN (LS_) 1.2 16V (LS1N, LS02, BS02) desde 02.2006 55KW 75CV 1149CC D4F 732 D4F 734 8212AAV - DACIA LOGAN (LS_) 1.2 16V LPG desde 02.2006 55KW 75CV 1149CC D4F 734 8212ACR - DACIA LOGAN (LS_) 1.4 MPI LPG (LS0C) 02.2006/12.2012 55KW 75CV 1390CC K7J 714 K7J 710 8212AAW - DACIA LOGAN (LS_) 1.5 dCi (LS04) 05.2010/12.2012 55KW 75CV 1461CC K9K 892 8212ABQ - DACIA LOGAN (LS_) 1.5 dCi (LS04) desde ...</p> <p>235x61x29mm 1f-d8mm</p>		<p>UFT90167 NO. 1106000Q0K - 110603026R - 110605536R - 8200954328</p> <p>FALANGE TERMOSTATO</p> <p>DACIA DOKKER Express Caixa/monovolume 1.5 dCi (FEAJ) desde 12.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACK - DACIA DOKKER Express Caixa/monovolume 1.5 dCi 75 / Blue dCi 75 (FEJW, FEAH) desde 12.2012 55KW 75CV 1461CC K9K 626 K9K 872 K9K 612 8212ABW - DACIA DOKKER Veiculo multiuso (KE_) 1.5 dCi (KEAJ, KEAH) desde 11.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA DOKKER Veiculo multiuso (KE_....</p> <p>169x101x100mm 3f-d7mm 1f-16mm 1f-d28mm</p>
	<p>UFT90167 NO. 1106000Q0K - 110603026R - 110605536R - 8200954328</p> <p>FALANGE TERMOSTATO</p> <p>DACIA LODGY (JS_) 1.5 dCi desde 03.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA LODGY (JS_) 1.5 dCi desde 01.2013 79KW 107CV 1461CC K9K 846 8212ABE</p> <p>169x101x100mm 3f-d7mm 1f-16mm 1f-d28mm</p>		<p>UMB80661 NO. 6001543014 - 7700274026 - 8200058022</p> <p>TAMPÃO BLOCO MOTOR</p> <p>DACIA DOKKER Veiculo multiuso (KE_) 1.6 desde 11.2012 61KW 83CV 1598CC K7M 828 K7M 812 8212ACW 8212ACV</p> <p>d42x8mm di-38x7mm</p>
	<p>UMB80661 NO. 6001543014 - 7700274026 - 8200058022</p> <p>TAMPÃO BLOCO MOTOR</p> <p>DACIA LODGY (JS_) 1.6 desde 03.2012 61KW 83CV 1598CC K7M 828 K7M 812 8212ACV</p> <p>d42x8mm di-38x7mm</p>		<p>URL36540 NO. 33140-33G01 - 33140-33G02 - 33142-33G10 - 8200651172</p> <p>ROLAMENTO DO APOIO SUPORTE AMORTECEDOR FRENTE COMPEMENTA A1479-C (GASTA 2 UNIDADES)</p> <p>DACIA DOKKER Express Caixa/monovolume 1.2 Tce 115 (FEM0) desde 12.2012 84KW 114CV 1198CC H5F 402 8212ADC - DACIA DOKKER Express Caixa/monovolume 1.5 dCi (FEAJ) desde 12.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACK - DACIA DOKKER Express Caixa/monovolume 1.5 dCi 75 / Blue dCi 75 (FEJW, FEAH) desde 12.2012 55KW 75CV 1461CC K9K 626 K9K 872 K9K 612 8212ABW - DACIA DOKKER Express Caixa/monovolume 1.6 ...</p> <p>d56x9mm 1f-d16mm</p>
	<p>URL36540 NO. 12371-64130 - 12371-64140 - 12371-64141 - 8200651172</p> <p>ROLAMENTO DO APOIO SUPORTE AMORTECEDOR FRENTE COMPEMENTA A1479-C (GASTA 2 UNIDADES)</p> <p>DACIA LODGY (JS_) 1.2 Tce (JSAY, JSM0) desde 03.2012 85KW 115CV 1197CC H5F 408 H5F 402 8212ACX - DACIA LODGY (JS_) 1.5 Blue dCi 115 (JSJT) desde 08.2018 85KW 116CV 1461CC K9K 872 K9K 876 8212AEQ - DACIA LODGY (JS_) 1.5 Blue dCi 95 (JSJL) desde 08.2018 70KW 95CV 1461CC K9K 872 8212AEP - DACIA LODGY (JS_) 1.5 dCi desde 03.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA LODGY (JS_) 1.5 dCi desde...</p> <p>d56x9mm 1f-d16mm</p>		<p>URTE6017 NO. 144652865R</p> <p>RETENTOR TUBO AR SOBREALIMENTAÇÃO D45,5X49X4,8MM</p> <p>DACIA DOKKER Express Caixa/monovolume 1.2 Tce 115 (FEAY) desde 07.2015 85KW 116CV 1197CC H5F 408 8212AEB - DACIA DOKKER Express Caixa/monovolume 1.2 Tce 115 (FEM0) desde 12.2012 84KW 114CV 1198CC H5F 402 8212ADC - DACIA DOKKER Veiculo multiuso (KE_) 1.2 Tce (KEM0, KEAY) desde 11.2012 85KW 115CV 1197CC H5F 408 H5F 402 8212ACX</p> <p>d48x5mm 1f-d45mm</p>
	<p>URTE6017 NO. 144652865R</p> <p>RETENTOR TUBO AR SOBREALIMENTAÇÃO D45,5X49X4,8MM</p> <p>DACIA LODGY (JS_) 1.2 Tce (JSAY, JSM0) desde 03.2012 85KW 115CV 1197CC H5F 408 H5F 402 8212ACX</p> <p>d48x5mm 1f-d45mm</p>		<p>URTE6018 NO. 140797120R</p> <p>RETENTOR TUBO AR SOBREALIMENTAÇÃO</p> <p>DACIA DOKKER Express Caixa/monovolume 1.5 dCi (FEAJ) desde 12.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACK - DACIA DOKKER Express Caixa/monovolume 1.5 dCi 75 / Blue dCi 75 (FEJW, FEAH) desde 12.2012 55KW 75CV 1461CC K9K 626 K9K 872 K9K 612 8212ABW - DACIA DOKKER Veiculo multiuso (KE_) 1.5 dCi (KEAJ, KEAH) desde 11.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA DOKKER Veiculo multiuso (KE_)...</p> <p>d46x5mm d42mm</p>
	<p>URTE6018 NO. 140797120R</p> <p>RETENTOR TUBO AR SOBREALIMENTAÇÃO</p> <p>DACIA LODGY (JS_) 1.5 dCi desde 03.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA LODGY (JS_) 1.5 dCi desde 03.2012 81KW 110CV 1461CC K9K 846 K9K 666 - DACIA LODGY (JS_) 1.5 dCi desde 01.2013 79KW 107CV 1461CC K9K 846 8212ABE - DACIA LODGY (JS_) 1.5 dCi desde 06.2015 80KW 109CV 1461CC K9K 846 K9K 666 8212ADG</p> <p>d46x5mm d42mm</p>		<p>UTR1403 NO. 7701470950 - 7701471585</p> <p>TAMPÃO DEPÓSITO COMBUSTIVEL</p> <p>DACIA DOKKER Express Caixa/monovolume 1.2 Tce 115 (FEM0) desde 12.2012 84KW 114CV 1198CC H5F 402 8212ADC - DACIA DOKKER Express Caixa/monovolume 1.5 dCi (FEAJ) desde 12.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACK - DACIA DOKKER Express Caixa/monovolume 1.5 dCi 75 / Blue dCi 75 (FEJW, FEAH) desde 12.2012 55KW 75CV 1461CC K9K 626 K9K 872 K9K 612 8212ABW - DACIA DOKKER Express Caixa/monovolume 1.6 ...</p> <p>d73x67mm d37mm</p>
	<p>UTR1403 NO. 7701470950 - 7701471585</p> <p>TAMPÃO DEPÓSITO COMBUSTIVEL</p> <p>DACIA LODGY (JS_) 1.2 Tce (JSAY, JSM0) desde 03.2012 85KW 115CV 1197CC H5F 408 H5F 402 8212ACX - DACIA LODGY (JS_) 1.5 dCi desde 03.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA LODGY (JS_) 1.5 dCi desde 03.2012 81KW 110CV 1461CC K9K 846 K9K 666 - DACIA LODGY (JS_) 1.5 dCi desde 01.2013 79KW 107CV 1461CC K9K 846 8212ABE - DACIA LODGY (JS_) 1.5 dCi desde 06.2015 80KW 109CV 1461CC K9K 846 K9K ...</p> <p>d73x67mm d37mm</p>		<p>W5106 NO. 8200184103 - 8200185800 - 8200477938 - 8200511194</p> <p>POLIE DA CAMBOTA (6 PISTAS)</p> <p>DACIA LODGY (JS_) 1.5 dCi desde 03.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA LODGY (JS_) 1.5 dCi desde 03.2012 81KW 110CV 1461CC K9K 846 K9K 666 - DACIA LODGY (JS_) 1.5 dCi desde 01.2013 79KW 107CV 1461CC K9K 846 8212ABE</p> <p>d155/151mm d26mm</p>

	<p>W5108 NO. 12201-00QAW - 12303-00QJ - 12303-00Q1H - 12303-00Q2K - 12303-00QAY - 12303-00QBA - 12303-BN700-12...</p> <p>POLIE DA CAMBOTA (5 PISTAS)</p> <p>DACIA LODGY (JS_) : 1.5 dCi 03.2012/» » 66KW 90CV 1461CC - DACIA LODGY (JS_) : 1.5 dCi 01.2013/» » 79KW 107CV 1461CC - DACIA LODGY (JS_) : 1.5 dCi 06.2015/» » 80KW 109CV 1461CC</p> <p>d153.4mm 1f-d26mm</p>		<p>W5108 NO. 12201-00QAW - 12303-00QJ - 12303-00Q1H - 12303-00Q2K - 12303-00QAY - 12303-00QBA - 12303-BN700-12...</p> <p>POLIE DA CAMBOTA (5 PISTAS)</p> <p>DACIA DOKKER Veículo multiuso (KE_) : 1.5 dCi / Blue dCi 75 (KEAJ, KEAH, KEJW) 11.2012/» » 55K2 75CV 1461CC - DACIA DOKKER Veículo multiuso (KE_) : 1.5 dCi (KEAJ, KEAH) 11.2012/» » 66KW 90CV 1461CC - DACIA DOKKER Veículo multiuso (KE_) : 1.5 Blue dCi 95 (KEJL) 12.2018/» » 70KW 95CV 1461CC - DACIA DOKKER Express Caixa/monovolume : 1.5 dCi 75 / Blue dCi 75 (FEJW, FEAH) 12.2012/» » 55KW 75CV 1461CC - DAC...</p> <p>d153.4mm 1f-d26mm</p>
	<p>W5137 NO. 7700105788 - 7700107122 - 8200044050 - 8200352613 - 8200395313 - 8200544135 - 8200552236 - 820055764...</p> <p>POLIE DA CAMBOTA 6 PISTAS</p> <p>DACIA DOKKER Veículo multiuso (KE_) : 1.5 dCi / Blue dCi 75 (KEAJ, KEAH, KEJW) 11.2012/» » 55KW 75CV 1461CC - DACIA DOKKER Veículo multiuso (KE_) : 1.5 dCi (KEAJ, KEAH) 11.2012/» » 66KW 90CV 1461CC - RENAULT DOKKER Veículo multiuso (KE_) : 1.5 Blue dCi 95 (KEJL) 12.2018/» » 70KW 95CV 1461CC - RENAULT DOKKER Express Caixa/monovolume : 1.5 dCi 75 / Blue dCi 75 (FEJW, FEAH) 12.2012/» » 55KW 75CV 1461CC ...</p> <p>d155mm d26mm</p>		<p>W5137 NO. 7700105788 - 7700107122 - 8200044050 - 8200352613 - 8200395313 - 8200544135 - 8200552236 - 820055764...</p> <p>POLIE DA CAMBOTA 6 PISTAS</p> <p>DACIA LODGY (JS_) : 1.5 dCi 03.2012/» » 66KW 90CV 1461CC - DACIA LODGY (JS_) : 1.5 Blue dCi 95 (JSJL) 08.2018/» » 70KW 95CV 1461CC - DACIA LODGY (JS_) : 1.5 dCi 01.2013/» » 79KW 107CV 1461CC - DACIA LODGY (JS_) : 1.5 dCi 03.2012/» » 81KW 110CV 1461CC</p> <p>d155mm d26mm</p>
	<p>Z57184 NO. 7703081056</p> <p>MOLAS FIXAÇÃO REV. CAVA RODA RENAULT/DACIA</p> <p>DACIA DOKKER Veículo multiuso (KE_) : 1.2 TcE (KEM0, KEAY) 11.2012/» » 85KW 115CV 1197CC - DACIA DOKKER Veículo multiuso (KE_) : 1.6 11.2012/» » 61KW 83CV 1598CC - DACIA DOKKER Veículo multiuso (KE_) : 1.6 LPG 11.2013/» » 61KW 83CV 1598CC - DACIA DOKKER Veículo multiuso (KE_) : 1.6 04.2015/» » 75KW 102CV 1598CC - DACIA DOKKER Veículo multiuso (KE_) : 1.6 LPG 04.2015/» » 75KW 102CV 1598CC - DACIA DOK...</p> <p>d30x14mm 1f-5x12mm</p>		<p>Z57184 NO. 7703081056</p> <p>MOLAS FIXAÇÃO REV. CAVA RODA RENAULT/DACIA</p> <p>DACIA LODGY (JS_) : 1.2 TcE (JSAY, JSM0) 03.2012/» » 85KW 115CV 1197CC - DACIA LODGY (JS_) : 1.6 03.2012/» » 61KW 83CV 1598CC - DACIA LODGY (JS_) : 1.6 LPG 11.2013/» » 61KW 83CV 1598CC - DACIA LODGY (JS_) : 1.6 ScE 100 06.2015/» » 75KW 102CV 1598CC - DACIA LODGY (JS_) : 1.6 LPG 04.2015/» » 75KW 102CV 1598CC - DACIA LODGY (JS_) : 1.5 dCi 03.2012/» » 66KW 90CV 1461CC - DACIA LODGY (JS_) : 1.5 Blue dCi 95 (...)</p> <p>d30x14mm 1f-5x12mm</p>
	<p>Z80633 NO. 7703081054 - 7703081127 - 7703081227 - 7703081237</p> <p>Mola de painel</p> <p>DACIA DOKKER Express Caixa/monovolume 1.2 TcE 115 (FEAY) desde 07.2015 85KW 116CV 1197CC H5F 408 8212AEB - DACIA DOKKER Express Caixa/monovolume 1.2 TcE 115 (FEMO) desde 12.2012 84KW 114CV 1198CC H5F 402 8212ADC - DACIA DOKKER Express Caixa/monovolume 1.5 dCi (FEAJ) desde 12.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACK - DACIA DOKKER Express Caixa/monovolume 1.5 dCi 75 / Blue dCi 75 (FEJW, FEAH) ...</p> <p>d30x17mm 1p-d9.7-15mm</p>		<p>Z80633 NO. 7703081054 - 7703081127 - 7703081227 - 7703081237</p> <p>Mola de painel</p> <p>DACIA LODGY (JS_) 1.2 TcE (JSAY, JSM0) desde 03.2012 85KW 115CV 1197CC H5F 408 H5F 402 8212ACX - DACIA LODGY (JS_) 1.5 Blue dCi 115 (JSJT) desde 08.2018 85KW 116CV 1461CC K9K 872 8212AEQ - DACIA LODGY (JS_) 1.5 Blue dCi 95 (JSJL) desde 08.2018 70KW 95CV 1461CC K9K 872 8212AEP - DACIA LODGY (JS_) 1.5 dCi desde 03.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA LODGY (JS_) 1.5 dCi desde 03.201...</p> <p>d30x17mm 1p-d9.7-15mm</p>

DACIA LOGAN - SOLENZA

















	<p>A1199 NO. 6001543760</p> <p>APOIO MOTOR ESQUERDO</p> <p>DACIA SOLENZA (B41_) : 1.4 (B41A, B41B, B41C) 02.2003/» » 55KW 75CV 1390CC - DACIA SOLENZA (B41_) : 1.9 D (B41E, B41F, B41G) 02.2003/» » 46KW 63CC 1870CC</p> <p>123x70x48mm 1f-d12mm</p>		<p>A1262 NO. 7700560571 - 7700760571 - 7700760572 - 7700765776 - 770077654 - 7700796766 - 7700797666 - 770082402...</p> <p>APOIO SUPORTE DO AMORTECEDOR DA FRENTE</p> <p>DACIA SOLENZA (B41_) : 1.4 (B41A, B41B, B41C) 02.2003/» » 55KW 75CV 1390CC - DACIA SOLENZA (B41_) : 1.9 D (B41E, B41F, B41G) 02.2003/» » 46KW 63CV 1870CC</p> <p>170x150x50mm 1f-d14mm 2r-d8mm</p>
	<p>A1471 NO. 6001543027</p> <p>APOIO MOTOR DIREITO</p> <p>DACIA SOLENZA (B41_) : 1.4 (B41A, B41B, B41C) 02.2003/» » 55KW 75CV 1390CC - DACIA SOLENZA (B41_) : 1.9 D (B41E, B41F, B41G) 02.2003/» » 46KW 63CV 1870CC</p> <p>170x110x110mm 1p-d10-30mm</p>		<p>A2043 NO. 8200105502 - 8200105503 - 8200105504 - 8200105505</p> <p>APOIO ESCAPE PARTE CENTRO</p> <p>DACIA LOGAN (LS_) : 1.4 (LSOA, LSOC, LSOE, LSOG) 09.2004/» » 55KW 75CV 1390CC - DACIA LOGAN (LS_) : 1.6 (LSOB, LSOD, LSOE, LSOH) 09.2004/» » 64KW 87CV 1598CC - DACIA LOGAN (LS_) : 1.6 16V (LSO9, LS0L, LS0M, LS0P, LS0V, LS18, LS1S, LS1V,... 02.2006/» » 77KW 105CV 1598CC - DACIA LOGAN (LS_) : 1.5 dCi (LS0J, LS0Y) 09.2005/» » 48KW 65CV 1461CC - DACIA LOGAN (LS_) : 1.5 dCi (LS0K) 01.2006/» » 50KW 68KW 1461...</p> <p>47x50x29mm 2f-17x7mm</p>
	<p>A2100 NO. 6001548160 - 8200014932 - 8200297939 - 8200358147</p> <p>APOIO DA CAIXA DE VELOCIDADES</p> <p>DACIA LOGAN (LS_) : 1.4 (LSOA, LSOC, LSOE, LSOG) 09.2004/» » 55KW 75CV 1390CC - DACIA LOGAN (LS_) : 1.6 (LSOB, LSOD, LSOE, LSOH) 09.2004/» » 64KW 87CV 1598CC</p> <p>152x72x57mm 1f-d11mm 2f-d17mm</p>		<p>A2101 NO. 6001548160 - 8200014932 - 8200297939 - 8200358147 - 8200395661</p> <p>APOIO CAIXA VELOCIDADES</p> <p>DACIA LOGAN (LS_) : 1.5 dCi (LS0J, LS0Y) 09.2005/» » 48KW 65CV 1461CC - DACIA LOGAN (LS_) : 1.5 dCi (LS0K) 01.2006/» » 50KW 68CV 1461CC - DACIA LOGAN (LS_) : 1.5 dCi (LS04) 05.2010/» » 55KW 75CV 1461CC - DACIA LOGAN (LS_) : 1.5 dCi (LS0W) 09.2007/» » 63KW 86CV 1461CC - DACIA LOGAN (LS_) : 1.5 dCi (LS04) 05.2010/» » 65KW 88CV 1461CC - DACIA LOGAN EXPRESS (FS_) : 1.4 03.2009/» » 55KW 75CV 1390CC - DACIA ...</p> <p>152x70x57mm 1f-d11mm 2f-d17mm</p>

	<p>A2102 NO. 2f-d17mm 1f-d10mm 1f-d12mm 1f-10x1</p> <p>APOIO DO MOTOR FRENTE DIREITO</p> <p>DACIA LOGAN (LS_) 1.2 16V LPG 02.2006/>>> 55KW 75CV 1149CC - DACIA LOGAN (LS_) 1.4 (LSOA, LSOC, LSOE, LSOG) 09.2004/>>> 55KW 75C 1390CC - DACIA LOGAN (LS_) 1.6 MPI 85 05.2010/>>> 62KW 84CV 1598CC - DACIA LOGAN (LS_) 1.6 Bifuel 05.2010/>>> 62KW 84CV 1598CC - DACIA LOGAN (LS_) 1.6 (LSOB, LSOD, LSOF, LSOH) 09.2004/>>> 64KW 87CV 1598CC - DACIA LOGAN MCV (KS_) 1.4 02.2007/>>> 55KW 75CV 1390CC - D...</p> <p>194x175x106mm 2f-d17mm 1f-d10mm 1f-d12mm 1f-10x12f</p>		<p>A2310 NO. 112100024R - 112102118R - 112845638R - 113756731R</p> <p>APOIO DO MOTOR FRENTE LADO DIREITO</p> <p>DACIA LOGAN II: 1.5 dCi / Blue dCi 75 10.2012/>>> 55KW 75CV 1461CC - DACIA LOGAN II: 1.5 dCi 01.2013/>>> 63KW 84CV 1461CC - DACIA LOGAN II: 1.5 dCi 10.2012/>>> 66KW 90CV 1461CC - DACIA LOGAN MCV II: 1.5 dCi 02.2013/>>> 55KW 75CV 1461CC - DACIA LOGAN MCV II: 1.5 dCi 02.2013/>>> 63KW 84CV 1461CC - DACIA LOGAN MCV II: 1.5 dCi 02.2013/>>> 66KW 90CV 1461CC</p> <p>232x129x206mm 3f-d16mm 4f-d12mm 1f-d10mm</p>
	<p>A2355 NO. 1f-d10mm 1f-d12mm 3f-d13mm 3f-d16m</p> <p>APOIO DO MOTOR LADO DIREITO</p> <p>DACIA LOGAN II: 1.5 dCi / Blue dCi 75 10.2012/>>> 55KW 75CV 1461CC - DACIA LOGAN II: 1.5 dCi 01.2013/>>> 63KW 84CV 1461CC - DACIA LOGAN II: 1.5 dCi 10.2012/>>> 66KW 90CV 1461CC - RENAULT LOGAN MCV II: 1.5 dCi 02.2013/>>> 55KW 75CV 1461CC - DACIA LOGAN MCV II: 1.5 dCi 02.2013/>>> 63KW 84CV 1461CC - DACIA LOGAN MCV II: 1.5 dCi 02.2013/>>> 66KW 90CV 1461CC</p> <p>200x222x127mm 1f-d10mm 1f-d12mm 3f-d13mm 3f-d16mm</p>		<p>A32744 NO. 543A06915R - 6001547499 - 6001548403 - 8200275528 - 8200307941 - 8200651172 - 8200723741 - 820087629...</p> <p>APOIO SUPORTE AMORTECEDOR FRENTE (GASTA 2 UNIDADES)</p> <p>DACIA LOGAN (LS_) 1.2 16V (LS1N, LS02, BS02) desde 02.2006 55KW 75CV 1149CC D4F 732 D4F 734 8212AAV - DACIA LOGAN (LS_) 1.2 16V LPG desde 02.2006 55KW 75CV 1149CC D4F 734 8212ACR - DACIA LOGAN (LS_) 1.4 (LSOA, LSOC, LSOE, LSOG) desde 09.2004 55KW 75CV 1390CC K7J 710 K7J 714 8212001 8212AAA 8212ABB - DACIA LOGAN (LS_) 1.4 MPI LPG (LS0C) 02.2006/12.2012 55KW 75CV 1390CC K7J 714 K7J 710 8212AAW - DAC...</p> <p>d104x45mm d79x20mm d56x47mm 1f-d15mm 1f-d16mm 1r-d12mm</p>
	<p>A32744 NO. 543A06915R - 6001547499 - 6001548403 - 8200275528 - 8200307941 - 8200651172 - 8200723741 - 820087629...</p> <p>APOIO SUPORTE AMORTECEDOR FRENTE (GASTA 2 UNIDADES)</p> <p>DACIA LOGAN EXPRESS (FS_) 1.4 desde 03.2009 55KW 75CV 1390CC K7J 710 8212AAR - DACIA LOGAN EXPRESS (FS_) 1.5 dCi desde 05.2010 55KW 75CV 1461CC K9K 892 8212ABW - DACIA LOGAN EXPRESS (FS_) 1.5 dCi desde 05.2010 65KW 88CV 1461CC K9K 892 8212ABX - DACIA LOGAN EXPRESS (FS_) 1.5 dCi (FS0K) desde 03.2009 50KW 68CV 1461CC K9K 792 8212AAS - DACIA LOGAN EXPRESS (FS_) 1.5 dCi (FS0W) desde 03.2009 63KW 86CV ...</p> <p>d104x45mm d79x20mm d56x47mm 1f-d15mm 1f-d16mm 1r-d12mm</p>		<p>A32744 NO. 543A06915R - 6001547499 - 6001548403 - 8200275528 - 8200307941 - 8200651172 - 8200723741 - 820087629...</p> <p>APOIO SUPORTE AMORTECEDOR FRENTE (GASTA 2 UNIDADES)</p> <p>DACIA LOGAN MCV (KS_) 1.4 desde 02.2007 55KW 75CV 1390CC K7J 710 8212AAH - DACIA LOGAN MCV (KS_) 1.5 dCi (KS04) 05.2010/06.2013 55KW 75CV 1461CC K9K 892 8212ABO - DACIA LOGAN MCV (KS_) 1.5 dCi (KS04) desde 05.2010 65KW 88CV 1461CC K9K 892 8212ABM - DACIA LOGAN MCV (KS_) 1.5 dCi (KS0K) desde 02.2007 50KW 68CV 1461CC K9K 792 8212AAF - DACIA LOGAN MCV (KS_) 1.5 dCi (KS0W) 09.2007/12.2012 63KW 86CV 14...</p> <p>d104x45mm d79x20mm d56x47mm 1f-d15mm 1f-d16mm 1r-d12mm</p>
	<p>A32744 NO. 543A06915R - 6001547499 - 6001548403 - 8200275528 - 8200307941 - 8200651172 - 8200723741 - 820087629...</p> <p>APOIO SUPORTE AMORTECEDOR FRENTE (GASTA 2 UNIDADES)</p> <p>DACIA LOGAN II 1.2 desde 10.2012 55KW 75CV 1149CC D4F 732 8212AAV - DACIA LOGAN II 1.2 LPG desde 10.2012 55KW 75CV 1149CC D4F 734 8212ACR - DACIA LOGAN II 1.5 dCi desde 10.2012 66KW 90CV 1461CC K9K 612 K9K 626 8212ADA - DACIA LOGAN II 1.5 dCi / Blue dCi 75 desde 10.2012 55KW 75CV 1461CC K9K 872 K9K 612 K9K 626 8212ABQ - DACIA LOGAN II Tce 90 desde 10.2012 66KW 90CV 898CC H4B 408 H4B 400 8212ACY - ...</p> <p>d104x45mm d79x20mm d56x47mm 1f-d15mm 1f-d16mm 1r-d12mm</p>		<p>A32744 NO. 543A06915R - 6001547499 - 6001548403 - 8200275528 - 8200307941 - 8200651172 - 8200723741 - 820087629...</p> <p>APOIO SUPORTE AMORTECEDOR FRENTE (GASTA 2 UNIDADES)</p> <p>DACIA LOGAN Pick-up (US_) 1.4 desde 01.2009 55KW 75CV 1390CC K7J 710 8212AAR - DACIA LOGAN Pick-up (US_) 1.5 dCi desde 05.2010 55KW 75CV 1461CC K9K 892 8212ABW - DACIA LOGAN Pick-up (US_) 1.5 dCi desde 05.2010 65KW 88CV 1461CC K9K 892 8212ABX - DACIA LOGAN Pick-up (US_) 1.5 dCi (US0K) desde 03.2008 50KW 68CV 1461CC K9K 792 8212AAS - DACIA LOGAN Pick-up (US_) 1.5 dCi (US0W) desde 03.2008 63KW 86CV ...</p> <p>d104x45mm d79x20mm d56x47mm 1f-d15mm 1f-d16mm 1r-d12mm</p>
	<p>E0217-M NO. 112383665R - 6001549205 - 6001549647 - 8200014933 - 8200050928 - 8200575641</p> <p>ESTICADOR SUPORTE APOIO MOTOR TRAS</p> <p>DACIA LOGAN (LS_) 1.2 16V desde 02.2006/>>> 55KW 75CV 1149CC D4F 732 8212AAV - DACIA LOGAN (LS_) 1.2 16V LPG desde 02.2006/>>> 55KW 75CV 1149CC D4F 734 8212ACR - DACIA LOGAN (LS_) 1.4 (LSOA, LSOC, LSOE, LSOG) desde 09.2004/>>> 55KW 75CV 1390CC K7J 710 8212001 8212AAA 8212ABB - DACIA LOGAN (LS_) 1.4 MPI LPG (LS0C) 02.2006/12.2012 55KW 75CV 1390CC K7J 714 K7J 710 8212AAW - DACIA LOGAN (LS_) 1.5 dCi ...</p> <p>270x90x60mm 2f-d13mm</p>		<p>E0246-M NO. 11360-9U000 - 11360-AX000 - 11360-AX600 - 11360-BN700 - 11360-ED000 - 11360-ED55A - 11360-EU00A 11...</p> <p>ESTICADOR SUPORTE APOIO MOTOR TRAS</p> <p>DACIA LOGAN (LS_) 1.4 (LSOA, LSOC, LSOE, LSOG) desde 09.2004 55KW 75CV 1390CC K7J 710 K7J 714 8212001 8212AAA 8212ABB - DACIA LOGAN (LS_) 1.5 dCi (LS0J, LS0Y) desde 09.2005 48KW 65CV 1461CC K9K 790 - DACIA LOGAN (LS_) 1.5 dCi (LS0K) 01.2006/12.2012 50KW 68CV 1461CC K9K 792 8212AAC - DACIA LOGAN (LS_) 1.5 dCi (LS0W) 09.2007/12.2011 63KW 86CV 1461CC K9K 796 8212AAJ 8212AAZ - DACIA LOGAN (LS_) 1.6 (L...</p> <p>265x90x52mm 1f-d12mm 1f-d13mm</p>
	<p>E0267-M NO. 112381035R - 112383905R</p> <p>ESTICADOR SUPORTE APOIO MOTOR TRAS</p> <p>DACIA LOGAN II: Tce 90 10.2012/>>> 66KW 90CV 898CC - DACIA LOGAN II: 1.2 10.2012/>>> 55KW 75CV 1149CC - DACIA LOGAN II: 1.2 LPG 10.2012/>>> 55KW 75CV 1149CC - DACIA LOGAN II: 1.6 16V 01.2013/>>> 77KW 105CV 1598CC - DACIA LOGAN II: 1.5 dCi / Blue dCi 75 10.2012/>>> 55KW 75CV 1461CC - DACIA LOGAN II: 1.5 dCi 01.2013/>>> 63KW 84CV 1461CC - DACIA LOGAN II: 1.5 dCi 10.2012/>>> 66KW 90CV 1461CC - DACIA LOGA...</p> <p>170x60x55mm 1f-d12mm 1f-d14mm</p>		<p>F1898-I NO. 392414459R - 6001547767 - 6001550339 - 6001551490 - 7701473830 - 8200017057</p> <p>FOLE TRANSMISSÃO JUNTO CAIXA</p> <p>DACIA LOGAN (LS.): 1.2 16V 02.2006/>>> 55KW 75CV 1149CC - DACIA LOGAN (LS.): 1.2 16V LPG 02.2006/>>> 55KW 75CV 1149CC - DACIA LOGAN (LS.): 1.4 (LSOA, LSOC, LSOE, LSOG) 09.2004/>>> 55KW 75CV 1390CC - DACIA LOGAN (LS.): 1.4 MPI LPG (LS0C) 02.2006/>>> 55KW 75CV 1390CC - DACIA LOGAN (LS.): 1.6 MPI 85 05.2010/>>> 62KW 84CV 1598CC - DACIA LOGAN (LS.): 1.6 Bifuel 05.2010/>>> 62KW 84CV 1598CC - DACIA LOGA...</p> <p>d107x89mm 1f-d30mm 1f-d78mm</p>
	<p>F1898-I NO. 392414459R - 6001547767 - 6001550339 - 6001551490 - 7701473830 - 8200017057</p> <p>FOLE TRANSMISSÃO JUNTO CAIXA</p> <p>DACIA SOLENZA (B41_) 1.4 (B41A, B41B, B41C) 02.2003/>>> 55KW 75CV 1390CC - DACIA SOLENZA (B41_) 1.9 D (B41E, B41F, B41G) 02.2003/>>> 46KW 63CV 1870CC</p> <p>d107x89mm 1f-d30mm 1f-d78mm</p>		<p>F1898A3-I NO. 392414459R - 6001547767 - 6001550339 - 6001551490 - 7701473830 - 8200017057</p> <p>FOLE TRANSMISSÃO JUNTO CAIXA</p> <p>DACIA LOGAN (LS.): 1.2 16V 02.2006/>>> 55KW 75CV 1149CC - DACIA LOGAN (LS.): 1.2 16V LPG 02.2006/>>> 55KW 75CV 1149CC - DACIA LOGAN (LS.): 1.4 (LSOA, LSOC, LSOE, LSOG) 09.2004/>>> 55KW 75CV 1390CC - DACIA LOGAN (LS.): 1.4 MPI LPG (LS0C) 02.2006/>>> 55KW 75CV 1390CC - DACIA LOGAN (LS.): 1.6 MPI 85 05.2010/>>> 62KW 84CV 1598CC - DACIA LOGAN (LS.): 1.6 Bifuel 05.2010/>>> 62KW 84CV 1598CC - DACIA LOGA...</p> <p>d107x89mm 1f-d25.8mm 1f-d78mm</p>
	<p>F1898A3-I NO. 392414459R - 6001547767 - 6001550339 - 6001551490 - 7701473830 - 8200017057</p> <p>FOLE TRANSMISSÃO JUNTO CAIXA</p> <p>DACIA SOLENZA (B41_) 1.4 (B41A, B41B, B41C) 02.2003/10.2005 55KW 75CV 1390CC E7J 262 - DACIA SOLENZA (B41_) 1.9 D (B41E, B41F, B41G) desde 02.2003 46KW 63CV 1870CC F8Q 636</p> <p>d107x89mm 1f-d25.8mm 1f-d78mm</p>		<p>F4145 NO. 6001548402 - 6001549290 - 8200499414 - 8200814709</p> <p>FOLE CAPA PROTEÇÃO AMORTECEDOR FRENTE (GASTA 2 UNIDADES)</p> <p>DACIA LOGAN (LS.): 1.2 16V 02.2006/>>> 55KW 75CV 1149CC - DACIA LOGAN (LS.): 1.2 16V LPG 02.2006/>>> 55KW 75CV 1149CC - DACIA LOGAN (LS.): 1.4 (LSOA, LSOC, LSOE, LSOG) 09.2004/>>> 55KW 75CV 1390CC - DACIA LOGAN (LS.): 1.4 MPI LPG (LS0C) 02.2006/>>> 55KW 75CV 1390CC - DACIA LOGAN (LS.): 1.6 MPI 85 05.2010/>>> 62KW 84CV 1598CC - DACIA LOGAN (LS.): 1.6 Bifuel 05.2010/>>> 62KW 84CV 1598CC - DACIA LOGA...</p> <p>d75x220mm 1f-d55mm 1f-d18mm</p>

	<p>F4366 NO. 969356242R</p> <p>FOLE DA ALAVANCA DE VELOCIDADES</p> <p>DACIA LOGAN II 1.0 LPG (11.2019 -) 74kw 101cv 999cm3 três volumes DACIA LOGAN II 1.0 SCe 75 (01.2017 -) 54kw 73cv 998cm3 três volumes DACIA LOGAN II 1.0 TCe 100 (11.2019 -) 74kw 101cv 999cm3 três volumes DACIA LOGAN II 1.2 (05.2015 -) 54kw 73cv 1149cm3 três volumes DACIA LOGAN II 1.2 (10.2012 -) 55kw 75cv 1149cm3 três volumes DACIA LOGAN II 1.2 LPG (10.2012 -) 55kw 75cv 1149cm3 três volumes DACIA ...</p> <p>240x108x137mm 1f-96x122mm</p>		<p>F9082H-I NO. 6001548666 - 7701209242</p> <p>FOLE TRANSMISSÃO JUNTO RODA</p> <p>DACIA LOGAN (LS_) : 1.4 (LSOA, LSOC, LSOE, LSOG) 09.2004/»» 55KW 75CV 1390CC - DACIA LOGAN (LS_) : 1.4 MPI LPG (LSOC) 02.2006/»» 55KW 75CV 1390CC - DACIA LOGAN (LS_) : 1.6 (LSOB, LSOD, LSOF, LSOH) 09.2004/»» 64KW 87CV 1598CC - DACIA LOGAN (LS_) : 1.6 (LSOJ, LSOL, LSOM, LSOP, LS0V, LS18, LS1S, LS1V,... 02.2006/»» 77KW 105CV 1598CC - DACIA LOGAN (LS_) : 1.5 dCi (LSOJ, LS0Y) 09.2005/»» 48KW 65CV ...</p> <p>d87x101mm 1f-d25mm 1f-d80mm</p>
	<p>F9530H-I NO. 482034581R</p> <p>FOLE DA DIREÇÃO LADO DIREITO E ESQUERDO</p> <p>DACIA LOGAN II 1.0 SCe 75 desde 01.2017 54KW 73CV 998CC B4D 401 B4D 400 8212AEK - DACIA LOGAN II 1.2 desde 10.2012 55KW 75CV 1149CC D4F 732 8212AAV - DACIA LOGAN II 1.2 desde 05.2015 54KW 73CV 1149CC 8212ADS - DACIA LOGAN II 1.2 LPG desde 10.2012 55KW 75CV 1149CC D4F 734 8212ACR - DACIA LOGAN II 1.5 dCi desde 10.2012 66KW 90CV 1461CC K9K 612 K9K 626 8212ADA - DACIA LOGAN II 1.5 dCi desde 01.2013 6...</p> <p>d60x166mm 1f-d12mm 1f-d15mm</p>		<p>F9530H-I NO. 482034581R</p> <p>FOLE DA DIREÇÃO LADO DIREITO E ESQUERDO</p> <p>DACIA LOGAN MCV II 1.0 SCe 75 desde 12.2016 54KW 73CV 998CC B4D 401 B4D 400 8212AEJ 8212AEL - DACIA LOGAN MCV II 1.2 desde 02.2013 55KW 75CV 1149CC D4F 732 8212ADE - DACIA LOGAN MCV II 1.2 desde 05.2015 54KW 73CV 1149CC D4F 732 8212ADU - DACIA LOGAN MCV II 1.2 LPG desde 02.2013 55KW 75CV 1149CC D4F 734 8212ADF - DACIA LOGAN MCV II 1.5 dCi desde 02.2013 55KW 75CV 1461CC K9K 626 K9K 612 8212...</p> <p>d60x166mm 1f-d12mm 1f-d15mm</p>
	<p>KF1695-I NO. 7701209258 - 7701471522</p> <p>KIT FOLE DIREITO TRANSMISSÃO JUNTO CAIXA</p> <p>DACIA LOGAN (LS_) : 1.4 (LSOA, LSOC, LSOE, LSOG) 09.2004/»» 55KW 75CV 1390CC - DACIA LOGAN (LS_) : 1.6 (LSOB, LSOD, LSOF, LSOH) 09.2004/»» 64KW 87CV 1598CC - DACIA LOGAN (LS_) : 1.6 16V (LSOJ, LSOL, LSOM, LSOP, LS0V, LS18, LS1S, LS1V,... 02.2006/»» 77KW 105CV 1598CC - DACIA LOGAN MCV (KS_) : 1.4 02.2007/»» 55KW 75CV 1390CC - DACIA LOGAN MCV (KS_) : 1.6 02.2007/»» 64KW 87CV 1598CC - DACIA LOGAN MCV...</p> <p>d86x98mm 1f-d22mm 1f-d74mm</p>		<p>KF1695-I NO. 7701209258</p> <p>KIT FOLE DIREITO TRANSMISSÃO JUNTO CAIXA</p> <p>DACIA SOLENZA (B41_) : 1.4 (B41A, B41B, B41C) 02.2003/10.2005 55KW 75CV 1390CC - DACIA SOLENZA (B41_) : 1.9 D (B41E, B41F, B41G) 02.2003/»» 46KW 63CV 1870CC</p> <p>d86x98mm 1f-d22mm 1f-d74mm</p>
	<p>KF1842-I NO. 6001550548 - 7701209925 - 7701209929</p> <p>FOLE DA TRANSMISSÃO JUNTO À CAIXA</p> <p>DACIA LOGAN (LS_) 1.5 dCi (LS04) 05.2010/12.2012 55KW 75CV 1461CC K9K 892 8212ABQ - DACIA LOGAN (LS_) 1.5 dCi (LS04) desde 05.2010 65KW 88CV 1461CC K9K 892 8212ABP - DACIA LOGAN (LS_) 1.5 dCi (LS0W) 09.2007/12.2011 63KW 86CV 1461CC K9K 796 8212AAJ 8212AAY - DACIA LOGAN (LS_) 1.6 16V Flexifuel desde 07.2010 77KW 105CV 1598CC K4M 696 8212ACJ 8212ACD - DACIA LOGAN EXPRESS (FS_) 1.4 desde 03.2009 55KW...</p> <p>d83x86mm 1f-d19mm 1f-d72mm</p>		<p>KF1898A3-I NO. 7701473830</p> <p>KIT FOLE TRANSMISSÃO JUNTO CAIXA</p> <p>DACIA LOGAN (LS_) 1.2 16V (LS1N, LS02, BS02) desde 02.2006 55KW 75CV 1149CC D4F 732 D4F 734 8212AAV - DACIA LOGAN (LS_) 1.2 16V LPG desde 02.2006 55KW 75CV 1149CC D4F 734 8212ACR - DACIA LOGAN (LS_) 1.4 (LSOA, LSOC, LSOE, LSOG) desde 09.2004 55KW 75CV 1390CC K7J 710 K7J 714 8212001 8212AAA 8212ABB - DACIA LOGAN (LS_) 1.4 MPI LPG (LSOC) 02.2006/12.2012 55KW 75CV 1390CC K7J 714 K7J 710 8212AAW - DAC...</p> <p>d107x89mm 1f-d25.8mm 1f-d78mm</p>
	<p>KF1898A3-I NO. 7701473830</p> <p>KIT FOLE TRANSMISSÃO JUNTO CAIXA</p> <p>DACIA SOLENZA (B41_) 1.4 (B41A, B41B, B41C) 02.2003/10.2005 55KW 75CV 1390CC E7J 262 - DACIA SOLENZA (B41_) 1.9 D (B41E, B41F, B41G) desde 02.2003 46KW 63CV 1870CC F8Q 636</p> <p>d107x89mm 1f-d25.8mm 1f-d78mm</p>		<p>KF9015 NO. 3910100Q1G - 6001548164 - 7701209255</p> <p>KIT DE FOLE DO CARDAN JUNTO À CAIXA</p> <p>DACIA LOGAN (LS_) 1.2 16V (LS1N, LS02, BS02) desde 02.2006 55KW 75CV 1149CC D4F 732 D4F 734 8212AAV - DACIA LOGAN (LS_) 1.2 16V LPG desde 02.2006 55KW 75CV 1149CC D4F 734 8212ACR - DACIA LOGAN (LS_) 1.5 dCi (LS04) 05.2010/12.2012 55KW 75CV 1461CC K9K 892 8212ABQ - DACIA LOGAN (LS_) 1.5 dCi (LS04) desde 05.2010 65KW 88CV 1461CC K9K 892 8212ABP - DACIA LOGAN (LS_) 1.5 dCi (LS0J, LS0Y) desde 09.2005 ...</p> <p>d86x104mm 1f-d76mm 1f-d25mm</p>
	<p>KN96019 NO. 7701475118</p> <p>KIT ORINGS DO RADIADOR DO ÓLEO</p> <p>DACIA LOGAN (LS_) 1.2 16V (LS1N, LS02, BS02) desde 02.2006 55KW 75CV 1149CC D4F 732 D4F 734 8212AAV - DACIA LOGAN (LS_) 1.2 16V LPG desde 02.2006 55KW 75CV 1149CC D4F 734 8212ACR - DACIA LOGAN (LS_) 1.4 MPI LPG (LSOC) 02.2006/12.2012 55KW 75CV 1390CC K7J 714 K7J 710 8212AAW - DACIA LOGAN (LS_) 1.5 dCi (LS04) 05.2010/12.2012 55KW 75CV 1461CC K9K 892 8212ABQ - DACIA LOGAN (LS_) 1.5 dCi (LS04) desde ...</p> <p>d70x5mm d30x5mm d25x31f-d66mm 1f-d20mm 1f-d18mm</p>		<p>KN96019 NO. 7701475118</p> <p>KIT ORINGS DO RADIADOR DO ÓLEO</p> <p>DACIA LOGAN II 1.0 SCe 75 desde 01.2017 54KW 73CV 998CC B4D 401 B4D 400 8212AEK - DACIA LOGAN II 1.5 Blue dCi 95 (L8JL) desde 05.2018 70KW 95CV 1461CC K9K 872 8212AER - DACIA LOGAN II TCe 90 LPG desde 09.2015 66KW 90CV 898CC H4B 405 H4B 410 8212ADX</p> <p>d70x5mm d30x5mm d25x31f-d66mm 1f-d20mm 1f-d18mm</p>
	<p>KN96019 NO. 7701475118</p> <p>KIT ORINGS DO RADIADOR DO ÓLEO</p> <p>DACIA LOGAN Pick-up (US_) 1.5 dCi desde 05.2010 55KW 75CV 1461CC K9K 892 8212ABW - DACIA LOGAN Pick-up (US_) 1.5 dCi desde 05.2010 65KW 88CV 1461CC K9K 892 8212ABX - DACIA LOGAN Pick-up (US_) 1.5 dCi (US0K) desde 03.2008 50KW 68CV 1461CC K9K 792 8212AAS - DACIA LOGAN Pick-up (US_) 1.5 dCi (US0W) desde 03.2008 63KW 86CV 1461CC K9K 796 8212AAT - DACIA LOGAN Pick-up (US_) 1.6 desde 03.2008 64KW 87CV 15...</p> <p>d70x5mm d30x5mm d25x31f-d66mm 1f-d20mm 1f-d18mm</p>		<p>KUA24400 NO. 7701208148</p> <p>KIT REPARAÇÃO RETENTOR HNBR VEDAÇÃO AR CONDICIONADO (BORRACHA ACRILONITRILICO-BUTADIENO HNBRC60N90)</p> <p>DACIA LOGAN (LS_) 1.2 16V (LS1N, LS02, BS02) desde 02.2006 55KW 75CV 1149CC D4F 732 D4F 734 8212AAV - DACIA LOGAN (LS_) 1.2 16V LPG desde 02.2006 55KW 75CV 1149CC D4F 734 8212ACR - DACIA LOGAN (LS_) 1.4 (LSOA, LSOC, LSOE, LSOG) desde 09.2004 55KW 75CV 1390CC K7J 710 K7J 714 8212001 8212AAA 8212ABB - DACIA LOGAN (LS_) 1.4 MPI LPG (LSOC) 02.2006/12.2012 55KW 75CV 1390CC K7J 714 K7J 710 8212AAW - DAC...</p> <p>d21x9mm(x4) d15x9mm(x4) 1f-d17mm(x4) 1f-d11mm(x4)</p>
	<p>KUA24400 NO. 7701208148</p> <p>KIT REPARAÇÃO RETENTOR HNBR VEDAÇÃO AR CONDICIONADO (BORRACHA ACRILONITRILICO-BUTADIENO HNBRC60N90)</p> <p>DACIA LOGAN EXPRESS (FS_) 1.4 desde 03.2009 55KW 75CV 1390CC K7J 710 8212AAR - DACIA LOGAN EXPRESS (FS_) 1.5 dCi desde 05.2010 55KW 75CV 1461CC K9K 892 8212ABW - DACIA LOGAN EXPRESS (FS_) 1.5 dCi desde 05.2010 65KW 88CV 1461CC K9K 892 8212ABX - DACIA LOGAN EXPRESS (FS_) 1.5 dCi (FS0K) desde 03.2009 50KW 68CV 1461CC K9K 792 8212AAS - DACIA LOGAN EXPRESS (FS_) 1.5 dCi (FS0W) desde 03.2009 63KW 86CV...</p> <p>d21x9mm(x4) d15x9mm(x4) 1f-d17mm(x4) 1f-d11mm(x4)</p>		<p>KUA24400 NO. 7701208148</p> <p>KIT REPARAÇÃO RETENTOR HNBR VEDAÇÃO AR CONDICIONADO (BORRACHA ACRILONITRILICO-BUTADIENO HNBRC60N90)</p> <p>DACIA LOGAN II 1.2 desde 10.2012 55KW 75CV 1149CC D4F 732 8212AAV - DACIA LOGAN II 1.2 desde 05.2015 54KW 73CV 1149CC 8212ADS - DACIA LOGAN II 1.2 LPG desde 05.2015 54KW 73CV 1149CC 8212ADS - DACIA LOGAN II 1.2 LPG desde 05.2015 54KW 73CV 1149CC D4F 734 8212ACR - DACIA LOGAN II 1.5 Blue dCi 95 (L8JL) desde 05.2018 70KW 95CV 1461CC K9K 872 8212AER - DACIA LOGAN II 1.5 dCi desde 10.2012 66KW 90CV 1461CC K9K 612 K9K 626 8212ADA - DACIA LOGAN II 1.5 dCi desde 01.2013 6...</p> <p>d21x9mm(x4) d15x9mm(x4) 1f-d17mm(x4) 1f-d11mm(x4)</p>

	<p>KUA24400 NO. 7701208148</p> <p>KIT REPARAÇÃO RETENTOR Hnbr VEDAÇÃO AR CONDICIONADO (BORRACHA ACRILONITRILICO-BUTADIENO HIBRIDO COM ANILIN)</p> <p>DACIA LOGAN Pick-up (US_) 1.4 desde 01.2009 55KW 75CV 1390CC K7J 710 8212AAR -</p> <p>DACIA LOGAN Pick-up (US_) 1.5 dCi desde 05.2010 55KW 75CV 1461CC K9K 892 - DACIA LOGAN Pick-up (US_) 1.5 dCi desde 05.2010 65KW 88CV 1461CC K9K 892 8212ABX - DACIA LOGAN Pick-up (US_) 1.5 dCi (US0K) desde 03.2008 50KW 68CV 1461CC K9K 792 8212AAS - DACIA LOGAN Pick-up (US_) 1.5 dCi (US0W) desde 03.2008 63KW 86CV 1461CC...</p> <p>d21x9mm(x4) d15x9mm(x4) 1f-d17mm(x4) 1f-d11mm(x4)</p>		<p>L25623 NO. 8200059575 - 8200059578 - 8200079112 - 8200079113 - 8200379950 - 8200596157</p> <p>CASQUILHO INTERIOR MANETE VELOCIDADES</p> <p>DACIA LOGAN I (LS_) 1.4 09.2004/>>> 55KW 75CV 1390CC - DACIA LOGAN I (LS_) 1.6 09.2004/>>> 64KW 87CV 1598CC - DACIA LOGAN I (LS_) 1.6 (LS0L, LS09, LS0V, LS0P, LS18, LS1S, LS1V, LS1Y,... 04.2007/>>> 77KW 105CV 1598CC - DACIA LOGAN I (LS_) 1.5 dCi 06.2011/>>> 48KW 65CV 1461CC - DACIA LOGAN I (LS_) 1.5 dCi 04.2007/>>> 50KW 68CV 1461CC - DACIA LOGAN I (LS_) 1.5 dCi 02.2008/06.2015 63KW 86CV 1461...</p> <p>d16x65mm 1f-d11mm</p>
	<p>L81653 NO. 7701056972 - 7701060158</p> <p>CASQUILHO COBERTURA TAMPA DO MOTOR</p> <p>DACIA LOGAN (LS_) 1.5 dCi (LS0J, LS0Y) 09.2005/>>> 48KW 65CV 1461CC - DACIA LOGAN (LS_) 1.5 dCi (LS0K) 01.2006/>>> 50KW 68CV 1461CC - DACIA LOGAN (LS_) 1.5 dCi (LS0W) 09.2007/>>> 63KW 86CV 1461CC - DACIA LOGAN MCV (KS_) 1.5 dCi (KS0K) 02.2007/>>> 50KW 68CV 1461CC - DACIA LOGAN MCV (KS_) 1.5 dCi (KS0W) 09.2007/>>> 63KW 86CV 1461CC - DACIA LOGAN EXPRESS (FS_) 1.5 dCi (FS0K) 03.2009/>>> 50KW 68...</p> <p>d37/31mm d17/11mm 1f-d15mm</p>		<p>P1104 NO. 6001547908</p> <p>CAPA DE PEDAL DO TRAVÃO</p> <p>DACIA LOGAN (LS_) 1.2 16V 02.2006/>>> 55KW 75CV 1149CC - DACIA LOGAN (LS_) 1.4 (LSOA, LSOC, LSOE, LSOG) 09.2004/>>> 55KW 75CV 1390CC - DACIA LOGAN (LS_) 1.4 MPI LPG (LS0C) 02.2006/>>> 55KW 75CV 1390CC - DACIA LOGAN (LS_) 1.6 MPI 85 05.2010/>>> 62KW 84CV 1598CC - DACIA LOGAN (LS_) 1.6 Bifuel 05.2010/>>> 62KW 84CV 1598CC - DACIA LOGAN (LS_) 1.6 (LSOB, LSOD, LSOF, LSOH) 09.2004/>>> 64KW 87CV 15...</p> <p>60x60x13mm 50x47x40mm</p>
	<p>P1129 NO. 465310981R - 6001551783</p> <p>CAPA DE PEDAL DO TRAVÃO</p> <p>DACIA LOGAN (LS_) 1.2 16V (LS1N, LS02, BS02) desde 02.2006 55KW 75CV 1149CC D4F 732 D4F 734 8212AAV - DACIA LOGAN (LS_) 1.4 (LSOA, LSOC, LSOE, LSOG) desde 09.2004 55KW 75CV 1390CC K7J 710 K7J 714 8212001 8212AAA 8212ABB - DACIA LOGAN (LS_) 1.4 MPI LPG (LS0C) 02.2006/12.2012 55KW 75CV 1390CC K7J 714 K7J 710 8212AAW - DACIA LOGAN (LS_) 1.5 dCi (LS04) 05.2010/12.2012 55KW 75CV 1461CC K9K 892 8212ABQ ...</p> <p>75x53x10mm 1f-d-52x33mm</p>		<p>P1129 NO. 465310981R - 6001551783</p> <p>CAPA DE PEDAL DO TRAVÃO</p> <p>DACIA LOGAN MCV (KS_) 1.4 desde 02.2007 55KW 75CV 1390CC K7J 710 8212AAH - DACIA LOGAN MCV (KS_) 1.5 dCi (KS04) 05.2010/06.2013 55KW 75CV 1461CC K9K 892 8212ABO - DACIA LOGAN MCV (KS_) 1.5 dCi (KS04) desde 05.2010 65KW 88CV 1461CC K9K 892 8212ABM - DACIA LOGAN MCV (KS_) 1.5 dCi (KS0K) desde 02.2007 50KW 68CV 1461CC K9K 792 8212AAF - DACIA LOGAN MCV (KS_) 1.5 dCi (KS0W) 09.2007/12.2012 63KW 86CV 14...</p> <p>75x53x10mm 1f-d-52x33mm</p>
	<p>Q2009 NO.</p> <p>UNIÃO DE ESCAPE 47/52,5x90mm</p> <p>DACIA - LOGAN (LS_) - 1.4 (LSOA - LSOC - LSOE - LSOG) (APÓS 09.04) 75cv 1390cc três volumes - DACIA - LOGAN (LS_) - 1.6 (LSOB - LSOD - LSOF - LSOH) (APÓS 09.04) 87cv 1598cc três volumes - DACIA - LOGAN (LS_) - 1.6 16V (LS0M) (APÓS 02.06) 105cv 1598cc três volu</p> <p>90x58x78mm 1f-d47mm</p>		<p>R080330 NO. 14875-00QAB - 7700101229 - 8200035903 - 8200134513</p> <p>TUBO RIGIDO REFRIGERAÇÃO</p> <p>DACIA LOGAN (LS_) 1.6 16V (LS09, LS0L, LS0M, LS0P, LS0V, LS18, LS1S, LS1V,... 02.2006/>>> 77KW 105CV 1598CC - DACIA LOGAN (LS_) 1.6 16V Flexifuel 07.2010/>>> 77KW 105CV 1598CC - DACIA LOGAN MCV (KS_) 1.6 16V (KS0L, KS0M, KS0P, KS1S) 02.2007/>>> 77KW 105CV 1598CC - DACIA LOGAN MCV (KS_) 1.6 16V Hi-Flex 11.2009/>>> 77KW 105CV 1598CC</p> <p>B365-26/26mm 76-320mm 1p-d20x45mm 1f-6x13</p>
	<p>R080332 NO. 56x203x70mm ch-d20x27mm ch-d18x43m</p> <p>TUBO RIGIDO DA REFRIGERAÇÃO</p> <p>DACIA LOGAN Pick-up (US_) 1.5 dCi (US0K) desde 03.2008 50KW 68CV 1461CC K9K 792 8212AAS</p> <p>B359-27/27mm 56x203x70mm ch-d20x27mm ch-d18x43m</p>		<p>R085226 NO. 1404200Q0C - 8200934107</p> <p>TUBO EXTRACTOR COMBUSTIVEL</p> <p>DACIA LOGAN (LS_) 1.5 dCi (LS04) (05.2010 - 12.2012) 55kw 75cv 1461 três volumes DACIA LOGAN (LS_) 1.5 dCi (LS04) (05.2010 -) 65kw 88cv 1461 três volumes DACIA LOGAN (LS_) 1.5 dCi (LS0J, LS0Y) (09.2005 -) 48kw 65cv 1461 três volumes DACIA LOGAN (LS_) 1.5 dCi (LS0K) (01.2006 - 12.2012) 50kw 68cv 1461 três volumes DACIA LOGAN (LS_) 1.5 dCi (LS0W) (09.2007 - 12.2011) 63kw 86cv 1461 três volumes</p> <p>B325-5/5mm 66x340x60x66mm</p>
	<p>R085226 NO. 1404200Q0C - 8200934107</p> <p>TUBO EXTRACTOR COMBUSTIVEL</p> <p>DACIA LOGAN EXPRESS (FS_) 1.5 dCi (05.2010 -) 55kw 75cv 1461cm3 Caixa/Combi DACIA LOGAN EXPRESS (FS_) 1.5 dCi (05.2010 -) 65kw 88cv 1461cm3 Caixa/Combi DACIA LOGAN EXPRESS (FS_) 1.5 dCi (FS0W) (03.2009 -) 63kw 86cv 1461cm3 Caixa/Combi</p> <p>B325-5/5mm 66x340x60x66mm</p>		<p>R085226 NO. 1404200Q0C - 8200934107</p> <p>TUBO EXTRACTOR COMBUSTIVEL</p> <p>DACIA LOGAN II 1.5 dCi (01.2013 -) 63kw 84cv 1461cm3 três volumes DACIA LOGAN II 1.5 dCi (10.2012 -) 66kw 90cv 1461cm3 três volumes DACIA LOGAN II 1.5 dCi / Blue dCi 75 (10.2012 -) 55kw 75cv 1461cm3 três volumes</p> <p>B325-5/5mm 66x340x60x66mm</p>
	<p>R085226 NO. 1404200Q0C - 8200934107</p> <p>TUBO EXTRACTOR COMBUSTIVEL</p> <p>DACIA LOGAN MCV (KS_) 1.5 dCi (KS04) (05.2010 - 06.2013) 55kw 75cv 1461cm3 Combi DACIA LOGAN MCV (KS_) 1.5 dCi (KS04) (05.2010 -) 65kw 88cv 1461cm3 Combi DACIA LOGAN MCV (KS_) 1.5 dCi (KS0W) (09.2007 - 12.2012) 63kw 86cv 1461cm3 Combi</p> <p>B325-5/5mm 66x340x60x66mm</p>		<p>R085226 NO. 1404200Q0C - 8200934107</p> <p>TUBO EXTRACTOR COMBUSTIVEL</p> <p>DACIA LOGAN MCV II 1.5 dCi (02.2013 -) 55kw 75cv 1461cm3 Combi DACIA LOGAN MCV II 1.5 dCi (02.2013 -) 63kw 84cv 1461cm3 Combi DACIA LOGAN MCV II 1.5 dCi (02.2013 -) 66kw 90cv 1461cm3 Comb</p> <p>B325-5/5mm 66x340x60x66mm</p>
	<p>R085226 NO. 1404200Q0C - 8200934107</p> <p>TUBO EXTRACTOR COMBUSTIVEL</p> <p>DACIA LOGAN Pick-up (US_) 1.5 dCi 05.2010 - 55kw 75cv 1461cm3 Pick-up DACIA LOGAN Pick-up (US_) 1.5 dCi 05.2010 - 65kw 88cv 1461cm3 Pick-up DACIA LOGAN Pick-up (US_) 1.5 dCi (US0K) 03.2008 - 50kw 68cv 1461cm3 Pick-up</p> <p>B325-5/5mm 66x340x60x66mm</p>		<p>R223276 NO. 7701061051</p> <p>TUBO LIGAÇÃO TERMOSTATO</p> <p>DACIA LOGAN (LS_) 1.5 dCi (LS0J, LS0Y) desde 09.2005/>>> 48KW 65CV 1461CC K9K 790 - DACIA LOGAN (LS_) 1.5 dCi (LS0K) 01.2006/12.2012 50KW 68CV 1461CC K9K 792 8212AAC - DACIA LOGAN (LS_) 1.5 dCi (LS0W) 09.2007/12.2011 63KW 86CV 1461CC K9K 796 8212AAJ, 8212AAY - DACIA LOGAN EXPRESS (FS_) 1.5 dCi (FS0K) desde 03.2009/>>> 50KW 68CV 1461CC K9K 792 8212AAS - DACIA LOGAN EXPRESS (FS_) 1.5 dCi (FS0W) desde...</p> <p>B117-15/19mm 78-73mm ch-d20-50mm</p>

	<p>R223383 NO. 8200240894 - 8200384940</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA LOGAN (LS_) 1.5 dCi (LS0J, LS0Y) desde 09.2005 48KW 65CV 1461CC K9K 790 - DACIA LOGAN (LS_) 1.5 dCi (LS0K) 01.2006/12.2012 50KW 68CV 1461CC K9K 792 8212AAC - DACIA LOGAN (LS_) 1.5 dCi (LS0W) 09.2007/12.2011 63KW 86CV 1461CC K9K 796 8212AAJ 8212AAY</p> <p>B660-33/51mm 69-105-170-420-125mm</p>		<p>R223461 NO. 1446000Q0J - 1446000Q0L - 1446000QAD - 1446000QAE - 14460AY900 - 14460BN709 - 8200136780 - 820027916</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA LOGAN (LS_) 1.5 dCi (LS0J, LS0Y) desde 09.2005 48KW 65CV 1461CC K9K 790 - DACIA LOGAN (LS_) 1.5 dCi (LS0K) 01.2006/12.2012 50KW 68CV 1461CC K9K 792 8212AAC</p> <p>B141-36/40mm 50x98x49x58mm 2ch-d11x177mm</p>
	<p>R223463 NO. 14460BN706 - 8200143188 - 8200143788 - 8200280084 - 8200368252</p> <p>TUBO ADMISSÃO FILTRO DE AR</p> <p>DACIA LOGAN (LS_) 1.5 dCi (LS0J, LS0Y) desde 09.2005 48KW 65CV 1461CC K9K 790 - DACIA LOGAN (LS_) 1.5 dCi (LS0K) 01.2006/12.2012 50KW 68CV 1461CC K9K 792 8212AAC - DACIA LOGAN (LS_) 1.5 dCi (LS0W) 09.2007/12.2011 63KW 86CV 1461CC K9K 796 8212AAJ 8212AAY</p> <p>245-44/63mm 210-80-63-55mm</p>		<p>R224078 NO. 1655600QAM - 8200331958</p> <p>TUBO ADMISSÃO FILTRO DE AR</p> <p>DACIA LOGAN (LS_) 1.5 dCi (LS04) 05.2010/12.2012 55KW 75CV 1461CC K9K 892 8212ABQ - DACIA LOGAN (LS_) 1.5 dCi (LS04) desde 05.2010 65KW 88CV 1461CC K9K 892 8212ABP - DACIA LOGAN (LS_) 1.5 dCi (LS0J, LS0Y) desde 09.2005 48KW 65CV 1461CC K9K 790 - DACIA LOGAN (LS_) 1.5 dCi (LS0K) 01.2006/12.2012 50KW 68CV 1461CC K9K 792 8212AAC - DACIA LOGAN (LS_) 1.5 dCi (LS0W) 09.2007/12.2011 63KW 86CV 1461CC K9K 796 8212AAJ 8212AAY</p> <p>260x40x61mm 45x140x113x71mm ch-d22x33mm</p>
	<p>R224548 NO. 8200469423 - 8200598010</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA LOGAN (LS_) 1.5 dCi (LS0K) 01.2006/12.2012 50KW 68CV 1461CC K9K 792 8212AAC - DACIA LOGAN (LS_) 1.5 dCi (LS0W) 09.2007/12.2011 63KW 86CV 1461CC K9K 796 8212AAJ 8212AAY</p> <p>B710-48/57mm 140-99-84-190-160-72-164mm</p>		<p>R224548 NO. 8200469423 - 8200598010</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA LOGAN EXPRESS (FS_) 1.5 dCi (FS0K) desde 03.2009 50KW 68CV 1461CC K9K 792 8212AAS - DACIA LOGAN EXPRESS (FS_) 1.5 dCi (FS0W) desde 03.2009 63KW 86CV 1461CC K9K 796 8212AAT</p> <p>B710-48/57mm 140-99-84-190-160-72-164mm</p>
	<p>R224548 NO. 8200469423 - 8200598010</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA LOGAN MCV (KS_) 1.5 dCi (KS0K) desde 02.2007 50KW 68CV 1461CC K9K 792 8212AAF - DACIA LOGAN MCV (KS_) 1.5 dCi (KS0W) 09.2007/12.2012 63KW 86CV 1461CC K9K 796 8212AAI</p> <p>B710-48/57mm 140-99-84-190-160-72-164mm</p>		<p>R224548 NO. 8200469423 - 8200598010</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA LOGAN Pick-up (US_) 1.5 dCi (US0K) desde 03.2008 50KW 68CV 1461CC K9K 792 8212AAS - DACIA LOGAN Pick-up (US_) 1.5 dCi (US0W) desde 03.2008 63KW 86CV 1461CC K9K 796 8212AAT</p> <p>B710-48/57mm 140-99-84-190-160-72-164mm</p>
	<p>R224723 NO. 1446000Q1D - 144600835R - 144601524R - 144602760R - 144606171R - 144606189R - 144606515R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA LOGAN MCV II 1.5 dCi desde 02.2013 55KW 75CV 1461CC K9K 626 K9K 612 8212ABO - DACIA LOGAN MCV II 1.5 dCi desde 02.2013 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF</p> <p>B115-49/52mm</p>		<p>R224728 NO. 8200240894 - 8200384940</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA LOGAN (LS_) 1.5 dCi (LS0J, LS0Y) desde 09.2005 48KW 65CV 1461CC K9K 790 - DACIA LOGAN (LS_) 1.5 dCi (LS0K) 01.2006/12.2012 50KW 68CV 1461CC K9K 792 8212AAC - DACIA LOGAN (LS_) 1.5 dCi (LS0W) 09.2007/12.2011 63KW 86CV 1461CC K9K 796 8212AAJ 8212AAY</p> <p>B540-46/49mm 100-175-170-140-61mm</p>
	<p>R224728 NO. 8200240894 - 8200384940</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA LOGAN EXPRESS (FS_) 1.5 dCi (FS0K) desde 03.2009 50KW 68CV 1461CC K9K 792 8212AAS - DACIA LOGAN EXPRESS (FS_) 1.5 dCi (FS0W) desde 03.2009 63KW 86CV 1461CC K9K 796 8212AAT</p> <p>B540-46/49mm 100-175-170-140-61mm</p>		<p>R224728 NO. 8200240894 - 8200384940</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>RENAULT LOGAN MCV (KS_) 1.5 dCi (KS04) 05.2010/06.2013 55KW 75CV 1461CC K9K 892 8212ABO - RENAULT LOGAN MCV (KS_) 1.5 dCi (KS04) desde 05.2010 65KW 88CV 1461CC K9K 892 8212ABM - RENAULT LOGAN MCV (KS_) 1.5 dCi (KS0K) desde 02.2007 50KW 68CV 1461CC K9K 792 8212AAF - RENAULT LOGAN MCV (KS_) 1.5 dCi (KS0W) 09.2007/12.2012 63KW 86CV 1461CC K9K 796 8212AAI</p> <p>B540-46/49mm 100-175-170-140-61mm</p>
	<p>R224729 NO. 8200240894 - 8200384940</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA LOGAN (LS_) 1.5 dCi (LS0J, LS0Y) desde 09.2005 48KW 65CV 1461CC K9K 790 - DACIA LOGAN (LS_) 1.5 dCi (LS0K) 01.2006/12.2012 50KW 68CV 1461CC K9K 792 8212AAC - DACIA LOGAN (LS_) 1.5 dCi (LS0W) 09.2007/12.2011 63KW 86CV 1461CC K9K 796 8212AAJ 8212AAY</p> <p>B70-36/36mm 70mm</p>		<p>R224729 NO. 8200240894 - 8200384940</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA LOGAN EXPRESS (FS_) 1.5 dCi (FS0K) desde 03.2009 50KW 68CV 1461CC K9K 792 8212AAS - DACIA LOGAN EXPRESS (FS_) 1.5 dCi (FS0W) desde 03.2009 63KW 86CV 1461CC K9K 796 8212AAT</p> <p>B70-36/36mm 70mm</p>
	<p>R224729 NO. 8200240894 - 8200384940</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA LOGAN MCV (KS_) 1.5 dCi (KS04) 05.2010/06.2013 55KW 75CV 1461CC K9K 892 8212ABO - DACIA LOGAN MCV (KS_) 1.5 dCi (KS04) desde 05.2010 65KW 88CV 1461CC K9K 892 8212ABM - DACIA LOGAN MCV (KS_) 1.5 dCi (KS0K) desde 02.2007 50KW 68CV 1461CC K9K 792 8212AAF - DACIA LOGAN MCV (KS_) 1.5 dCi (KS0W) 09.2007/12.2012 63KW 86CV 1461CC K9K 796 8212AAI</p> <p>B70-36/36mm 70mm</p>		<p>R224730 NO. 8200240894 - 8200384940</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA LOGAN (LS_) 1.5 dCi (LS0J, LS0Y) desde 09.2005 48KW 65CV 1461CC K9K 790 - DACIA LOGAN (LS_) 1.5 dCi (LS0K) 01.2006/12.2012 50KW 68CV 1461CC K9K 792 8212AAC - DACIA LOGAN (LS_) 1.5 dCi (LS0W) 09.2007/12.2011 63KW 86CV 1461CC K9K 796 8212AAJ 8212AAY</p> <p>B551-48/48mm 100-170-170-125-48mm</p>

	<p>R224730 NO. 8200240894 - 8200384940</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA LOGAN EXPRESS (FS_) 1.5 dCi (FS0K) desde 03.2009 50KW 68CV 1461CC K9KCV 792CC 8212AAS - DACIA LOGAN EXPRESS (FS_) 1.5 dCi (FS0W) desde 03.2009 63KW 86CV 1461CC K9K 796 8212AAT</p> <p>B551-48/48mm 100-170-170-125-48mm</p>		<p>R224730 NO. 8200240894 - 8200384940</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA LOGAN MCV (KS_) 1.5 dCi (KS04) 05.2010/06.2013 55KW 75CV 1461CC K9K 892 8212ABO - DACIA LOGAN MCV (KS_) 1.5 dCi (KS04) desde 05.2010 65KW 88CV 1461CC K9K 892 8212ABM - DACIA LOGAN MCV (KS_) 1.5 dCi (KS0K) desde 02.2007 50KW 68CV 1461CC K9K 792 8212AAF - DACIA LOGAN MCV (KS_) 1.5 dCi (KS0W) 09.2007/12.2012 63KW 86CV 1461CC K9K 796 8212AAI</p> <p>B551-48/48mm 100-170-170-125-48mm</p>
	<p>R224759 NO. 144604599R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA LOGAN II 1.5 dCi desde 10.2012 66KW 90CV 1461CC K9K 612 K9K 626 8212ADA - DACIA LOGAN II 1.5 dCi / Blue dCi 75 desde 10.2012 55KW 75CV 1461CC K9K 872 K9K 612 K9K 626 8212ABQ - DACIA LOGAN MCV II 1.5 dCi desde 02.2013 55KW 75CV 1461CC K9K 626 K9K 612 8212ABO - DACIA LOGAN MCV II 1.5 dCi desde 02.2013 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF</p> <p>B650-50/52mm 56-92-108-156-185-77-46-45mm</p>		<p>R224764 NO. 144606189R - 144600835R - 144601524R - 144602760R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA LOGAN MCV II 1.5 dCi desde 02.2013 55KW 75CV 1461CC K9K 626 K9K 612 8212ABO - DACIA LOGAN MCV II 1.5 dCi desde 02.2013 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF</p> <p>B270-46/47mm 86-89-78mm</p>
	<p>R224819 NO. 1412000QJ - 1412000Q1E - 1412000Q1G - 223211229R - 223211568R - 223211824R - 223214402R - 820091250R</p> <p>TUBO VALVULA REGULADOR DE VELOCIDADE</p> <p>DACIA LOGAN (LS_) 1.5 dCi (LS0J, LS0Y) desde 09.2005 48KW 65CV 1461CC K9K 790 - DACIA LOGAN (LS_) 1.5 dCi (LS0K) 01.2006/12.2012 50KW 68CV 1461CC K9K 792 8212AAC - DACIA LOGAN EXPRESS (FS_) 1.5 dCi (FS0K) desde 03.2009 50KW 68CV 1461CC K9K 792 8212AAS - DACIA LOGAN MCV (KS_) 1.5 dCi (KS0K) desde 02.2007 50KW 68CV 1461CC K9K 792 8212AAF - DACIA LOGAN Pick-up (US_) 1.5 dCi (US0K) desde 03.2008 50KW ...</p> <p>B67-6/6mm</p>		<p>R230055 NO.</p> <p>TUBO ADMISSÃO FILTRO DE AR</p> <p>DACIA LOGAN MCV II 1.5 dCi desde 02.2013 55KW 75CV 1461CC K9K 626 K9K 612 8212ABO - DACIA LOGAN MCV II 1.5 dCi desde 02.2013 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF - DACIA LOGAN MCV II TcE 90 (K8M1, K8MA, K8AC) desde 02.2013 66KW 90CV 898CC H4B 408 H4B 400 H4B 412 8212ADD - DACIA LOGAN MCV II TcE 90 LPG desde 09.2015 66KW 90CV 898CC H4B 410 H4B 405 8212ADZ</p> <p>B505-62/82x41mm 100-190-158-56mm</p>
	<p>R230055 NO.</p> <p>TUBO ADMISSÃO FILTRO DE AR</p> <p>DACIA SANDERO II 1.5 Blue dCi 95 (B8JL) desde 08.2018 70KW 95CV 1461CC K9K 872 8212AES - DACIA SANDERO II 1.5 dCi desde 10.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ADB - DACIA SANDERO II 1.5 dCi 75 / Blue dCi 75 (B8JW, B8M4, B8AH, B8M7, B8M6) desde 10.2012 55KW 75CV 1461CC K9K 872 K9K 626 K9K 612 K9K 838 8212ABN - DACIA SANDERO II TcE 90 (B8M1, B8MA, B8AC) desde 10.2012 66KW 90CV 898CC H4B 400 H4...</p> <p>B505-62/82x41mm 100-190-158-56mm</p>		<p>R8210 NO. 223211229R - 223214402R</p> <p>TUBO DA VALVULA DO REGULADOR DE VELOCIDADE</p> <p>DACIA LOGAN (LS_) 1.5 dCi (LS0J, LS0Y) desde 09.2005 48KW 65CV 1461CC K9K 790 - DACIA LOGAN (LS_) 1.5 dCi (LS0K) 01.2006/12.2012 50KW 68CV 1461CC K9K 792 8212AAC - DACIA LOGAN EXPRESS (FS_) 1.5 dCi (FS0K) desde 03.2009 50KW 68CV 1461CC K9K 792 8212AAS - DACIA LOGAN MCV (KS_) 1.5 dCi (KS0K) desde 02.2007 50KW 68CV 1461CC K9K 792 8212AAF - DACIA LOGAN Pick-up (US_) 1.5 dCi (US0K) desde 03.2008 50KW ...</p> <p>222x82x16mm 1f-d6mm 1f-d11mm</p>
	<p>R8219 NO. 1446000Q1H - 144600492R - 144605243R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA LOGAN II TcE 90 (L8MA, L8M1, L8AC) desde 10.2012 66KW 90CV 898CC H4B 408 H4B 400 8212ACY - DACIA LOGAN II TcE 90 LPG desde 09.2015 66KW 90CV 898CC H4B 405 H4B 410 8212ADX</p> <p>B560-31/39mm 110-53-230-105-58mm</p>		<p>R8219 NO. 1446000Q1H - 144600492R - 144605243R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA LOGAN MCV II TcE 90 (K8M1, K8MA, K8AC) desde 02.2013 66KW 90CV 898CC H4B 408 H4B 400 8212ADD - DACIA LOGAN MCV II TcE 90 LPG desde 09.2015 66KW 90CV 898CC H4B 410 H4B 405 8212ADZ</p> <p>B560-31/39mm 110-53-230-105-58mm</p>
	<p>RFL19610 NO. 8200140155 - 8200231833 - 8200714635</p> <p>TUBO FLEXIVEL DO ÓLEO DO TURBO</p> <p>DACIA LOGAN II 1.5 Blue dCi 95 (L8JL) desde 05.2018 70KW 95CV 1461CC K9K 872 8212AER - DACIA LOGAN II 1.5 dCi desde 10.2012 66KW 90CV 1461CC K9K 612 K9K 626 8212ADA - DACIA LOGAN II 1.5 dCi desde 01.2013 63KW 84CV 1461CC K9K 838 K9K 830 - DACIA LOGAN II 1.5 dCi / Blue dCi 75 desde 10.2012 55KW 75CV 1461CC K9K 872 K9K 612 K9K 626 8212ABQ</p> <p>B222-14/14mm 129x67x30mm 1f-d6mm 1f-6x8mm</p>		<p>RFL19610 NO. 8200140155 - 8200231833 - 8200714635</p> <p>TUBO FLEXIVEL DO ÓLEO DO TURBO</p> <p>DACIA LOGAN MCV II 1.5 Blue dCi 95 (K8JL) desde 10.2018 70KW 95CV 1461CC K9K 872 8212AEP - DACIA LOGAN MCV II 1.5 dCi desde 02.2013 55KW 75CV 1461CC K9K 626 K9K 612 8212ABO - DACIA LOGAN MCV II 1.5 dCi desde 02.2013 63KW 84CV 1461CC K9K 838 K9K 830 - DACIA LOGAN MCV II 1.5 dCi desde 02.2013 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF</p> <p>B222-14/14mm 129x67x30mm 1f-d6mm 1f-6x8mm</p>
	<p>RFL61319 NO. 8200310122 - 8200376094 - 8200575489 - 8200714635</p> <p>TUBO FLEXIVEL DO OLEO</p> <p>DACIA LOGAN II 1.5 Blue dCi 95 (L8JL) desde 05.2018 70KW 95CV 1461CC K9K 872 8212AER - DACIA LOGAN II 1.5 dCi desde 10.2012 66KW 90CV 1461CC K9K 612 K9K 626 8212ADA - DACIA LOGAN II 1.5 dCi desde 01.2013 63KW 84CV 1461CC K9K 838 K9K 830 - DACIA LOGAN II 1.5 dCi / Blue dCi 75 desde 10.2012 55KW 75CV 1461CC K9K 872 K9K 612 K9K 626 8212ABQ</p> <p>B236-11/12mm 1f-d6mm 71x96x51x31mm</p>		<p>RFL61319 NO. 8200310122 - 8200376094 - 8200575489 - 8200714635</p> <p>TUBO FLEXIVEL DO OLEO</p> <p>DACIA LOGAN MCV II 1.5 Blue dCi 95 (K8JL) desde 10.2018 70KW 95CV 1461CC K9K 872 8212AEP - DACIA LOGAN MCV II 1.5 dCi desde 02.2013 55KW 75CV 1461CC K9K 626 K9K 612 8212ABO - DACIA LOGAN MCV II 1.5 dCi desde 02.2013 63KW 84CV 1461CC K9K 838 K9K 830 - DACIA LOGAN MCV II 1.5 dCi desde 02.2013 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF</p> <p>B236-11/12mm 1f-d6mm 71x96x51x31mm</p>
	<p>RT08443 NO. 6001547816 - 6001547819 - 6001551098</p> <p>TUBO DE TRAVÃO FRENTE LH-RH</p> <p>DACIA LOGAN (LS_) 1.4 (LSOA, LSOC, LSOE, LSPG) 09.2004/»»» 55KW 75CV 1390CC - DACIA LOGAN (LS_) 1.4 MPI LPG (LS0C) 02.2006/»»» 55KW 75CV 1390CC - DACIA LOGAN (LS_) 1.6 (LSOB, LSOD, LSOF, LSOH) 09.2004/»»» 64KW 87CV 1598CC - DACIA LOGAN (LS_) 1.6 16V (LS09, LS0L, LS0M, LS0P, LS0V, LS18, LS1S, LS1V, ... 02.2006/»»» 77KW 105CV 1598CC - DACIA LOGAN (LS_) 1.5 dCi (LS0J, LS0Y) 09.2005/»»» 48KW 65CV ...</p> <p>330mm FZ - MC11</p>		<p>S1060 NO. 7700762574 - 7704000681</p> <p>SILENT-BLOC DO BRAÇO INFERIOR DA SUSPENSÃO FRENTE</p> <p>DACIA SOLENZA (B41_) 1.4 (B41A, B41B, B41C) 02.2003/10.2005 55KW 75CV 1390CC E7J 262 - DACIA SOLENZA (B41_) 1.9 D (B41E, B41F, B41G) desde 02.2003 46KW 63CV 1870CC F8Q 636</p> <p>d32x46mm c36mm 1f-d12mm</p>

	<p>UMV25619 NO. 7700430135 - 8200208090 - 8200236191 - 8200822162</p> <p>MANETE PUNHO TOPO ALAVANCA MUDANÇAS 5 VELOCIDADES F11/29MM</p> <p>DACIA LOGAN (LS_) 1.4 (LSOA, LSOC, LSOE, LSOG) 09.2004/>>> 55KW 75CV 1390CC - DACIA LOGAN (LS_) 1.6 (LSOB, LSOD, LSOE, LSOH) 09.2004/>>> 64KW 87CV 1598CC - DACIA LOGAN MCV (KS_) 1.4 02.2007/>>> 55KW 75CV 1390CC - DACIA LOGAN MCV (KS_) 1.6 02.2007/>>> 64KW 87CV 1598CC - DACIA LOGAN MCV (KS_) 1.6 16V (KS0L, KS0M, KS0P, KS1S) 02.2007/>>> 77KW 105CV 1598CC - DACIA LOGAN MCV (KS_) 1.5 dCi (KS0K) ...</p> <p>d49x58mm 1f-d29/11mm</p>		<p>UMV25620 NO. 6001543466 - 8200059572 - 8200059575 - 8200059578 - 8200079113 - 8200276921 - 8200276923 - 820037994...</p> <p>MANETE PUNHO TOPO ALAVANCA MUDANÇAS 5 VELOCIDADES F19MM</p> <p>DACIA LOGAN EXPRESS (FS_) 1.4 desde 03.2009 55KW 75CV 1390CC K7J 710 8212AAR - DACIA LOGAN EXPRESS (FS_) 1.5 dCi desde 05.2010 55KW 75CV 1461CC K9K 892 8212ABW - DACIA LOGAN EXPRESS (FS_) 1.5 dCi desde 05.2010 65KW 88CV 1461CC K9K 892 8212ABX - DACIA LOGAN EXPRESS (FS_) 1.5 dCi (FS0K) desde 03.2009 50KW 68CV 1461CC K9K 792 8212AAS - DACIA LOGAN EXPRESS (FS_) 1.5 dCi (FS0W) desde 03.2009 63KW 8...</p> <p>d49x104mm 1f-d19mm</p>
	<p>UMV25620 NO. 6001543466 - 8200059572 - 8200059575 - 8200059578 - 8200079113 - 8200276921 - 8200276923 - 820037994...</p> <p>MANETE PUNHO TOPO ALAVANCA MUDANÇAS 5 VELOCIDADES F19MM</p> <p>DACIA LOGAN II 1.2 desde 10.2012 55KW 75CV 1149CC D4F 732 8212AAV - DACIA LOGAN II 1.2 desde 05.2015 54KW 73CV 1149CC 8212ADS - DACIA LOGAN II 1.2 LPG desde 10.2012 55KW 75CV 1149CC D4F 734 8212ACR - DACIA LOGAN II 1.5 dCi desde 10.2012 66KW 90CV 1461CC K9K 612 K9K 626 8212ADA - DACIA LOGAN II 1.5 dCi desde 01.2013 63KW 84CV 1461CC K9K 838 K9K 830 - DACIA LOGAN II 1.5 dCi / Blue dCi 75 desde 10.20...</p> <p>d49x104mm 1f-d19mm</p>		<p>UMV25641 NO. 8200059575 - 8200059578 - 8200079112 - 8200079113 - 8200379945 - 8200379950</p> <p>MANETE PUNHO TOPO ALAVANCA MUDANÇAS 5 VELOCIDADES F19MM</p> <p>DACIA LOGAN II 1.2 desde 10.2012 55KW 75CV 1149CC D4F 732 8212AAV - DACIA LOGAN II 1.2 desde 05.2015 54KW 73CV 1149CC 8212ADS - DACIA LOGAN II 1.2 LPG desde 10.2012 55KW 75CV 1149CC D4F 734 8212ACR - DACIA LOGAN II 1.5 dCi desde 10.2012 66KW 90CV 1461CC K9K 612 K9K 626 8212ADA - DACIA LOGAN II 1.5 dCi desde 01.2013 63KW 84CV 1461CC K9K 838 K9K 830 - DACIA LOGAN II 1.5 dCi / Blue dCi 75 desde 10.20...</p> <p>49x108x57mm 1f-d19mm</p>
	<p>UMV25641 NO. 8200059575 - 8200059578 - 8200079112 - 8200079113 - 8200379945 - 8200379950</p> <p>MANETE PUNHO TOPO ALAVANCA MUDANÇAS 5 VELOCIDADES F19MM</p> <p>DACIA LOGAN MCV II 1.2 desde 02.2013 55KW 75CV 1149CC D4F 732 8212ADE - DACIA LOGAN MCV II 1.2 desde 05.2015 54KW 73CV 1149CC D4F 732 8212ADR 8212ADU - DACIA LOGAN MCV II 1.2 LPG desde 02.2013 53KW 72CV 1149CC D4F 734 - DACIA LOGAN MCV II 1.2 LPG desde 02.2013 55KW 75CV 1149CC D4F 734 8212ADF - DACIA LOGAN MCV II 1.5 dCi desde 02.2013 55KW 75CV 1461CC K9K 626 K9K 612 8212ABO - DACIA LOGAN MCV II 1...</p> <p>49x108x57mm 1f-d19mm</p>		<p>URL36540 NO. 33140-33G01 - 33140-33G02 - 33142-33G10 - 8200651172</p> <p>ROLAMENTO DO APOIO SUPORTE AMORTECEDOR FRENTE COMPEMETA A1479-C (GASTA 2 UNIDADES)</p> <p>DACIA LOGAN (LS_) 1.2 16V (LS1N, LS02, BS02) desde 02.2006 55KW 75CV 1149 D4F 732 D4F 734 8212AAV - DACIA LOGAN (LS_) 1.2 16V LPG desde 02.2006 55KW 75CV 1149CC D4F 734 8212ACR - DACIA LOGAN (LS_) 1.4 (LSOA, LSOC, LSOE, LSOG) desde 09.2004 55KW 75CV 1390CC K7J 710 K7J 714 8212001 8212AAA 8212ABB - DACIA LOGAN (LS_) 1.4 MPI LPG (LS0C) 02.2006/12.2012 55KW 75CV 1390CC K7J 714 K7J 710 8212AAW - DACIA...</p> <p>d56x9mm 1f-d16mm</p>
	<p>URTE6017 NO. 144652865R</p> <p>RETENTOR TUBO AR SOBREALIMENTAÇÃO D45,5X49X4,8MM</p> <p>DACIA LOGAN II TcE 90 desde 10.2012 66KW 90CV 898CC H4B 408 H4B 400 8212ACY - DACIA LOGAN II TcE 90 LPG desde 09.2015 66KW 90CV 898CC H4B 405 H4B 410 8212ADX</p> <p>d48x5mm 1f-d45mm</p>		<p>URTE6017 NO. 144652865R</p> <p>RETENTOR TUBO AR SOBREALIMENTAÇÃO D45,5X49X4,8MM</p> <p>DACIA LOGAN MCV II TcE 90 (K8M1) desde 02.2013 66KW 90CV 898CC H4B 408 H4B 400 8212ADD - DACIA LOGAN MCV II TcE 90 LPG desde 09.2015 66KW 90CV 898CC H4B 410 H4B 405 8212ADZ</p> <p>d48x5mm 1f-d45mm</p>
	<p>URTE6018 NO. 140797120R</p> <p>RETENTOR TUBO AR SOBREALIMENTAÇÃO</p> <p>DACIA LOGAN II 1.5 dCi desde 10.2012 66KW 90CV 1461CC K9K 612 K9K 626 8212ADA - DACIA LOGAN II 1.5 dCi desde 01.2013 63KW 84CV 1461CC K9K 838 K9K 830 - DACIA LOGAN II 1.5 dCi / Blue dCi 75 desde 10.2012 55KW 75CV 1461CC K9K 872 K9K 612 K9K 626 8212ABQ</p> <p>d46x5mm d42mm</p>		<p>URTE6018 NO. 140797120R</p> <p>RETENTOR TUBO AR SOBREALIMENTAÇÃO</p> <p>DACIA LOGAN MCV II 1.5 dCi desde 02.2013 55KW 75CV 1461CC K9K 626 K9K 612 8212ABO - DACIA LOGAN MCV II 1.5 dCi desde 02.2013 66KW 90CV 1461CC K9K 626 K9K 612 8212ACF</p> <p>d46x5mm d42mm</p>
	<p>UTR0800 NO.</p> <p>TAMPÃO RESERVATÓRIO LIQUIDO REFRIGERAÇÃO</p> <p>DACIA LOGAN MCV (KS_) 1.4 desde 02.2007 55KW 75CV 1390CC K7J 710 8212AAH</p> <p>d62x25mm 1f-d53x14mm</p>		<p>UTR0803 NO. 1H0121321A - 1H0121321B - 1H0121321C - 357121321 - 357121321A - 357121321C</p> <p>TAMPÃO RESERVATÓRIO LIQUIDO REFRIGERAÇÃO</p> <p>DACIA LOGAN MCV (KS_) 1.5 dCi (KS0K) desde 02.2007 50KW 68CV 1461CC K9K 792 8212AAF - DACIA LOGAN MCV (KS_) 1.6 (KS0B, KS0D, KS0F) 02.2007/06.2013 64KW 87CV 1598CC K7M 710 K7M 718 8212AAG - DACIA LOGAN MCV (KS_) 1.6 16V (KS0L, KS0M, KS0P, KS1S) desde 02.2007 77KW 105CV 1598CC K4M 697 K4M 696 K4M 690 8212AAE</p> <p>d79x36mm d53x20mm</p>
	<p>UTR0817 NO. 21430-AX300 - 21430-AX600 - 21430AX30A - 4408066 - 7700805131 - 8200048024 - 91166192</p> <p>TAMPÃO RESERVATÓRIO LIQUIDO REFRIGERAÇÃO</p> <p>DACIA LOGAN (LS_) 1.2 16V (LS1N, LS02, BS02) desde 02.2006 55KW 75CV 1149CC D4F 732 D4F 734 8212AAV - DACIA LOGAN (LS_) 1.2 16V LPG desde 02.2006 55KW 75CV 1149CC D4F 734 8212ACR - DACIA LOGAN (LS_) 1.4 (LSOA, LSOC, LSOE, LSOG) desde 09.2004 55KW 75CV 1390CC K7J 710 K7J 714 8212001 8212AAA 8212ABB - DACIA LOGAN (LS_) 1.4 MPI LPG (LS0C) 02.2006/12.2012 55KW 75CV 1390CC K7J 714 K7J 710 8212AAW - DAC...</p> <p>53x36mm 1f-d46x18mm</p>		<p>UTR0839 NO. 1H0121321A - 1H0121321B - 1H0121321C - 357121321 - 357121321A - 357121321C</p> <p>TAMPÃO RESERVATÓRIO LIQUIDO REFRIGERAÇÃO</p> <p>DACIA LOGAN MCV (KS_) 1.5 dCi (KS0K) desde 02.2007 50KW 68CV 1461CC K9K 792 8212AAF - DACIA LOGAN MCV (KS_) 1.6 (KS0B, KS0D, KS0F) 02.2007/06.2013 64KW 87CV 1598CC K7M 710 K7M 718 8212AAG - DACIA LOGAN MCV (KS_) 1.6 16V (KS0L, KS0M, KS0P, KS1S) desde 02.2007 77KW 105CV 1598CC K4M 697 K4M 696 K4M 690 8212AAE</p> <p>d80x38mm d58x20mm</p>
	<p>UTR0851 NO. 1357390 - 30811055 - 30864125 - 3463536 - 3463537 - 434374 - 9445462</p> <p>TAMPÃO RESERVATÓRIO LIQUIDO REFRIGERAÇÃO</p> <p>DACIA LOGAN (LS_) 1.5 dCi (LS0K) 01.2006/12.2012 50KW 68CV 1461CC K9K 792 8212AAC</p> <p>d76x19mm 1f-d45x11mm</p>		<p>UTR0859 NO. 1650630 - 94539597 - 96293957 - 96312510 - 96351578 - 96420303 - 96536649</p> <p>TAMPÃO RESERVATÓRIO LIQUIDO REFRIGERAÇÃO</p> <p>DACIA LOGAN MCV (KS_) 1.4 desde 02.2007 55KW 75CV 1390CC K7J 710 8212AAH</p> <p>d63x23mm 1f-d53x11mm</p>

	<p>UTR1403 NO. 7701470950 - 7701471585</p> <p>TAMPÃO DEPÓSITO COMBUSTIVEL</p> <p>DACIA LOGAN (LS_) 1.2 16V (LS1N, LS02, BS02) desde 02.2006 55KW 75CV 1149CC D4F 732 D4F 734 8212AAV - DACIA LOGAN (LS_) 1.2 16V LPG desde 02.2006 55KW 75CV 1149CC D4F 734 8212ACR - DACIA LOGAN (LS_) 1.4 (LSOA, LSOC, LSOE, LSOG) desde 09.2004 55KW 75CV 1390CC K7J 710 K7J 714 8212001 8212AAA 8212ABB - DACIA LOGAN (LS_) 1.4 MPI LPG (LS0C) 02.2006/12.2012 55KW 75CV 1390CC K7J 714 K7J 710 8212AAW - DAC...</p> <p>d73x67mm d37mm</p>		<p>W5000 NO. 1230300Q1N - 6001545312</p> <p>POLIE CAMBOTA (6 PISTAS)</p> <p>DACIA SOLENZA (B41_) : 1.9 D (B41E, B41F, B41G) 02.2003/»»» 46KW 63CV 1870CC</p> <p>d132mm d12.6mm</p>
	<p>W5106 NO. 8200477938</p> <p>POLIE DA CAMBOTA (6 PISTAS)</p> <p>DACIA LOGAN (LS_) : 1.6 16V (LS09, LS0L, LS0M, LS0P, LS0V, LS18, LS1S, LS1V,... 02.2006/»»» 77KW 105CV 1598CC - DACIA LOGAN (LS_) : 1.5 dCi (LS0J, LS0Y) 09.2005/»»» 48KW 65CV 1461CC - DACIA LOGAN (LS_) : 1.5 dCi (LS0K) 01.2006/»»» 50KW 68CV 1461CC - DACIA LOGAN (LS_) : 1.5 dCi (LS04) 05.2010/»»» 55KW 75CV 1461CC - DACIA LOGAN (LS_) : 1.5 dCi (LS0W) 09.2007/»»» 63KW 86CV 1461CC - DACIA LOGAN (LS_) : 1.5 ...</p> <p>d155/151mm d26mm</p>		<p>W5108 NO. 12201-00QAW - 12303-00QJ - 12303-0001H - 12303-00Q2K - 12303-00QAY - 12303-00QBA - 12303-BN700</p> <p>POLIE DA CAMBOTA (5 PISTAS)</p> <p>RENAULT LOGAN (LS_) : 1.6 16V (LS09, LS0L, LS0M, LS0P, LS0V, LS18, LS1S, LS1V,... 02.2006/»»» 77KW 105CV 1598CC - RENAULT LOGAN (LS_) : 1.6 16V Flexifuel 07.2010/»»» 77KW 105CV 1598CC - RENAULT LOGAN (LS_) : 1.5 dCi (LS0J, LS0Y) 09.2005/»»» 48KW 65CV 1461CC - RENAULT LOGAN (LS_) : 1.5 dCi (LS0K) 01.2006/»»» 50KW 68CV 1461CC - RENAULT LOGAN (LS_) : 1.5 dCi (LS04) 05.2010/»»» 55KW 75CV 1461CC - RENAULT L...</p> <p>d153.4mm 1f-d26mm</p>
	<p>W5137 NO. 7700105788 - 7700107122 - 8200044050 - 8200352613 - 8200395313 - 8200544135 - 8200552236 - 820055764...</p> <p>POLIE DA CAMBOTA 6 PISTAS</p> <p>DACIA LOGAN (LS_) : 1.6 16V (LS09, LS0L, LS0M, LS0P, LS0V, LS18, LS1S, LS1V,... 02.2006/»»» 77KW 105CV 1598CC - DACIA LOGAN MCV (KS_) : 1.6 16V (KS0L, KS0M, KS0P, KS1S) 02.2007/»»» 77KW 105CV 1598CC - DACIA LOGAN MCV (KS_) : 1.6 16V Hi-Flex 11.2009/»»» 77KW 105CV 1598CC</p> <p>d155mm d26mm</p>		<p>W5168 NO. 7700273916 - 8200847840</p> <p>POLIE DA CAMBOTA (6 PISTAS)</p> <p>DACIA LOGAN (LS_) : 1.4 (LSOA, LSOC, LSOE, LSOG) 09.2004/»»» 55KW 75CV 1390CC - DACIA LOGAN (LS_) : 1.4 MPI LPG (LS0C) 02.2006/»»» 55KW 75CV 1390CC - DACIA LOGAN (LS_) : 1.6 MPI 85 05.2010/»»» 62KW 84CV 1598CC - DACIA LOGAN (LS_) : 1.6 Bifuel 05.2010/»»» 62KW 84CV 1598CC - DACIA LOGAN (LS_) : 1.6 (LS0B, LS0D, LS0F, LS0H) 09.2004/»»» 64KW 87CV 1598CC</p> <p>d133mm 1f-d13/25mm</p>
	<p>W5216 NO. 8200758088</p> <p>POLIE DA CAMBOTA RODA DENTADA (19 DENTES)</p> <p>DACIA LOGAN (LS_) 1.6 16V (LS09, LS0L, LS0M, LS0P, LS0V, LS18, LS1S, LS1V,... desde 02.2006 77KW 105CV 1598CC K4M 694 K4M 697 K4M 698 K4M 690 K4M 696 8212AAD 8212ACD - DACIA LOGAN (LS_) 1.6 16V Flexifuel desde 07.2010 77KW 105CV 1598CC K4M 696 8212ACJ 8212ACD - DACIA LOGAN MCV (KS_) 1.6 16V (KS0L, KS0M, KS0P, KS1S) desde 02.2007 77KW 105CV 1598CC K4M 697 K4M 696 K4M 690 8212AAE - DACIA LOGAN MCV (...)</p> <p>d56x32mm 1f-26mm</p>		<p>W5216 NO. 8200758088</p> <p>POLIE DA CAMBOTA RODA DENTADA (19 DENTES)</p> <p>DACIA LOGAN II 1.6 16V desde 01.2013 77KW 105CV 1598CC K4M 842</p> <p>d56x32mm 1f-26mm</p>
	<p>Y3239 NO. 8200473313 - 8200610460</p> <p>PARAFUSO PERNO RODA CHAVE 17 M12X1,50X50MM (BASE CONICA)</p> <p>RENAULT LOGAN (LS_) 1.2 16V (LS1N, LS02, BS02) desde 02.2006 55KW 75CV 1149CC D4F 732 D4F 734 8212AAV - RENAULT LOGAN (LS_) 1.2 16V LPG desde 02.2006 55KW 75CV 1149CC D4F 734 8212ACR - RENAULT LOGAN (LS_) 1.4 (LSOA, LSOC, LSOE, LSOG) desde 09.2004 55KW 75CV 1390CC K7J 710 K7J 714 8212001 8212AAA 8212ABB - RENAULT LOGAN (LS_) 1.5 dCi (LS04) 05.2010/12.2012 55KW 75CV 1461CC K9K 892 8212ABQ - RENAULT...</p> <p>c51mm (ch-17mm) M12x1x24mm</p>		<p>Y3239 NO. 8200473313 - 8200610460</p> <p>PARAFUSO PERNO RODA CHAVE 17 M12X1,50X50MM (BASE CONICA)</p> <p>RENAULT LOGAN EXPRESS (FS_) 1.4 desde 03.2009 55KW 75CV 1390CC K7J 710 8212AAR - RENAULT LOGAN EXPRESS (FS_) 1.5 dCi desde 05.2010 55KW 75CV 1461CC K9K 892 8212ABW - RENAULT LOGAN EXPRESS (FS_) 1.5 dCi desde 05.2010 65KW 88CV 1461CC K9K 892 8212ABX - RENAULT LOGAN EXPRESS (FS_) 1.5 dCi (FS0K) desde 03.2009 50KW 68CV 1461CC K9K 792 8212AAS - RENAULT LOGAN EXPRESS (FS_) 1.5 dCi (FS0W) desde 03.2009 ...</p> <p>c51mm (ch-17mm) M12x1x24mm</p>
	<p>Y3239 NO. 8200473313 - 8200610460</p> <p>PARAFUSO PERNO RODA CHAVE 17 M12X1,50X50MM (BASE CONICA)</p> <p>DACIA LOGAN MCV (KS_) 1.4 desde 02.2007 55KW 75CV 1390CC K7J 710 8212AAH - DACIA LOGAN MCV (KS_) 1.5 dCi (KS04) 05.2010/06.2013 55KW 75CV 1461CC K9K 892 8212ABO - DACIA LOGAN MCV (KS_) 1.5 dCi (KS04) desde 05.2010 65KW 88CV 1461CC K9K 892 8212ABM - DACIA LOGAN MCV (KS_) 1.5 dCi (KS0K) desde 02.2007 50KW 68CV 1461CC K9K 792 8212AAF - DACIA LOGAN MCV (KS_) 1.5 dCi (KS0W) 09.2007/12.2012 63KW 86CV 14...</p> <p>c51mm (ch-17mm) M12x1x24mm</p>		<p>Y3239 NO. 8200473313 - 8200610460</p> <p>PARAFUSO PERNO RODA CHAVE 17 M12X1,50X50MM (BASE CONICA)</p> <p>DACIA LOGAN Pick-up (US_) 1.4 desde 01.2009 55KW 75CV 1390CC K7J 710 8212AAR - DACIA LOGAN Pick-up (US_) 1.5 dCi desde 05.2010 55KW 75CV 1461CC K9K 892 8212ABW - DACIA LOGAN Pick-up (US_) 1.5 dCi desde 05.2010 65KW 88CV 1461CC K9K 892 8212ABX - DACIA LOGAN Pick-up (US_) 1.5 dCi (US0K) desde 03.2008 50KW 68CV 1461CC K9K 792 8212AAS - DACIA LOGAN Pick-up (US_) 1.5 dCi (US0W) desde 03.2008 63KW 8...</p> <p>c51mm (ch-17mm) M12x1x24mm</p>
	<p>Z57184 NO. 7703081056</p> <p>MOLAS FIXAÇÃO REV. CAVA RODA RENAULT/DACIA</p> <p>DACIA LOGAN (LS_) : 1.2 16V 02.2006/»»» 55KW 75CV 1149CC - DACIA LOGAN (LS_) : 1.2 16V LPG 02.2006/»»» 55KW 75CV 1149CC - DACIA LOGAN (LS_) : 1.4 (LSOA, LSOC, LSOE, LSOG) 09.2004/»»» 55KW 75CV 1390CC - DACIA LOGAN (LS_) : 1.4 MPI LPG (LS0C) 02.2006/»»» 55KW 75CV 1390CC - DACIA LOGAN (LS_) : 1.6 MPI 85 05.2010/»»» 62KW 84 1598CC - DACIA LOGAN (LS_) : 1.6 Bifuel 05.2010/»»» 84KW 1598CC - DACIA LOGAN (LS_...</p> <p>d30x14mm 1f-5x12mm</p>		<p>Z57184 NO. 7703081056</p> <p>MOLAS FIXAÇÃO REV. CAVA RODA RENAULT/DACIA</p> <p>DACIA LOGAN II: TcE 90 10.2012/»»» 66KW 90CV 898CC - DACIA LOGAN II: 1.0 ScE 75 01.2017/»»» 54KW 73CV 998CC - DACIA LOGAN II: 1.2 05.2015/»»» 54KW 73CV 1149CC - DACIA LOGAN II: 1.2 10.2012/»»» 55KW 75CV 1149CC - DACIA LOGAN II: 1.2 LPG 10.2012/»»» 55KW 75CV 1149CC - DACIA LOGAN II: 1.6 16V 01.2013/»»» 77KW 105CV 1598CC - DACIA LOGAN II: 1.5 dCi / Blue dCi 75 10.2012/»»» 55KW 75CV 1461CC - DACIA LO...</p> <p>d30x14mm 1f-5x12mm</p>
	<p>Z59106 NO. 8200909084</p> <p>MOLA DO PAINEL DAS PORTAS</p> <p>DACIA LOGAN (LS_) 1.2 16V (LS1N, LS02, BS02) desde 02.2006 55KW 75CV 1149CC D4F 732 D4F 734 8212AAV - DACIA LOGAN (LS_) 1.2 16V LPG desde 02.2006 55KW 75CV 1149CC D4F 734 8212ACR - DACIA LOGAN (LS_) 1.4 (LSOA, LSOC, LSOE, LSOG) desde 09.2004 55KW 75CV 1390CC K7J 710 K7J 714 8212001 8212AAA 8212ABB - DACIA LOGAN (LS_) 1.4 MPI LPG (LS0C) 02.2006/12.2012 55KW 75CV 1390CC K7J 714 K7J 710 8212AAW - DAC...</p> <p>F12mm T17.5mm L13mm H19mm S1-7mm</p>		<p>Z80633 NO. 7703081054 - 7703081127 - 7703081227 - 7703081237</p> <p>Mola de painel</p> <p>DACIA LOGAN (LS_) 1.2 16V (LS1N, LS02, BS02) desde 02.2006 55KW 75CV 1149CC D4F 732 D4F 734 8212AAV - DACIA LOGAN (LS_) 1.2 16V LPG desde 02.2006 55KW 75CV 1149CC D4F 734 8212ACR - DACIA LOGAN (LS_) 1.4 (LSOA, LSOC, LSOE, LSOG) desde 09.2004 55KW 75CV 1390CC K7J 710 K7J 714 8212001 8212AAA 8212ABB - DACIA LOGAN (LS_) 1.4 MPI LPG (LS0C) 02.2006/12.2012 55KW 75CV 1390CC K7J 714 K7J 710 8212AAW - DAC...</p> <p>d30x17mm 1p-d9.7-15mm</p>

	<p>A2043 NO. 8200105502 - 8200105503 - 8200105504 - 8200105505</p> <p>APOIO ESCAPE PARTE CENTRO</p> <p>DACIA SANDERO: 1.2 16V 11.2008/>>> 55KW 75CV 1149CC - DACIA SANDERO: 1.4 06.2008/>>> 55KW 75CV 1390CC - DACIA SANDERO: 1.6 06.2008/>>> 64KW 87CV 1598CC - DACIA SANDERO: 1.5 dCi 11.2008/>>> 50KW 68CV 1461CC - DACIA SANDERO: 1.5 dCi 11.2008/>>> 50KW 68CV 1461CC - DACIA SANDERO: 1.5 dCi 11.2008/>>> 63KW 86CV 1461CC</p> <p>47x50x29mm 2f-17x7mm</p>		<p>A2100 NO. 6001548160 - 8200014932 - 8200297939 - 8200358147</p> <p>APOIO DA CAIXA DE VELOCIDADES</p> <p>DACIA SANDERO: 1.4 06.2008/>>> 55KW 75CV 1390CC - DACIA SANDERO: 1.6 06.2008/>>> 64KW 87CV 1598CC - DACIA SANDERO: 1.5 dCi 11.2008/>>> 50KW 68CV 1461CC - DACIA SANDERO: 1.5 dCi 05.2010/>>> 55KW 75CV 1461CC - DACIA SANDERO: 1.5 dCi 11.2008/>>> 63KW 86CV 1461CC - DACIA SANDERO: 1.5 dCi 05.2010/>>> 65KW 88CV 1461CC</p> <p>152x72x57mm 1f-d11mm 2f-d17mm</p>
	<p>A2101 NO. 6001548160 - 8200014932 - 8200297939 - 8200358147 - 8200395661</p> <p>APOIO CAIXA VELOCIDADES</p> <p>DACIA SANDERO: 1.4 06.2008/>>> 55KW 75CV 1390CC - DACIA SANDERO: 1.6 06.2008/>>> 64KW 87CV 1598CC - DACIA SANDERO: 1.5 dCi 11.2008/>>> 50KW 68CV 1461CC - DACIA SANDERO: 1.5 dCi 05.2010/>>> 55KW 75CV 1461CC - DACIA SANDERO: 1.5 dCi 11.2008/>>> 63KW 86CV 1461CC - DACIA SANDERO: 1.5 dCi 05.2010/>>> 65KW 88CV 1461CC</p> <p>152x70x57mm 1f-d11mm 2f-d17mm</p>		<p>A2102 NO. 2f-d17mm 1f-d10mm 1f-d12mm 1f-10x1</p> <p>APOIO DO MOTOR FRENTE DIREITO</p> <p>DACIA SANDERO: 1.4 MPI LPG 01.2009/>>> 53KW 72CV 1390CC - DACIA SANDERO: 1.4 06.2008/>>> 55KW 75CV 1390CC - DACIA SANDERO: 1.6 MPI 85 05.2010/>>> 62KW 84CV 1598CC - DACIA SANDERO: 1.6 LPG 05.2010/10.2012 62KW 84CV 1598CC - DACIA SANDERO: 1.6 06.2008/>>> 64KW 87CV 1598CC - DACIA SANDERO: 1.6 LPG 06.2008/12.2012 64KW 87CV 1598CC - DACIA SANDERO: 1.6 Hi-Flex (BS1H) 06.2008/12.2012 64KW 87CV 1598CC</p> <p>194x175x106mm 2f-d17mm 1f-d10mm 1f-d12mm 1f-10x12mm...</p>
	<p>A2310 NO. 112100024R - 112102118R - 112845638R - 113756731R</p> <p>APOIO DO MOTOR FRENTE LADO DIREITO</p> <p>DACIA SANDERO II: 1.5 dCi 75 / Blue dCi 75 (B8JW, B8M4, B8AH, B8M7, B8M6) 10.2012/>>> 55KW 75CV 1461CC - DACIA SANDERO II: 1.5 dCi 10.2012/>>> 66KW 90CV 1461CC</p> <p>232x129x206mm 3f-d16mm 4f-d12mm 1f-d10mm</p>		<p>A2355 NO. 1f-d10mm 1f-d12mm 3f-d13mm 3f-d16mm</p> <p>APOIO DO MOTOR LADO DIREITO</p> <p>DACIA SANDERO II: 1.5 dCi 75 / Blue dCi 75 (B8JW, B8M4, B8AH, B8M7, B8M6) 10.2012/>>> 55KW 75CV 1461CC - DACIA SANDERO II: 1.5 dCi 10.2012/>>> 66KW 90CV 1461CC</p> <p>200x222x127mm 1f-d10mm 1f-d12mm 3f-d13mm 3f-d16mm...</p>
	<p>A32744 NO. 543A06915R - 6001547499 - 6001548403 - 8200275528 - 8200307941 - 8200651172 - 8200723741 - 820087629...</p> <p>APOIO SUPORTE AMORTECEDOR FRENTE (GASTA 2 UNIDADES)</p> <p>DACIA SANDERO 1.2 16V desde 11.2008 55KW 75CV 1149CC D4F 732 8212AAU 8212ABV - DACIA SANDERO 1.2 16V LPG desde 11.2008 55KW 75CV 1149CC D4F 732 8212ACQ - DACIA SANDERO 1.4 (BS0C, BS0A, BS0G, BS1F, BS0E) desde 06.2008 55KW 75CV 1390CC K7J 710 K7J 714 8212AAK 8212ABB 8212ABR - DACIA SANDERO 1.4 MPI LPG desde 01.2009 53KW 72CV 1390CC K7J 714 8212AAP - DACIA SANDERO 1.5 dCi desde 11.2008 50KW 68CV 146...</p> <p>d104x45mm d79x20mm d56x27mm 1f-d15mm 1f-d16mm 1r-d12mm</p>		<p>A32744 NO. 543A06915R - 6001547499 - 6001548403 - 8200275528 - 8200307941 - 8200651172 - 8200723741 - 820087629...</p> <p>APOIO SUPORTE AMORTECEDOR FRENTE (GASTA 2 UNIDADES)</p> <p>DACIA SANDERO II 1.2 desde 10.2012 55KW 75CV 1149CC D4F 732 8212AAU - DACIA SANDERO II 1.2 LPG desde 10.2012 55KW 75CV 1149CC D4F 732 8212ACQ - DACIA SANDERO II 1.5 dCi desde 10.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ADB - DACIA SANDERO II 1.5 dCi 75 / Blue dCi 75 (B8JW, B8M4, B8AH, B8M7, B8M6) desde 10.2012 55KW 75CV 1461CC K9K 626 K9K 612 K9K 838 8212ABN - DACIA SANDERO II Tce 90 (B8M...</p> <p>d104x45mm d79x20mm d56x27mm 1f-d15mm 1f-d16mm 1r-d12mm</p>
	<p>E0217-M NO. 112383665R - 6001549205 - 6001549647 - 8200014933 - 8200500928 - 8200575641</p> <p>ESTICADOR SUPORTE APOIO MOTOR TRAS</p> <p>DACIA SANDERO 1.2 16V desde 11.2008/>>> 55KW 75CV 1149CC D4F 732 8212AAU 8212ABV - DACIA SANDERO 1.2 16V LPG desde 11.2008/>>> 55KW 75CV 1149CC D4F 732 8212ACQ - DACIA SANDERO 1.4 desde 06.2008/>>> 55KW 75CV 1390CC K7J 710 8212AAK 8212ABB 8212ABR - DACIA SANDERO 1.4 MPI LPG desde 01.2009/>>> 53KW 72CV 1390CC K7J 714 8212AAP - DACIA SANDERO 1.5 dCi desde 11.2008/>>> 50KW 68CV 1461CC K9K 792 8212AAAM...</p> <p>270x90x60mm 2f-d13mm</p>		<p>E0246-M NO. 11360-9U000 - 11360-AX000 - 11360-AX600 - 11360-BN700 - 11360-ED000 - 11360-ED55A - 11360-ELO0A 11...</p> <p>ESTICADOR SUPORTE APOIO MOTOR TRAS</p> <p>DACIA SANDERO 1.2 16V desde 11.2008 55KW 75CV 1149CC D4F 732 8212AAU 8212ABV - DACIA SANDERO 1.4 (BS0C, BS0A, BS0G, BS1F, BS0E) desde 06.2008 55KW 75CV 1390CC K7J 710 K7J 714 8212AAK 8212ABB 8212ABR - DACIA SANDERO 1.4 MPI LPG desde 01.2009 53KW 72CV 1390CC K7J 714 8212AAP - DACIA SANDERO 1.5 dCi desde 11.2008 50KW 68CV 1461CC K9K 792 8212AAAM 8212ABC 8212ABT - DACIA SANDERO 1.5 dCi desde 11.2008 6...</p> <p>265x90x52mm 1f-d12mm 1f-d13mm</p>
	<p>E0267-M NO. 112381035R - 112383905R</p> <p>ESTICADOR SUPORTE APOIO MOTOR TRAS</p> <p>DACIA SANDERO II: Tce 90 10.2012/>>> 66KW 90CV 898CC - DACIA SANDERO II: 1.2 05.2015/>>> 54KW 73CV 1149CC - DACIA SANDERO II: 1.2 10.2012/>>> 55KW 75CV 1149CC - DACIA SANDERO II: 1.2 LPG 10.2012/>>> 55KW 75CV 1149CC - DACIA SANDERO II: 1.5 dCi 75 / Blue dCi 75 (B8JW, B8M4, B8AH, B8M7, B8M6) 10.2012/>>> 55KW 75CV 1461CC - DACIA SANDERO II: 1.5 dCi 10.2012/>>> 66KW 90CV 1461CC</p> <p>170x60x55mm 1f-d12mm 1f-d14mm</p>		<p>F1898-I NO. 392414459R - 6001547767 - 6001550339 - 6001551490 - 7701473830 - 8200017057</p> <p>FOLE TRANSMISSÃO JUNTO CAIXA</p> <p>DACIA SANDERO: 1.2 16V 11.2008/>>> 55KW 75CV 1149CC - DACIA SANDERO: 1.2 16V LPG 11.2008/>>> 55KW 75CV 1149CC - DACIA SANDERO: 1.4 MPI LPG 01.2009/>>> 53KW 72CV 1390CC - DACIA SANDERO: 1.4 06.2008/>>> 55KW 75CV 1390CC - DACIA SANDERO: 1.6 MPI 85 05.2010/>>> 62KW 84CV 1598CC - DACIA SANDERO: 1.6 LPG 05.2010/10.2012 62KW 84CV 1598CC - DACIA SANDERO: 1.6 06.2008/>>> 64KW 87CV 1598CC - DACIA SANDERO: ...</p> <p>d107x89mm 1f-d30mm 1f-d78mm</p>
	<p>F1898A3-I NO. 392414459R - 6001547767 - 6001550339 - 6001551490 - 7701473830 - 8200017057</p> <p>FOLE TRANSMISSÃO JUNTO CAIXA</p> <p>DACIA SANDERO: 1.2 16V 11.2008/>>> 55KW 75CV 1149CC - DACIA SANDERO: 1.2 16V LPG 11.2008/>>> 55KW 75CV 1149CC - DACIA SANDERO: 1.4 MPI LPG 01.2009/>>> 53KW 72CV 1390CC - DACIA SANDERO: 1.4 06.2008/>>> 55KW 75CV 1390CC - DACIA SANDERO: 1.6 MPI 85 05.2010/>>> 62KW 84CV 1598CC - DACIA SANDERO: 1.6 LPG 05.2010/10.2012 62KW 84CV 1598CC - DACIA SANDERO: 1.6 06.2008/>>> 64KW 87CV 1598CC - DACIA SANDERO: ...</p> <p>d107x89mm 1f-d25.8mm 1f-d78mm</p>		<p>F3773-T NO.</p> <p>FOLE TRANSMISSÃO JUNTO Á RODA</p> <p>DACIA SANDERO: 1.5 dCi 11.2008/>>> 50KW 68CV 1461CC - DACIA SANDERO: 1.5 dCi 11.2008/>>> 63KW 86CV 1461CC</p> <p>d93x121mm 1f-d76mm 1f-d23mm</p>
	<p>F4145 NO. 6001548402 - 6001549290 - 8200499414 - 8200814709</p> <p>FOLE CAPA PROTEÇÃO AMORTECEDOR FRENTE (GASTA 2 UNIDADES)</p> <p>DACIA SANDERO: 1.2 16V 11.2008/>>> 55KW 75CV 1149CC - DACIA SANDERO: 1.2 16V LPG 11.2008/>>> 55KW 75CV 1149CC - DACIA SANDERO: 1.4 MPI LPG 01.2009/>>> 53KW 72CV 1390CC - DACIA SANDERO: 1.4 06.2008/>>> 55KW 75CV 1390CC - DACIA SANDERO: 1.6 MPI 85 05.2010/>>> 62KW 84CV 1598CC - DACIA SANDERO: 1.6 LPG 05.2010/10.2012 62KW 84CV 1598CC - DACIA SANDERO: 1.6 06.2008/>>> 64KW 87CV 1598CC - DACIA SANDERO: ...</p> <p>d75x220mm 1f-d55mm 1f-d18mm</p>		<p>F4366 NO. 969356242R</p> <p>FOLE DA ALAVANCA DE VELOCIDADES</p> <p>DACIA SANDERO II 1.0 LPG (B8ML) (11.2019 -) 74kw 101cv 999cm3 Hatchback DACIA SANDERO II 1.0 ScE 75 (B8JC, B8JD) (12.2016 -) 54kw 73cv 999cm3 Hatchback DACIA SANDERO II 1.0 Tce 100 (B8ML) (11.2019 -) 74kw 101cv 999cm3 Hatchback DACIA SANDERO II 1.2 (05.2015 -) 54kw 73cv 1149cm3 Hatchback DACIA SANDERO II 1.2 (10.2012 -) 55kw 75cv 1149cm3 Hatchback DACIA SANDERO II 1.2 LPG (10.2012 -) 55kw 75cv 114...</p> <p>240x108x137mm 1f-96x122mm</p>

	<p>F9024H-I NO. 05014914AA - 39241BM525 - 39241BM526 - 39241BM527 - 44018-S6D-E01</p> <p>FOLE TRANSMISSÃO JUNTO RODA</p> <p>DACIA SANDERO: 1.5 dCi 11.2008/>>> 50KW 68CV 1461CC - DACIA SANDERO: 1.5 dCi 11.2008/>>> 63KW 86CV 1461CC</p> <p>d93x120mm 1f-d23mm 1f-d77mm</p>		<p>F9082H-I NO. 6001548666 - 7701209242</p> <p>FOLE TRANSMISSÃO JUNTO RODA</p> <p>DACIA SANDERO: 1.5 dCi 05.2010/>>> 55KW 75CV 1461CC - DACIA SANDERO: 1.5 dCi 05.2010/>>> 65KW 88CV 1461CC</p> <p>d87x101mm 1f-d25mm 1f-d80mm</p>
	<p>KF1695-I NO. 7701209258</p> <p>KIT FOLE DIREITO TRANSMISSÃO JUNTO CAIXA</p> <p>DACIA SANDERO: 1.5 dCi 11.2008/>>> 48KW 65CV 1461CC</p> <p>d86x98mm 1f-d22mm 1f-d74mm</p>		<p>KF1842-I NO. 6001550548 - 7701209925 - 7701209929</p> <p>FOLE DA TRANSMISSÃO JUNTO À CAIXA</p> <p>DACIA SANDERO 1.5 dCi desde 11.2008 50KW 68CV 1461CC K9K 792 8212AAM 8212ABC 8212ABT - DACIA SANDERO 1.5 dCi desde 11.2008 63KW 86CV 1461CC K9K 796 8212AAN 8212AAY 8212ABU - DACIA SANDERO 1.5 dCi desde 05.2010 55KW 75CV 1461CC K9K 892 8212ABN 8212ABW - DACIA SANDERO 1.5 dCi desde 05.2010 65KW 88CV 1461CC K9K 892 8212ABK 8212ABX - DACIA SANDERO 1.6 16V Bifuel desde 01.2011 77KW 105CV 1598CC K4M 694...</p> <p>d83x86mm 1f-d19mm 1f-d72mm</p>
	<p>KF1898A3-I NO. 7701473830</p> <p>KIT FOLE TRANSMISSÃO JUNTO CAIXA</p> <p>DACIA SANDERO: 1.2 16V 11.2008/>>> 55KW 75CV 1149CC - DACIA SANDERO: 1.2 16V LPG 11.2008/>>> 55KW 75CV 1149CC - DACIA SANDERO: 1.4 MPI LPG 01.2009/>>> 53KW 72CV 1390CC - DACIA SANDERO: 1.4 06.2008/>>> 55KW 75CV 1390CC - DACIA SANDERO: 1.6 MPI 85 05.2010/>>> 62KW 84CV 1598CC - DACIA SANDERO: 1.6 LPG 05.2010/10.2012 62KW 84CV 1598CC - DACIA SANDERO: 1.6 06.2008/>>> 64KW 87CV 1598CC - DACIA SANDERO: ...</p> <p>d107x89mm 1f-d25.8mm 1f-d78mm</p>		<p>KF9024H-I NO. 05014914AA - 39241BM525 - 39241BM526 - 39241BM527</p> <p>KIT FOLE TRANSMISSÃO JUNTO RODA</p> <p>DACIA SANDERO: 1.5 dCi 11.2008/>>> 50KW 68CV 1461CC - DACIA SANDERO: 1.5 dCi 11.2008/>>> 63KW 86CV 1461CC</p> <p>d93x120mm 1f-d23mm 1f-d77mm</p>
	<p>P1104 NO. 6001547908</p> <p>CAPA DE PEDAL DO TRAVÃO</p> <p>DACIA SANDERO: 1.2 16V 11.2008/>>> 55KW 75CV 1149CC - DACIA SANDERO: 1.2 16V LPG 11.2008/>>> 55KW 75CV 1149CC - DACIA SANDERO: 1.4 MPI LPG 01.2009/>>> 53KW 72CV 1390CC - DACIA SANDERO: 1.4 06.2008/>>> 55KW 75CV 1390CC - DACIA SANDERO: 1.6 MPI 85 05.2010/>>> 62KW 84CV 1598CC - DACIA SANDERO: 1.6 LPG 05.2010/10.2012 62KW 84CV 1598CC - DACIA SANDERO: 1.6 06.2008/>>> 64KW 87CV 1598CC - DACIA SANDERO: ...</p> <p>60x60x13mm 50x47x40mm</p>		<p>P1129 NO. 465310981R - 6001551783</p> <p>CAPA DE PEDAL DO TRAVÃO</p> <p>DACIA SANDERO 1.2 16V desde 11.2008 55KW 75CV 1149CC D4F 732 8212AAU 8212ABV - DACIA SANDERO 1.2 16V LPG desde 11.2008 55KW 75CV 1149CC D4F 732 8212ACQ - DACIA SANDERO 1.4 MPI LPG desde 01.2009 53KW 72CV 1390CC K7J 714 8212AAP - DACIA SANDERO 1.5 dCi desde 11.2008 50KW 68CV 1461CC K9K 792 8212AAM 8212ABC 8212ABT - DACIA SANDERO 1.5 dCi desde 11.2008 63KW 86CV 1461CC K9K 796 8212AAN 8212AAY 8212ABU...</p> <p>75x53x10mm 1f-d-52x33mm</p>
	<p>P1129 NO. 465310981R - 6001551783</p> <p>CAPA DE PEDAL DO TRAVÃO</p> <p>DACIA SANDERO II 1.0 LPG (B8ML) desde 11.2019 74KW 101CV 999CC H4D 460 H4D 450 8212AEZ - DACIA SANDERO II 1.0 SCe 75 (B8JC, B8JD) desde 12.2016 54KW 73CV 998CC B4D 400 B4D 401 B4D 490 8212AEI 8212AEL - DACIA SANDERO II 1.2 desde 10.2012 55KW 75CV 1149CC D4F 732 8212AAU - DACIA SANDERO II 1.2 desde 05.2015 54KW 73CV 1149CC D4F 732 8212ADT - DACIA SANDERO II 1.2 LPG desde 10.2012 55KW 75CV 1149CC D4...</p> <p>75x53x10mm 1f-d-52x33mm</p>		<p>Q2009 NO.</p> <p>UNIÃO DE ESCAPE 47/52.5x90mm</p> <p>DACIA - SANDERO - 1.4 (APÓS 06.08) 75cv 1390cc Hatchback - DACIA - SANDERO - 1.6 (APÓS 06.08) 87cv 1598cc Hatchback - DACIA - SANDERO - 1.5 dCi (APÓS 11.08) 68cv 1461cc Hatchback - DACIA - SANDERO - 1.5 dCi (APÓS 11.08) 86cv 1461cc Hatchback</p> <p>90x58x78mm 1f-d47mm</p>
	<p>R080330 NO. 14875-00QAB - 7700101229 - 8200035903 - 8200134513</p> <p>TUBO RIGIDO REFRIGERAÇÃO</p> <p>DACIA SANDERO 1.6 16V 07.2011/>>> 77KW 105CV 1598CC K4M 694, K4M 690 8212ACT - DACIA SANDERO 1.6 16V Bifuel 01.2011/>>> 77KW 105CV 1598CC K4M 694, K4M 696, K4M 690 8212ACJ, 8212ACC</p> <p>B365-26/26mm 76-320mm 1p-d20x45mm 1f-6x13</p>		<p>R080332 NO. 56x203x70mm ch-d20x27mm ch-d18x43mm ch-d</p> <p>TUBO RIGIDO DA REFRIGERAÇÃO</p> <p>DACIA SANDERO 1.5 dCi desde 11.2008 48KW 65CV 1461CC K9K 790</p> <p>B359-27/27mm 56x203x70mm ch-d20x27mm ch-d18x43mm ch-d</p>
	<p>R085226 NO. 1404200Q0C - 8200934107</p> <p>TUBO EXTRACTOR COMBUSTIVEL</p> <p>DACIA SANDERO 1.5 dCi (11.2008 -) 48kw 65cv 1461cm3 Hatchback DACIA SANDERO 1.5 dCi (05.2010 -) 55kw 75cv 1461cm3 Hatchback DACIA SANDERO 1.5 dCi (11.2008 -) 63kw 86cv 1461cm3 Hatchback DACIA SANDERO 1.5 dCi (05.2010 -) 65kw 88cv 1461cm3 Hatchback</p> <p>B325-5/5mm 66x340x60x66mm</p>		<p>R085226 NO. 1404200Q0C - 8200934107</p> <p>TUBO EXTRACTOR COMBUSTIVEL</p> <p>DACIA SANDERO II 1.5 dCi (10.2012 -) 66kw 90cv 1461cm3 Hatchback DACIA SANDERO II 1.5 dCi 75 / Blue dCi 75 (B8JW, B8M4, B8AH, B8M7, B8M6) (10.2012 -) 55kw 75cv 1461cm3 Hatchback</p> <p>B325-5/5mm 66x340x60x66mm</p>
	<p>R223276 NO. 7701061051</p> <p>TUBO LIGAÇÃO TERMOSTATO</p> <p>DACIA SANDERO 1.5 dCi desde 11.2008/>>> 50KW 68CV 1461CC K9K 792 8212AAM, 8212ABC, 8212ABT - DACIA SANDERO 1.5 dCi desde 11.2008/>>> 63KW 86CV 1461CC K9K 796 8212AAN, 8212AAY, 8212ABU</p> <p>B117-15/19mm 78-73mm ch-d20-50mm</p>		<p>R223383 NO. 8200240894 - 8200384940</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA SANDERO 1.5 dCi desde 11.2008 50KW 68CV 1461CC K9K 792 8212AAM 8212ABC 8212ABT - DACIA SANDERO 1.5 dCi desde 11.2008 63KW 86CV 1461CC K9K 796 8212AAN 8212AAY 8212ABU - DACIA SANDERO 1.5 dCi desde 05.2010 65KW 88CV 1461CC K9K 892 8212ABK 8212ABX</p> <p>B660-33/51mm 69-105-170-420-125mm</p>

	<p>R224078 NO. 1655600QAM - 8200331958</p> <p>TUBO ADMISSÃO FILTRO DE AR</p> <p>DACIA SANDERO 1.5 dCi desde 11.2008 48KW 65CV 1461CC K9K 790 - DACIA SANDERO 1.5 dCi desde 11.2008 50KW 68CV 1461CC K9K 792 8212AAM 8212ABC 8212ABT - DACIA SANDERO 1.5 dCi desde 11.2008 63KW 86CV 1461CC K9K 796 8212AAN 8212AAY 8212ABU - DACIA SANDERO 1.5 dCi desde 05.2010 55KW 75CV 1461CC K9K 892 8212ABN 8212ABW - DACIA SANDERO 1.5 dCi desde 05.2010 65KW 88CV 1461CC K9K 892 8212ABK 8212ABX</p> <p>260x40x61mm 45x140x113x71mm ch-d22x33mm</p>		<p>R224548 NO. 8200469423 - 8200598010</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA SANDERO 1.5 dCi desde 11.2008 50KW 68CV 1461CC K9K 792 8212AAM 8212ABC 8212ABT - DACIA SANDERO 1.5 dCi desde 11.2008 63KW 86CV 1461CC K9K 796 8212AAN 8212AAY 8212ABU</p> <p>B710-48/57mm 140-99-84-190-160-72-164mm</p>
	<p>R224723 NO. 1446000Q1D - 144600835R - 144601524R - 144602760R - 144606171R - 144606189R - 144606515R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA SANDERO II 1.5 dCi desde 10.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ADB - DACIA SANDERO II 1.5 dCi 75 / Blue dCi 75 (B8JW, B8M4, B8AH, B8M7, B8M6) desde 10.2012 55KW 75CV 1461CC K9K 872 K9K 626 K9K 612 K9K 838 8212ABN</p> <p>B115-49/52mm</p>		<p>R224759 NO. 144604599R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA SANDERO II 1.5 Blue dCi 95 (B8JL) desde 08.2018 70KW 95CV 1461CC K9K 872 8212AES - DACIA SANDERO II 1.5 dCi desde 10.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ADB - DACIA SANDERO II 1.5 dCi 75 / Blue dCi 75 (B8JW, B8M4, B8AH, B8M7, B8M6) desde 10.2012 55KW 75CV 1461CC K9K 872 K9K 626 K9K 612 K9K 838 8212ABN</p> <p>B650-50/52mm 56-92-108-156-185-77-46-45mm</p>
	<p>R224764 NO. 144606189R - 144600835R - 144601524R - 144602760R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA SANDERO II 1.5 dCi desde 10.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ADB - DACIA SANDERO II 1.5 dCi 75 / Blue dCi 75 (B8JW, B8M4, B8AH, B8M7, B8M6) desde 10.2012 55KW 75CV 1461CC K9K 872 K9K 626 K9K 612 K9K 838 8212ABN</p> <p>B270-46/47mm 86-89-78mm</p>		<p>R224819 NO. 1412000QJ - 1412000Q1E - 1412000Q1G - 223211229R - 223211568R - 223211824R - 223214402R - 220991250</p> <p>TUBO VALVULA REGULADOR DE VELOCIDADE</p> <p>DACIA SANDERO 1.5 dCi desde 11.2008 48KW 65CV 1461CC K9K 790 - DACIA SANDERO 1.5 dCi desde 11.2008 50KW 68CV 1461CC K9K 792 8212AAM 8212ABC 8212ABT</p> <p>B67-6/6mm</p>
	<p>R8210 NO. 223211229R - 223214402R</p> <p>TUBO DA VALVULA DO REGULADOR DE VELOCIDADE</p> <p>DACIA SANDERO 1.5 dCi desde 11.2008 48KW 65CV 1461CC K9K 790 - DACIA SANDERO 1.5 dCi desde 11.2008 50KW 68CV 1461CC K9K 792 8212AAM 8212ABC 8212ABT</p> <p>222x82x16mm 1f-d6mm 1f-d11mm</p>		<p>R8219 NO. 1446000Q1H - 144600492R - 144605243R</p> <p>TUBO DO AR SOBREALIMENTAÇÃO</p> <p>DACIA SANDERO II TCe 90 (B8M1, B8MA, B8AC) desde 10.2012 66KW 90CV 898CC H4B 400 H4B 408 8212ACZ - DACIA SANDERO II TCe 90 LPG (B8M1) desde 09.2015 66KW 90CV 898CC H4B 410 8212ADY</p> <p>B560-31/39mm 110-53-230-105-58mm</p>
	<p>RFL19610 NO. 8200140155 - 8200231833 - 8200714635</p> <p>TUBO FLEXIVEL DO ÓLEO DO TURBO</p> <p>DACIA SANDERO II 1.5 Blue dCi 95 (B8JL) desde 08.2018 70KW 95CV 1461CC K9K 872 8212AES - DACIA SANDERO II 1.5 dCi desde 10.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ADB - DACIA SANDERO II 1.5 dCi 75 / Blue dCi 75 (B8JW, B8M4, B8AH, B8M7, B8M6) desde 10.2012 55KW 75CV 1461CC K9K 872 K9K 626 K9K 612 K9K 838 8212ABN</p> <p>B222-14/14mm 129x67x30mm 1f-d6mm 1f-6x8mm</p>		<p>RFL61319 NO. 8200310122 - 8200376094 - 8200575489 - 8200714635</p> <p>TUBO FLEXIVEL DO OLEO</p> <p>DACIA SANDERO II 1.5 Blue dCi 95 (B8JL) desde 08.2018 70KW 95CV 1461CC K9K 872 8212AES - DACIA SANDERO II 1.5 dCi desde 10.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ADB - DACIA SANDERO II 1.5 dCi 75 / Blue dCi 75 (B8JW, B8M4, B8AH, B8M7, B8M6) desde 10.2012 55KW 75CV 1461CC K9K 872 K9K 626 K9K 612 K9K 838 8212ABN</p> <p>B236-11/12mm 1f-d6mm 71x96x51x31mm</p>
	<p>RT08443 NO. 6001547816 - 6001547819 - 6001551098</p> <p>TUBO DE TRAVÃO FRENTE LH-RH</p> <p>DACIA SANDERO 1.4 (BS0C, BS0A, BS0G, BS1F, BS0E) desde 06.2008 55KW 75CV 1390CC K7J 710 K7J 714 8212AAB 8212ABB 8212ABR - DACIA SANDERO 1.5 dCi desde 11.2008 50KW 68KW 1461CC K9K 792 8212AAM 8212ABC 8212ABT - DACIA SANDERO 1.5 dCi desde 11.2008 63KW 86CV 1461CC K9K 796 8212AAN 8212AAY 8212ABU - DACIA SANDERO 1.6 (BS0D, BS0B, BS0F, BS0H) desde 06.2008 64KW 87CV 1598CC K7M 710 K7M 718 8212AAL 8212AB...</p> <p>330mm FZ - MC11</p>		<p>S1675 NO. 430004469R - 555016396R - 55511772R4 - 6001547887 - 6001548949 - 6001549988 - 6001549989 - 820028791...</p> <p>SILENT-BLOC DO EIXO SUSPENSÃO DE TRÁS</p> <p>DACIA SANDERO 1.2 16V desde 11.2008 55KW 75CV 1149CC D4F 732 8212AAU 8212ABV - DACIA SANDERO 1.2 16V LPG desde 11.2008 55KW 75CV 1149CC D4F 732 8212ACQ - DACIA SANDERO 1.4 (BS0C, BS0A, BS0G, BS1F, BS0E) desde 06.2008 55KW 75CV 1390CC K7J 710 K7J 714 8212AAB 8212ABB 8212ABR - DACIA SANDERO 1.4 MPI LPG desde 01.2009 53KW 72CV 1390CC K7J 714 8212AAP - DACIA SANDERO 1.5 dCi desde 11.2008 50KW 68CV 146...</p> <p>76x90mm c54mm d67mm 1f-d12mm</p>
	<p>S1689 NO. 60 01 547 519 - 60 01 547 520 - 60 01 549 181 - 60 01 549 182 - 60 01 550 446 - 60 01 550 447 - 60 01 550 448 - 60 01 550 449 - 60 01 550 450</p> <p>SILENT-BLOC DO BRAÇO DA SUSPENSÃO DA FRENTE</p> <p>DACIA SANDERO 1.2 16V desde 11.2008 55KW 75CV 1149CC D4F 732 8212AAU 8212ABV - DACIA SANDERO 1.2 16V LPG desde 11.2008 55KW 75CV 1149CC D4F 732 8212ACQ - DACIA SANDERO 1.4 (BS0C, BS0A, BS0G, BS1F, BS0E) desde 06.2008 55KW 75CV 1390CC K7J 710 K7J 714 8212AAB 8212ABB 8212ABR - DACIA SANDERO 1.4 MPI LPG desde 01.2009 53KW 72CV 1390CC K7J 714 8212AAP - DACIA SANDERO 1.5 dCi desde 11.2008 50KW 68CV 146...</p> <p>d50x46mm c29mm d37mm 1f-d12mm</p>		<p>S1689 NO. 545004529R - 545007106R - 545010294R - 545011727R - 6640096299</p> <p>SILENT-BLOC DO BRAÇO SUSPENSÃO DA FRENTE</p> <p>DACIA SANDERO II 1.0 ScE 75 (B8JC, B8JD) desde 12.2016 54KW 73CV 998CC B4D 400 B4D 401 B4D 490 8212AEI 8212AEL - DACIA SANDERO II 1.2 desde 10.2012 55KW 75CV 1149CC D4F 732 8212AAU - DACIA SANDERO II 1.2 desde 05.2015 54KW 73CV 1149CC D4F 732 8212ADT - DACIA SANDERO II 1.2 LPG desde 10.2012 55KW 75CV 1149CC D4F 734 8212ACQ - DACIA SANDERO II 1.5 Blue dCi 95 (B8JL) desde 08.2018 70KW 95CV 1461CC K9...</p> <p>d50x46mm c29mm d37mm 1f-d12mm</p>
	<p>T1185 NO. 6001547140</p> <p>BATENTE DA BARRA ESTABILIZADORA DA FRENTE</p> <p>DACIA SANDERO 1.2 16V desde 11.2008 55KW 75CV 1149CC D4F 732 8212AAU 8212ABV - DACIA SANDERO 1.2 16V LPG desde 11.2008 55KW 75CV 1149CC D4F 732 8212ACQ - DACIA SANDERO 1.4 (BS0C, BS0A, BS0G, BS1F, BS0E) desde 06.2008 55KW 75CV 1390CC K7J 710 K7J 714 8212AAB 8212ABB 8212ABR - DACIA SANDERO 1.4 MPI LPG desde 01.2009 53KW 72CV 1390CC K7J 714 8212AAP - DACIA SANDERO 1.5 dCi desde 11.2008 50KW 68CV 146...</p> <p>35x39x37mm 1f-d22mm</p>		<p>UAP81637 NO. 7703062072 - 8200014894</p> <p>ANILHA PROTEÇÃO TÉRMICA INJECTORES</p> <p>DACIA SANDERO 1.5 dCi desde 11.2008 50KW 68CV 1461CC K9K 792 8212AAM 8212ABC 8212ABT - DACIA SANDERO 1.5 dCi desde 11.2008 63KW 86CV 1461CC K9K 796 8212AAN 8212AAY 8212ABU - DACIA SANDERO 1.5 dCi desde 05.2010 55KW 75CV 1461CC K9K 892 8212ABN 8212ABW - DACIA SANDERO 1.5 dCi desde 05.2010 65KW 88CV 1461CC K9K 892 8212ABK 8212ABX - DACIA SANDERO II 1.5 dCi desde 10.2012 66KW 90CV 1461CC K9K 626 K9K ...</p> <p>d15x3mm 1f-d7mm</p>

	<p>UFT90167 NO. 1106000Q0K - 110603026R - 110605536R - 8200954328</p> <p>FALANGE TERMOSTATO</p> <p>DACIA SANDERO II 1.5 dCi desde 10.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ADB - DACIA SANDERO II 1.5 dCi 75 / Blue dCi 75 (B8JW, B8M4, B8AH, B8M7, B8M6) desde 10.2012 55KW 75CV 1461CC K9K 872 K9K 626 K9K 612 K9K 838 8212ABN</p> <p>169x101x100mm 3f-d7mm 1f-16mm 1f-d28mm</p>		<p>UMB80660 NO. 7700106271 - 7700106383</p> <p>TAMPÃO BLOCO MOTOR</p> <p>DACIA SANDERO 1.6 16V desde 07.2011 77KW 105CV 1598CC K4M 694 K4M 690 8212ACT - DACIA SANDERO 1.6 16V Bifuel desde 01.2011 77KW 105CV 1598CC K4M 694 K4M 696 K4M 690 8212ACJ 8212ACC</p> <p>d-57,3x10mm di-52,7mm</p>
	<p>UMB80661 NO. 6001543014 - 7700274026 - 8200058022</p> <p>TAMPÃO BLOCO MOTOR</p> <p>DACIA SANDERO 1.4 (BS0C, BS0A, BS0G, BS1F, BS0E) desde 06.2008 55KW 75CV 1390CC K7J 710 K7J 714 8212AAK 8212ABB 8212ABR - DACIA SANDERO 1.6 (BS0D, BS0B, BS0F, BS0H) desde 06.2008 64KW 87CV 1598CC K7M 710 K7M 718 8212AAL 8212ABA 8212ABS - DACIA SANDERO 1.6 MPI 85 (BS03) 05.2010/06.2013 62KW 84CV 1598CC K7M 800 K7M 818 8212ACI 8212ACE</p> <p>d42x8mm di-38x7mm</p>		<p>URL36540 NO. 33140-33G01 - 33140-33G02 - 33142-33G10 - 8200651172</p> <p>ROLAMENTO DO APOIO SUPORTE AMORTECEDOR FRENTE COMPENETA A1479-C (GASTA 2 UNIDADES)</p> <p>DACIA SANDERO 1.2 16V desde 11.2008 55KW 75CV 1149CC D4F 732 8212AAU 8212ABV - DACIA SANDERO 1.2 16V LPG desde 11.2008 55KW 75CV 1149CC D4F 732 8212ACQ - DACIA SANDERO 1.4 (BS0C, BS0A, BS0G, BS1F, BS0E) desde 06.2008 55KW 75CV 1390CC K7J 710 K7J 714 8212AAK 8212ABB 8212ABR - DACIA SANDERO 1.4 MPI LPG desde 01.2009 53KW 72CV 1390CC K7J 714 8212AAP - DACIA SANDERO 1.5 dCi desde 11.2008 50KW 68CV 146...</p> <p>d56x9mm 1f-d16mm</p>
	<p>URTE6017 NO. 144652865R</p> <p>RETENTOR TUBO AR SOBREALIMENTAÇÃO D45,5X49X4,8MM</p> <p>DACIA SANDERO II TCe 90 (B8M1, B8MA) desde 10.2012 66KW 90CV 898CC H4B 400 H4B 408 8212ACZ - DACIA SANDERO II TCe 90 LPG (B8M1) desde 09.2015 66KW 90CV 898CC H4B 410 8212ADY</p> <p>d48x5mm 1f-d45mm</p>		<p>URTE6018 NO. 140797120R</p> <p>RETENTOR TUBO AR SOBREALIMENTAÇÃO</p> <p>DACIA SANDERO II 1.5 dCi desde 10.2012 66KW 90CV 1461CC K9K 626 K9K 612 8212ADB - DACIA SANDERO II 1.5 dCi 75 / Blue dCi 75 (B8JW, B8M4, B8AH, B8M7, B8M6) desde 10.2012 55KW 75CV 1461CC K9K 872 K9K 626 K9K 612 K9K 838 8212ABN</p> <p>d46x5mm d42mm</p>
	<p>UTR0817 NO. 21430-AX300 - 21430-AX600 - 21430AX30A - 4408066 - 7700805131 - 8200048024 - 91166192</p> <p>TAMPÃO RESERVATÓRIO LÍQUIDO REFRIGERAÇÃO</p> <p>DACIA SANDERO 1.4 (BS0C, BS0A, BS0G, BS1F, BS0E) desde 06.2008 55KW 75CV 1390CC K7J 710 K7J 714 8212AAK 8212ABB 8212ABR - DACIA SANDERO 1.6 (BS0D, BS0B, BS0F, BS0H) desde 06.2008 64KW 87CV 1598CC K7M 710 K7M 718 8212AAL 8212ABA 8212ABS</p> <p>53x36mm 1f-d46x18mm</p>		<p>UTR1403 NO. 7701470950 - 7701471585</p> <p>TAMPÃO DEPÓSITO COMBUSTÍVEL</p> <p>DACIA SANDERO 1.2 16V desde 11.2008 55KW 75CV 1149CC D4F 732 8212AAU 8212ABV - DACIA SANDERO 1.2 16V LPG desde 11.2008 55KW 75CV 1149CC D4F 732 8212ACQ - DACIA SANDERO 1.4 (BS0C, BS0A, BS0G, BS1F, BS0E) desde 06.2008 55KW 75CV 1390CC K7J 710 K7J 714 8212AAK 8212ABB 8212ABR - DACIA SANDERO 1.4 MPI LPG desde 01.2009 53KW 72CV 1390CC K7J 714 8212AAP - DACIA SANDERO 1.5 dCi desde 11.2008 48KW 65CV 146...</p> <p>d73x67mm d37mm</p>
	<p>W5106 NO. 8200184103 - 8200185800 - 8200477938 - 8200511194</p> <p>POLIE DA CAMBOTA (6 PISTAS)</p> <p>DACIA SANDERO 1.5 dCi desde 11.2008 48KW 65CV 1461CC K9K 790 - DACIA SANDERO 1.5 dCi desde 11.2008 50KW 68CV 1461CC K9K 792 8212AAM 8212ABC 8212ABT - DACIA SANDERO 1.5 dCi desde 11.2008 63KW 86CV 1461CC K9K 796 8212AAN 8212AAY 8212ABU - DACIA SANDERO 1.5 dCi desde 05.2010 55KW 75CV 1461CC K9K 892 8212ABN 8212ABW - DACIA SANDERO 1.5 dCi desde 05.2010 65KW 88CV 1461CC K9K 892 8212ABK 8212ABX - DACIA...</p> <p>d155/151mm d26mm</p>		<p>W5108 NO. 12201-00QAW - 12303-00QJ - 12303-00Q1H - 12303-00Q2K - 12303-00QAY - 12303-00QBA - 12303-BN700</p> <p>POLIE DA CAMBOTA (5 PISTAS)</p> <p>DACIA SANDERO: 1.5 dCi 05.2010/»»» 55KW 75CV 1461CC - DACIA SANDERO: 1.5 dCi 05.2010/»»» 65KW 88CV 1461CC - DACIA SANDERO II: 1.5 dCi 75 / Blue dCi 75 (B8JW, B8M4, B8AH, B8M7, B8M6) 10.2012/»»» 55KW 75CV 1461CC - DACIA SANDERO II: 1.5 dCi 10.2012/»»» 66KW 90CV 1461CC</p> <p>d153.4mm 1f-d26mm</p>
	<p>W5137 NO. 7700105788 - 7700107122 - 8200044050 - 8200352613 - 8200395313 - 8200544135 - 8200552236 - 820055764...</p> <p>POLIE DA CAMBOTA 6 PISTAS</p> <p>DACIA SANDERO: 1.6 16V 07.2011/»»» 77KW 105CV 1598CC - DACIA SANDERO: 1.5 dCi 11.2008/»»» 50KW 68CV 1461CC - DACIA SANDERO: 1.5 dCi 05.2010/»»» 55KW 75CV 1461CC - DACIA SANDERO: 1.5 dCi 11.2008/»»» 63KW 86CV 1461CC - DACIA SANDERO: 1.5 dCi 05.2010/»»» 65KW 88CV 1461CC - DACIA SANDERO II: 1.5 dCi 75 / Blue dCi 75 (B8JW, B8M4, B8AH, B8M7, B8M6) 10.2012/»»» 55KW 75CV 1461CC - DACIA SANDERO II: 1.5 dCi...</p> <p>d155mm d26mm</p>		<p>W5168 NO. 7700273916 - 8200847840</p> <p>POLIE DA CAMBOTA (6 PISTAS)</p> <p>DACIA SANDERO: 1.4 MPI LPG 01.2009/»»» 53KW 72CV 1390CC - DACIA SANDERO: 1.4 06.2008/»»» 55KW 75CV 1390CC - DACIA SANDERO: 1.6 MPI 85 05.2010/»»» 62KW 84CV 1598CC - DACIA SANDERO: 1.6 05.2010/10.2012 62KW 84CV 1598CC - DACIA SANDERO: 1.6 06.2008/»»» 64KW 87CV 1598CC - DACIA SANDERO: 1.6 Hi-Flex (BS1H) 06.2008/12.2012 64KW 87CV 1598CC</p> <p>d133mm 1f-d13/25mm</p>
	<p>W5216 NO. 8200758088</p> <p>POLIE DA CAMBOTA RODA DENTADA (19 DENTES)</p> <p>DACIA SANDERO 1.6 16V desde 07.2011 77KW 105CV 1598CC K4M 694 K4M 690 8212ACT</p> <p>d56x32mm 1f-26mm</p>		<p>Y3239 NO. 8200473313 - 8200610460</p> <p>PARAFUSO PERNO RODA CHAVE 17 M12X1,50X50MM (BASE CÔNICA)</p> <p>DACIA SANDERO 1.2 16V desde 11.2008 55KW 75CV 1149CC D4F 732 8212AAU 8212ABV - DACIA SANDERO 1.4 (BS0C, BS0A, BS0G, BS1F, BS0E) desde 06.2008 55KW 75CV 1390CC K7J 710 K7J 714 8212AAK 8212ABB 8212ABR - DACIA SANDERO 1.4 MPI LPG desde 01.2009 53KW 72CV 1390CC K7J 714 8212AAP - DACIA SANDERO 1.5 dCi desde 11.2008 50KW 68CV 1461CC K9K 792 8212AAM 8212ABC 8212ABT - DACIA SANDERO 1.5 dCi desde 11.2008 6...</p> <p>c51mm (ch-17mm) M12x1x24mm</p>
	<p>Z80633 NO. 7703081054 - 7703081127 - 7703081227</p> <p>Mola de painel</p> <p>DACIA SANDERO 1.2 16V desde 11.2008 55KW 75CV 1149CC D4F 732 8212AAU 8212ABV - DACIA SANDERO 1.2 16V LPG desde 11.2008 55KW 75CV 1149CC D4F 732 8212ACQ - DACIA SANDERO 1.4 (BS0C, BS0A, BS0G, BS1F, BS0E) desde 06.2008 55KW 75CV 1390CC K7J 710 K7J 714 8212AAK 8212ABB 8212ABR - DACIA SANDERO 1.4 MPI LPG desde 01.2009 53KW 72CV 1390CC K7J 714 8212AAP - DACIA SANDERO 1.5 dCi desde 11.2008 48KW 65CV 146...</p> <p>d30x17mm 1p-d9.7-15mm</p>		