

	<p><b>UTR0913</b> NO. 1192550041</p> <p>TAMPÃO DEPOSITO COMBUSTIVEL</p> <p>NEW HOLLAND</p> <p>d86x29mm      d67x13mm</p>		<p><b>UTR0923</b> NO. 82009352</p> <p>TAMPÃO DEPÓSITO COMBUSTIVEL</p> <p>NEW HOLLAND</p> <p>d89x21mm      1f-d75x17mm d27x27mm</p>
	<p><b>UTR0924</b> NO. 84385969 - 87324388 - JX1070C - JX1070U - JX1075C</p> <p>TAMPÃO DEPÓSITO COMBUSTIVEL</p> <p>NEW HOLLAND</p> <p>d109x27mm      1f-d83x28mm</p>		<p><b>UTR0925</b> NO. 17584994939 - 32584994939 - 84991165 - 84994939</p> <p>TAMPÃO DEPÓSITO COMBUSTIVEL</p> <p>NEW HOLLAND</p> <p>d109x38mm      1f-d83x31mm</p>
	<p><b>UTR0926</b> NO. 87761857 - F3A6766BA</p> <p>TAMPÃO RESERVATORIO DO OLEO</p> <p>NEW HOLLAND</p> <p>d68x18mm      d31x18mm</p>		