



















	<p><b>UPCR5020</b> NO. 1377747 - 1382841 - 1428137 - 1676176 - 5196786 - 5275544</p> <p>PORCA DA RODA</p> <p>FORD C-MAX II (DXA/CB7, DXA/CEU) 1.0 EcoBoost (10.2012 -06.2019) 74kw 100cv 998cm3 Veículo multiuso FORD C-MAX II (DXA/CB7, DXA/CEU) 1.0 EcoBoost (10.2012 -06.2019) 92kw 125cv 998cm3 Veículo multiuso FORD C-MAX II (DXA/CB7, DXA/CEU) 1.0 EcoBoost (07.2018 -06.2019) 74kw 100cv 999cm3 Veículo multiuso FORD C-MAX II (DXA/CB7, DXA/CEU) 1.0 EcoBoost (07.2018 -06.2019) 92kw 125cv...</p> <p>d28x34mm M14x32mm</p>		<p><b>UPCR5020</b> NO. 1377747 - 1382841 - 1428137 - 1676176 - 5196786 - 5275544</p> <p>PORCA DA RODA</p> <p>FORD FOCUS III 1.0 EcoBoost (02.2012 -12.2017) 74kw 100cv 998cm3 Hatchback FORD FOCUS III 1.0 EcoBoost (02.2012 -12.2017) 92kw 125cv 998cm3 Hatchback FORD FOCUS III 1.0 EcoBoost (10.2017 -06.2019) 103kw 140cv 998cm3 Hatchback FORD FOCUS III 1.5 EcoBoost (09.2014 -12.2017) 110kw 150cv 1498cm3 Hatchback FORD FOCUS III 1.5 EcoBoost (09.2014 -12.2017) 134kw 182cv 1498cm3 Hatchba...</p> <p>d28x34mm M14x32mm</p>
	<p><b>UPCR5020</b> NO. 1377747 - 1382841 - 1428137 - 1676176 - 5196786 - 5275544</p> <p>PORCA DA RODA</p> <p>FORD GALAXY II (WA6) 1.6 EcoBoost (11.2010 -06.2015) 118kw 160cv 1596cm3 Veículo multiuso FORD GALAXY II (WA6) 1.6 TDCi (02.2011 -06.2015) 85kw 115cv 1560cm3 Veículo multiuso FORD GALAXY II (WA6) 1.8 TDCi (05.2006 -06.2015) 74kw 100cv 1753cm3 Veículo multiuso FORD GALAXY II (WA6) 1.8 TDCi (05.2006 -06.2015) 92kw 125cv 1753cm3 Veículo multiuso FORD GALAXY II (WA6) 2.0 (05...</p> <p>d28x34mm M14x32mm</p>		<p><b>UPCR5020</b> NO. 1377747 - 1382841 - 1428137 - 1676176 - 5196786 - 5275544</p> <p>PORCA DA RODA</p> <p>FORD GALAXY MK II VAN (WA6) TDCi (11.2006 -06.2015) 96kw 131cv 1997cm3 Caixa/monovolume FORD GALAXY MK II VAN (WA6) TDCi (05.2006 -06.2015) 103kw 140cv 1997cm3 Caixa/monovolume FORD GALAXY MK II VAN (WA6) TDCi (03.2013 -06.2015) 147kw 200cv 2179cm3 Caixa/monovolume</p> <p>d28x34mm M14x32mm</p>
	<p><b>UPCR5020</b> NO. 1377747 - 1382841 - 1428137 - 1676176 - 5196786 - 5275544</p> <p>PORCA DA RODA</p> <p>FORD S-MAX (CJ, WA6) 2.0 EcoBlue (07.2018 -) 88kw 120cv 1995cm3 Veículo multiuso FORD S-MAX (CJ, WA6) 2.0 EcoBlue (07.2018 -) 110kw 150cv 1995cm3 Veículo multiuso FORD S-MAX (CJ, WA6) 2.0 EcoBlue (07.2018 -) 140kw 190cv 1995cm3 Veículo multiuso FORD S-MAX (CJ, WA6) 2.0 EcoBlue 4x4 (07.2018 -) 110kw 150cv 1995cm3 Veículo multiuso FORD S-MAX (CJ, WA6) 2.0 EcoBlue 4x4 (07.2...</p> <p>d28x34mm M14x32mm</p>		<p><b>UPCR5020</b> NO. 1377747 - 1382841 - 1428137 - 1676176 - 5196786 - 5275544</p> <p>PORCA DA RODA</p> <p>FORD TOURNEO CONNECT / GRAND TOURNEO CONNECT V408 Veículo multius 1.0 EcoBoost (11.2013 -) 74kw 100cv 998cm3 Veículo multiuso FORD TOURNEO CONNECT / GRAND TOURNEO CONNECT V408 Veículo multius 1.5 EcoBlue (05.2018 -) 55kw 75cv 1499cm3 Veículo multiuso FORD TOURNEO CONNECT / GRAND TOURNEO CONNECT V408 Veículo multius 1.5 EcoBlue (05.2018 -) 74kw 101cv 1499cm3 Veículo mul...</p> <p>d28x34mm M14x32mm</p>
	<p><b>UPCR5020</b> NO. 1377747 - 1382841 - 1428137 - 1676176 - 5196786 - 5275544</p> <p>PORCA DA RODA</p> <p>FORD TOURNEO COURIER B460 Veículo multiuso 1.0 EcoBoost (02.2014 -) 74kw 100cv 998cm3 Veículo multiuso FORD TOURNEO COURIER B460 Veículo multiuso 1.5 EcoBlue (04.2018 -) 74kw 100cv 1499cm3 Veículo multiuso FORD TOURNEO COURIER B460 Veículo multiuso 1.5 TDCi (02.2014 -) 55kw 75cv 1499cm3 Veículo multiuso FORD TOURNEO COURIER B460 Veículo multiuso 1.5 TDCi (05.2015 -) 7...</p> <p>d28x34mm M14x32mm</p>		<p><b>UPCR5020</b> NO. 1377747 - 1382841 - 1428137 - 1676176 - 5196786 - 5275544</p> <p>PORCA DA RODA</p> <p>FORD TRANSIT CONNECT V408 Caixa/monovolume 1.0 EcoBoost (02.2013 -) 74kw 100cv 998cm3 Caixa/monovolume FORD TRANSIT CONNECT V408 Caixa/monovolume 1.5 EcoBlue (05.2018 -) 88kw 120cv 1499cm3 Caixa/monovolume FORD TRANSIT CONNECT V408 Caixa/monovolume 1.5 EcoBlue (05.2018 -) 55kw 75cv 1499cm3 Caixa/monovolume FORD TRANSIT CONNECT V408 Caixa/monovolume 1.5 EcoBlue (05.2018 -) 74...</p> <p>d28x34mm M14x32mm</p>
	<p><b>UPCR5020</b> NO. 1377747 - 1382841 - 1428137 - 1676176 - 5196786 - 5275544</p> <p>PORCA DA RODA</p> <p>FORD TRANSIT COURIER B460 Caixa/monovolume 1.0 EcoBoost (02.2014 -) 74kw 100cv 998cm3 Caixa/monovolume FORD TRANSIT COURIER B460 Caixa/monovolume 1.5 EcoBlue (04.2018 -) 74kw 100cv 1499cm3 Caixa/monovolume FORD TRANSIT COURIER B460 Caixa/monovolume 1.5 TDCi (02.2014 -) 55kw 75cv 1499cm3 Caixa/monovolume FORD TRANSIT COURIER B460 Caixa/monovolume 1.5 TDCi (05.2015 -) 70kw 95c...</p> <p>d28x34mm M14x32mm</p>		<p><b>UPCR5020</b> NO. 1377747 - 1382841 - 1428137 - 1676176 - 5196786 - 5275544</p> <p>PORCA DA RODA</p> <p>FORD TRANSIT TOURNEO Autocarro 2.2 (10.2011 -08.2014) 92kw 125cv 2198cm3 Autocarro FORD TRANSIT TOURNEO Autocarro 2.2 TDCi (07.2006 -08.2014) 81kw 110cv 2198cm3 Autocarro FORD TRANSIT TOURNEO Autocarro 2.2 TDCi (10.2008 -08.2014) 85kw 115cv 2198cm3 Autocarro FORD TRANSIT TOURNEO Autocarro 2.2 TDCi (07.2006 -08.2014) 96kw 131cv 2198cm3 Autocarro FORD TRANSIT TOURNEO Autocarro...</p> <p>d28x34mm M14x32mm</p>
	<p><b>UPCR5020</b> NO. 1377747 - 1382841 - 1428137 - 1676176 - 5196786 - 5275544</p> <p>PORCA DA RODA</p> <p>FORD USA EDGE 2.0 EcoBlue (08.2018 -) 110kw 150cv 1995cm3 SUV FORD USA EDGE 2.0 EcoBlue AWD (08.2018 -) 140kw 190cv 1995cm3 SUV FORD USA EDGE 2.0 EcoBlue AWD (08.2018 -) 175kw 238cv 1995cm3 SUV FORD USA EDGE 2.0 TDCi AWD (08.2015 - 07.2018) 132kw 180cv 1997cm3 SUV FORD USA EDGE 2.0 TDCi Bi-Turbo AWD (08.2015 - 07.2018) 154kw 210cv 1997cm3 SUV</p> <p>d28x34mm M14x32mm</p>		<p><b>UPCR5020</b> NO. 1377747 - 1382841 - 1428137 - 1676176 - 5196786 - 5275544</p> <p>PORCA DA RODA</p> <p>FORD USA MUSTANG Convertible 2.3 EcoBoost (09.2017 -) 213kw 290cv 2261cm3 Cabriolet FORD USA MUSTANG Convertible 2.3 EcoBoost (12.2014 -) 228kw 310cv 2261cm3 Cabriolet FORD USA MUSTANG Convertible 2.3 EcoBoost (01.2015 -) 231kw 314cv 2264cm3 Cabriolet FORD USA MUSTANG Convertible 2.3 EcoBoost (07.2015 -) 233kw 317cv 2261cm3 Cabriolet FORD USA MUSTANG Convertible 5.0 (09.2010)...</p> <p>d28x34mm M14x32mm</p>
	<p><b>UPCR5020</b> NO. LR001381 - LR043267</p> <p>PORCA DA RODA</p> <p>LAND ROVER FREELANDER 2 (L359) 2.0 Si4 4x4 (10.2011 - 10.2014) 177kw 241cv 1999cm3 Veículo todo-terreno fechado LAND ROVER FREELANDER 2 (L359) 2.0 Si4 4x4 (10.2011 - 10.2014) 177kw 241cv 1999cm3 Veículo todo-terreno fechado LAND ROVER FREELANDER 2 (L359) 2.2 SD4 4x4 (08.2010 - 10.2014) 140kw 190cv 2179cm3 Veículo todo-terreno fechado LAND ROVER FREELANDER 2 (L359) 2.2 SD4...</p> <p>d28x34mm M14x32mm</p>		<p><b>UPCR5020</b> NO. LR001381 - LR043267</p> <p>PORCA DA RODA</p> <p>LAND ROVER RANGE ROVER EVOQUE (L538) 2.0 4x4 (09.2011 - 12.2019) 176kw 240cv 1999cm3 SUV LAND ROVER RANGE ROVER EVOQUE (L538) 2.0 4x4 (09.2011 - 12.2019) 176kw 240cv 1999cm3 SUV LAND ROVER RANGE ROVER EVOQUE (L538) 2.0 4x4 (06.2011 - 12.2019) 177kw 241cv 1999cm3 SUV LAND ROVER RANGE ROVER EVOQUE (L538) 2.0 4x4 (06.2011 - 12.2019) 177kw 241cv 1999cm3 SUV LAND ROVER RANGE ROVE...</p> <p>d28x34mm M14x32mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p>KIT TAMPÃO BLOCO DO MOTOR</p> <p>MERCEDES-BENZ 123 Coupé (C123) 230 CE (123.243) (04.1980 -12.1985) 100kw 136cv 2299cm3 Coupé</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p>KIT TAMPÃO BLOCO DO MOTOR</p> <p>MERCEDES-BENZ 123 T-Model (S123) 200 T (11.1980 -11.1985) 80kw 109cv 1997cm3 Combi MERCEDES-BENZ 123 T-Model (S123) 200 T (123.280) (11.1980 -11.1985) 74kw 101cv 1997cm3 Combi MERCEDES-BENZ 123 T-Model (S123) 230 TE (123.283) (04.1980 -11.1985) 100kw 136cv 2299cm3 Combi</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>

	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ 123 três volumes (W123) 200 (06.1980 -11.1985) 74kw 101cv 1996cm3 três volumes  MERCEDES-BENZ 123 três volumes (W123) 200 (123.220) (06.1980 -11.1985) 80kw 109cv 1996cm3 três volumes</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ 124 Cabriolet (A124) 300 CE-24 (124.061) (04.1992 -06.1993) 162kw 220cv 2960cm3  Cabriolet MERCEDES-BENZ 124 Cabriolet (A124) 300 CE-24 (124.061) (04.1992 -06.1993) 170kw 231cv 2960cm3 Cabriolet</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ 124 Coupé (C124) 220 CE (124.042) (10.1992 -05.1993) 110kw 150cv 2199cm3 Coupé MERCEDES-BENZ 124 Coupé (C124) 230 CE (124.043) (03.1987 -12.1992) 97kw 132cv 2298cm3 Coupé MERCEDES-BENZ 124 Coupé (C124) 230 CE (124.043) (03.1987 -12.1992) 100kw 136cv 2298cm3 Coupé  MERCEDES-BENZ 124 Coupé (C124) 230 CE Cat (124.043) (06.1989 -12.1992) 97kw 132cv 2298cm3 Co...</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ 124 T-Model (S124) 200 T (124.080) (01.1986 -05.1990) 77kw 105cv 1996cm3 Combi MERCEDES-BENZ 124 T-Model (S124) 200 T (124.080) (09.1985 -08.1989) 80kw 109cv 1996cm3 Combi  MERCEDES-BENZ 124 T-Model (S124) 200 T D (124.180) (09.1985 -08.1991) 53kw 72cv 1997cm3 Combi MERCEDES-BENZ 124 T-Model (S124) 200 T D (124.180) (09.1988 -08.1991) 55kw 75cv 1997cm3 Combi MER...</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ 124 três volumes (W124) 200 (01.1986 -10.1992) 77kw 105cv 1996cm3 três volumes MERCEDES-BENZ 124 três volumes (W124) 200 (124.020) (01.1986 -05.1990) 75kw 102cv 1996cm3 três volumes MERCEDES-BENZ 124 três volumes (W124) 200 (124.020) (12.1985 -05.1990) 80kw 109cv 1996cm3 três volumes  MERCEDES-BENZ 124 três volumes (W124) 200 D (124.120) (12.1984 -08.1989)...</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ 190 (W201) 2.0 (201.022) (10.1982 -10.1984) 66kw 90cv 1996cm3 três volumes MERCEDES-BENZ 190 (W201) 2.0 (201.023) (01.1986 -05.1990) 75kw 102cv 1996cm3 três volumes  MERCEDES-BENZ 190 (W201) 2.0 (201.023) (08.1983 -05.1990) 77kw 105cv 1996cm3 três volumes MERCEDES-BENZ 190 (W201) D 2.0 (201.122) (08.1983 -08.1989) 53kw 72cv 1997cm3 três volumes  MERCEDES-BENZ...</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ A-CLASS (W169) A 160 CDI (169.006, 169.306) (09.2004 -06.2012) 60kw 82cv 1991cm3 Hatchback MERCEDES-BENZ A-CLASS (W169) A 180 CDI (169.007, 169.307) (09.2004 -06.2012) 80kw 109cv 1991cm3 Hatchback MERCEDES-BENZ A-CLASS (W169) A 200 CDI (169.008, 169.308) (09.2004 -06.2012) 103kw 140cv 1991cm3 Hatchback MERCEDES-BENZ A-CLASS (W169) A 200 CDI (169.308, 169.008) (...)</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ A-CLASS (W176) A 180 CDI (176.000) (06.2012 -10.2014) 80kw 109cv 1796cm3 Hatchback  MERCEDES-BENZ A-CLASS (W176) A 200 CDI (176.001) (06.2012 -10.2014) 100kw 136cv 1796cm3 Hatchback  MERCEDES-BENZ A-CLASS (W176) A 220 CDI (176.003) (09.2012 -05.2018) 125kw 170cv 2143cm3 Hatchback</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ B-CLASS Sports Tourer (W245) B 180 CDI (245.207) (03.2005 -11.2011) 80kw 109cv 1991cm3 Hatchback MERCEDES-BENZ B-CLASS Sports Tourer (W245) B 200 CDI (245.208) (03.2005 -11.2011) 100kw 136cv 1991cm3 Hatchback MERCEDES-BENZ B-CLASS Sports Tourer (W245) B 200 CDI (245.208) (03.2005 -11.2011) 103kw 140cv 1991cm3 Hatchback MERCEDES-BENZ B-CLASS Sports Tourer (W246,....)</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>ERCEDES-BENZ C-CLASS (W202) C 180 (202.018) (11.1994 -05.2000) 89kw 121cv 1799cm3 três volumes MERCEDES-BENZ C-CLASS (W202) C 180 (202.018) (03.1993 -05.2000) 90kw 122cv 1799cm3 três volumes  MERCEDES-BENZ C-CLASS (W202) C 200 (202.020) (01.1994 -05.2000) 100kw 136cv 1998cm3 três volumes MERCEDES-BENZ C-CLASS (W202) C 200 CDI (202.134) (03.1998 -05.2000) 75kw 102cv 2151cm3...</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ C-CLASS (W203) C 180 (203.035) (10.2000 -05.2002) 95kw 129cv 1998cm3 três volumes MERCEDES-BENZ C-CLASS (W203) C 180 Kompressor (203.046) (05.2002 -02.2007) 105kw 143cv 1796cm3 três volumes MERCEDES-BENZ C-CLASS (W203) C 200 CDI (203.004) (02.2001 -06.2003) 75kw 102cv 2148cm3 três volumes  MERCEDES-BENZ C-CLASS (W203) C 200 CDI (203.004) (09.2000 -06.2003) 85...</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ C-CLASS (W204) C 180 CDI (204.000) (04.2010 -03.2014) 88kw 120cv 2143cm3 três volumes MERCEDES-BENZ C-CLASS (W204) C 180 Kompressor (204.044, 204.045) (01.2008 -01.2014) 115kw 156cv 1597cm3 três volumes MERCEDES-BENZ C-CLASS (W204) C 180 Kompressor (204.046) (01.2007 -01.2014) 115kw 156cv 1796cm3 três volumes  MERCEDES-BENZ C-CLASS (W204) C 200 CDI (204.001) ...</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ C-CLASS Coupé (CL203) C 160 Kompressor (203.730) (05.2002 -05.2008) 90kw 122cv 1796cm3 Coupé  MERCEDES-BENZ C-CLASS Coupé (CL203) C 180 (203.735) (03.2001 -05.2002) 95kw 129cv 1998cm3 Coupé MERCEDES-BENZ C-CLASS Coupé (CL203) C 180 Kompressor (203.746) (05.2002 -05.2008) 105kw 143cv 1796cm3 Coupé MERCEDES-BENZ C-CLASS Coupé (CL203) C 200 CDI (203.707) (03...</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ C-CLASS T-Model (S202) C 180 T (202.078) (06.1996 -09.2000) 90kw 122cv 1799cm3 Combi MERCEDES-BENZ C-CLASS T-Model (S202) C 180 T (202.081) (09.2000 -03.2001) 95kw 129cv 1998cm3 Combi  MERCEDES-BENZ C-CLASS T-Model (S202) C 200 T (202.080) (06.1996 -03.2001) 100kw 136cv 1998cm3 Combi  MERCEDES-BENZ C-CLASS T-Model (S202) C 200 T CDI (202.194) (03.1998 -03.2001) 7...</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ C-CLASS T-Model (S203) C 180 (203.235) (03.2001 -05.2002) 95kw 129cv 1998cm3 Combi MERCEDES-BENZ C-CLASS T-Model (S203) C 180 Kompressor (203.246) (05.2002 -08.2007) 105kw 143cv 1796cm3 Combi  MERCEDES-BENZ C-CLASS T-Model (S203) C 200 CDI (203.204) (03.2001 -08.2007) 75kw 102cv 2148cm3 Combi  MERCEDES-BENZ C-CLASS T-Model (S203) C 200 CDI (203.204) (03.2001 -08...</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ C-CLASS T-Model (S204) C 180 CDI (204.200) (04.2010 -08.2014) 88kw 120cv 2143cm3 Combi MERCEDES-BENZ C-CLASS T-Model (S204) C 180 Kompressor (204.245) (01.2008 -08.2014) 115kw 156cv 1597cm3 Combi  MERCEDES-BENZ C-CLASS T-Model (S204) C 180 Kompressor (204.246) (08.2007 -08.2014) 115kw 156cv 1796cm3 Combi  MERCEDES-BENZ C-CLASS T-Model (S204) C 200 CDI (204.201) (...)</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>

	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ CLC-CLASS (CL203) CLC 160 (203.731) (02.2009 -06.2011) 95kw 129cv 1597cm3 Coupé MERCEDES-BENZ CLC-CLASS (CL203) CLC 180 Kompressor (203.746) (05.2008 -06.2011) 105 143 1796 Coupé MERCEDES-BENZ CLC-CLASS (CL203) CLC 200 CDI (203.707) (05.2008 -06.2011) 90kw 122cv 2148cm3 Coupé MERCEDES-BENZ CLC-CLASS (CL203) CLC 200 Kompressor (203.741) (05.2008 -06.2011) 135...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ CLK (C208) CLK 200 (208.335) (06.1997 -06.2002) 100kw 136cv 1998cm3 Coupé MERCEDES-BENZ CLK (C208) CLK 200 Kompressor (208.344) (06.2000 -06.2002) 120kw 163cv 1998cm3 Coupé MERCEDES-BENZ CLK (C208) CLK 200 Kompressor (208.345) (06.1997 -06.2000) 141kw 192cv 1998cm3 Coupé MERCEDES-BENZ CLK (C208) CLK 230 Kompressor (208.347) (06.1997 -06.2000) 142kw 193cv 229...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ CLK (C209) CLK 200 CGI (209.343) 07.2003 -05.2009) 125kw 170cv 1796cm3 Coupé MERCEDES-BENZ CLK (C209) CLK 200 Kompressor (209.341) 10.2006 -05.2009) 135kw 184cv 1796cm3 Coupé MERCEDES-BENZ CLK (C209) CLK 200 Kompressor (209.342) 09.2002 -05.2009) 120kw 163cv 1796cm3 Coupé MERCEDES-BENZ CLK (C209) CLK 220 CDI (209.308) 01.2005 -05.2009) 110kw 150cv 2148cm3 Co...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ CLK Cabriolet (A208) CLK 200 (208.435) (03.1998 -03.2002) 100kw 136cv 1998cm3 Cabriolet MERCEDES-BENZ CLK Cabriolet (A208) CLK 200 Kompressor (208.444) (06.2000 -03.2002) 120kw 163cv 1998cm3 Cabriolet MERCEDES-BENZ CLK Cabriolet (A208) CLK 200 Kompressor (208.445) (03.1998 -06.2000) 141kw 192cv 1998cm3 Cabriolet MERCEDES-BENZ CLK Cabriolet (A208) CLK 230 Kompre...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ CLS (C218) CLS 250 CDI / BlueTEC / d (218.303, 218.304) (04.2011-12.2017) 150kw 204cv 2143cm3 Coupé MERCEDES-BENZ CLS (C219) CLS 280 (219.354) (07.2008 -12.2010) 170kw 231cv 2996cm3 Coupé MERCEDES-BENZ CLS (C219) CLS 300 (219.354) (04.2009 -12.2010) 170kw 231cv 2996cm3 Coupé MERCEDES-BENZ CLS (C219) CLS 350 (219.356) (10.2004 -12.2010) 200kw 272cv 3498cm3 Co...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ E-CLASS (W124) E 200 (124.019) (06.1993 -06.1995) 100kw 136cv 1998cm3 três volumes MERCEDES-BENZ E-CLASS (W124) E 200 D (124.120) (06.1993 -06.1995) 55kw 75cv 1997cm3 três volumes MERCEDES-BENZ E-CLASS (W124) E 220 (124.022) (06.1993 -06.1995) 110kw 150cv 2199cm3 três volumes MERCEDES-BENZ E-CLASS (W124) E 250 D (124.126, 124.129) (07.1993 -06.1995) 83kw 113...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ E-CLASS (W210) E 200 (210.035) (06.1995 -08.2000) 100kw 136cv 1998cm3 três volumes MERCEDES-BENZ E-CLASS (W210) E 200 CDI (210.007) (06.1998 -03.2002) 75kw 102cv 2151cm3 três volumes MERCEDES-BENZ E-CLASS (W210) E 200 CDI (210.007) (07.1999 -03.2002) 85kw 116cv 2148cm3 três volumes MERCEDES-BENZ E-CLASS (W210) E 200 D (210.003) (01.1996 -03.2002) 65kw 88cv 1...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ E-CLASS (W211) E 200 CDI (211.004) (07.2002 -12.2008) 75kw 102cv 2148cm3 três volumes MERCEDES-BENZ E-CLASS (W211) E 200 CDI (211.004) (07.2002 -12.2008) 90kw 122cv 2148cm3 três volumes MERCEDES-BENZ E-CLASS (W211) E 200 CDI (211.007) (04.2006 -12.2008) 100kw 136cv 2148cm3 três volumes MERCEDES-BENZ E-CLASS (W211) E 200 Kompressor (211.041) (04.2006 -12.2008...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ E-CLASS (W212) E 200 CDI / BlueTEC (212.005, 212.006) (01.2009 -12.2015) 100kw 136cv 2143cm3 três volumes MERCEDES-BENZ E-CLASS (W212) E 200 NGT (212.041) (03.2011 -12.2015) 120kw 163cv 1796cm3 três volumes MERCEDES-BENZ E-CLASS (W212) E 220 CDI (01.2009 -12.2015) 120kw 163cv 2143cm3 três volumes MERCEDES-BENZ E-CLASS (W212) E 220 CDI / BlueTEC (212.001, 212...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ E-CLASS Cabriolet (A124) E 200 (124.060) (06.1993 -03.1998) 100kw 136cv 1998cm3 Cabriolet MERCEDES-BENZ E-CLASS Cabriolet (A124) E 220 (124.062) (06.1993 -03.1998) 110kw 150cv 2199cm3 Cabriolet MERCEDES-BENZ E-CLASS Cabriolet (A124) E 320 (124.066) (06.1993 -03.1998) 162kw 220cv 3199cm3 Cabriolet MERCEDES-BENZ E-CLASS Cabriolet (A124) E 36 AMG (124.066) (05.199...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ E-CLASS Cabriolet (A207) E 220 CDI / BlueTEC / d (207.402, 207.401) (01.2010 -12.2016) 125kw 170cv 2143cm3 Cabriolet MERCEDES-BENZ E-CLASS Cabriolet (A207) E 250 CDI / BlueTEC / d (207.403, 207.404) (01.2010 -12.2016) 150kw 204cv 2143cm3 Cabriolet MERCEDES-BENZ E-CLASS Cabriolet (A207) E 350 CGI (207.457) (01.2010 -12.2014) 215kw 292cv 3498cm3 Cabriolet MERCEDE...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ E-CLASS Coupé (C124) E 200 (124.040) (06.1993 -06.1997) 100kw 136cv 1998cm3 Coupé MERCEDES-BENZ E-CLASS Coupé (C124) E 220 (124.042) (06.1993 -06.1997) 110kw 150cv 2199cm3 Coupé MERCEDES-BENZ E-CLASS Coupé (C124) E 320 (124.052) (06.1993 -06.1997) 162kw 220cv 3199cm3 Coupé MERCEDES-BENZ E-CLASS Coupé (C124) E 36 AMG (124.052) (05.1994 -06.1997) 200kw 272...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ E-CLASS T-Model (S124) E 200 T (124.079) (06.1993 -06.1996) 100kw 136cv 1998cm3 Combi MERCEDES-BENZ E-CLASS T-Model (S124) E 220 T (124.082) (06.1993 -06.1996) 110kw 150cv 2199cm3 Combi MERCEDES-BENZ E-CLASS T-Model (S124) E 250 TD (124.186) (06.1993 -06.1996) 83kw 113cv 2497cm3 Combi MERCEDES-BENZ E-CLASS T-Model (S124) E 250 Turbo D (06.1993 -06.1996) 93kw 12...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ E-CLASS T-Model (S210) E 200 T (210.235) (06.1996 -08.2000) 100kw 136cv 1998cm3 Combi MERCEDES-BENZ E-CLASS T-Model (S210) E 200 T Kompressor (210.245) (06.1997 -03.2003) 137kw 186cv 1998cm3 Combi MERCEDES-BENZ E-CLASS T-Model (S210) E 200 T Kompressor (210.248) (08.2000 -03.2003) 120kw 163cv 1998cm3 Combi MERCEDES-BENZ E-CLASS T-Model (S210) E 220 T CDI (210.2...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ E-CLASS T-Model (S211) 350 CGI (211.257) (05.2006 -07.2009) 215kw 292cv 3498cm3 Combi MERCEDES-BENZ E-CLASS T-Model (S211) E 200 CDI (211.207) (04.2006 -07.2009) 100kw 136cv 2148cm3 Combi MERCEDES-BENZ E-CLASS T-Model (S211) E 200 Kompressor (211.241) (04.2006 -07.2009) 135kw 184cv 1796cm3 Combi MERCEDES-BENZ E-CLASS T-Model (S211) E 200 T Kompressor (211.242) ...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ E-CLASS T-Model (S212) E 200 CDI / BlueTEC (212.205, 212.206) (11.2009-12.2016) 100kw 136cv 2143cm3 Combi MERCEDES-BENZ E-CLASS T-Model (S212) E 220 CDI (212.202) (08.2009 -08.2014) 120kw 163cv 2143cm3 Combi MERCEDES-BENZ E-CLASS T-Model (S212) E 220 CDI / BlueTEC (212.202, 212.201) (11.2009 -12.2016) 125kw 170cv 2143cm3 Combi MERCEDES-BENZ E-CLASS T-Model (S21...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>

	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ G-CLASS (W460) 230 G (460.2) (03.1979 -07.1993) 66kw 90cv 2307cm3 Veículo todoterreno fechado MERCEDES-BENZ G-CLASS (W460) 230 G (460.2) (02.1980 -07.1987) 75kw 102cv 2277cm3 Veículo todoterreno fechado MERCEDES-BENZ G-CLASS (W460) 230 GE (460.2) (05.1987 -08.1992) 90kw 122cv 2298cm3 Veículo todoterreno fechado MERCEDES-BENZ G-CLASS (W460) 230 GE (460.2) (04...)</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ G-CLASS (W461) 230 GE (461) (06.1993 -07.2000) 92kw 125cv 2298cm3 Veículo todoterreno fechado MERCEDES-BENZ G-CLASS (W461) 230 GE (461.238, 461.239) (09.1989 -07.1996) 90kw 122cv 2298cm3 Veículo todoterreno fechado MERCEDES-BENZ G-CLASS (W461) 250 GD (461) (02.1990 -05.1993) 68kw 92cv 2497cm3 Veículo todoterreno fechado MERCEDES-BENZ G-CLASS (W461) 290 GD/G ...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ G-CLASS (W463) 230 GE (463.224, 463.225) (06.1990 -06.1993) 93kw 126cv 2298cm3 Veículo todoterreno fechado MERCEDES-BENZ G-CLASS (W463) 250 GD (463.324, 463.325) (06.1990 -10.1992) 69kw 94cv 2497cm3 Veículo todoterreno fechado MERCEDES-BENZ G-CLASS (W463) 300 GD (463.327, 463.328) (09.1989 -08.1993) 83kw 113cv 2996cm3 Veículo todoterreno fechado MERCEDES-BEN...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ GL-CLASS (X164) GL 450 4-matic (164.871) (09.2006 -08.2012) 250kw 340cv 4663cm3 SUV MERCEDES-BENZ GL-CLASS (X164) GL 500 4-matic (164.886) (09.2006 -12.2012) 285kw 388cv 5461cm3 SUV</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ GLK-CLASS (X204) 200 CDI (204.901) (07.2010 -06.2015) 105kw 143cv 2143cm3 SUV MERCEDES-BENZ GLK-CLASS (X204) 220 CDI (204.902) (12.2008 -06.2015) 125kw 170cv 2143cm3 SUV MERCEDES-BENZ GLK-CLASS (X204) 220 CDI 4-matic (204.984) (12.2008 -06.2015) 120kw 163cv 2143cm3 SUV MERCEDES-BENZ GLK-CLASS (X204) 220 CDI 4-matic (204.984, 204.997) (12.2008 -06.2015) 125kw 17... </p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ M-CLASS (W163) ML 230 (163.136) (02.1998 -06.2005) 110kw 150cv 2295cm3 SUV MERCEDES-BENZ M-CLASS (W163) ML 270 CDI (163.113) (12.1999 -06.2005) 120kw 163cv 2685cm3 SUV MERCEDES-BENZ M-CLASS (W163) ML 320 (163.154) (02.1998 -08.2002) 160kw 218cv 3199cm3 SUV MERCEDES-BENZ M-CLASS (W163) ML 350 (02.2003 -06.2005) 173kw 235cv 3724cm3 SUV MERCEDES-BENZ M-CLASS (W163...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ R-CLASS (W251, V251) R 280 (251.054, 251.154) (01.2007 -12.2014) 170kw 231cv 2996cm3 Veículo multiuso MERCEDES-BENZ R-CLASS (W251, V251) R 300 (251.054, 251.154) (07.2009 -12.2014) 170kw 231cv 2996cm3 Veículo multiuso MERCEDES-BENZ R-CLASS (W251, V251) R 350 (251.056, 251.156) (01.2007 -12.2012) 200kw 272cv 3498cm3 Veículo multiuso MERCEDES-BENZ R-CLASS (W25...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ S-CLASS (W126) 260 SE (126.020) (09.1985 -06.1991) 118kw 160cv 2599cm3 três volumes MERCEDES-BENZ S-CLASS (W126) 260 SE (126.020) (09.1985 -06.1991) 122kw 166cv 2599cm3 três volumes MERCEDES-BENZ S-CLASS (W126) 300 SE, SEL (126.024, 126.025) (01.1986 -06.1991) 132kw 180cv 2960cm3 três volumes MERCEDES-BENZ S-CLASS (W126) 300 SE, SEL (126.024, 126.025) (09.19...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ S-CLASS (W140) 300 SE 2.8 (140.028) (01.1993 -10.1998) 145kw 197cv 2799cm3 três volumes MERCEDES-BENZ S-CLASS (W140) 300 SE, SEL/S320 (140.032, 140.033) (03.1991 -10.1998) 170kw 231cv 3199cm3 três volumes MERCEDES-BENZ S-CLASS (W140) 400 SE, SEL/S420 (140.042, 140.043) (02.1991 -10.1998) 210kw 286cv 4196cm3 três volumes MERCEDES-BENZ S-CLASS (W140) 500 SE, S...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ S-CLASS (W220) S 280 (220.063, 220.163) (10.1998 -08.2005) 150kw 204cv 2799cm3 três volumes MERCEDES-BENZ S-CLASS (W220) S 320 (220.065, 220.165) (10.1998 -08.2005) 165kw 224cv 3199cm3 três volumes MERCEDES-BENZ S-CLASS (W220) S 320 CDI (220.025, 220.125) (09.2002 -08.2005) 150kw 204cv 3222cm3 três volumes MERCEDES-BENZ S-CLASS (W220) S 320 CDI (220.026, 220...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ S-CLASS (W221) S 250 CDI (221.003, 221.103) (01.2011 -12.2013) 150kw 204cv 2143cm3 três volumes MERCEDES-BENZ S-CLASS (W221) S 280 (221.054) (08.2006 -12.2013) 170kw 231cv 2996cm3 três volumes MERCEDES-BENZ S-CLASS (W221) S 350 (221.056, 221.156) (10.2005 -12.2013) 200kw 272cv 3498cm3 três volumes MERCEDES-BENZ S-CLASS (W221) S 350 4-matic (221.087, 221.187)...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ S-CLASS Coupé (C126) 380 SEC (126.043) (10.1981 -07.1985) 150kw 204cv 3839cm3 Coupé MERCEDES-BENZ S-CLASS Coupé (C126) 420 SEC (126.046) (10.1985 -06.1991) 150kw 204cv 4196cm3 Coupé MERCEDES-BENZ S-CLASS Coupé (C126) 420 SEC (126.046) (10.1985 -12.1987) 160kw 218cv 4196cm3 Coupé MERCEDES-BENZ S-CLASS Coupé (C126) 420 SEC (126.046) (10.1985 -06.1991) 165kw...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ S-CLASS Coupé (C140) 500 SEC / CL 500 (140.070) (10.1992 -12.1999) 235kw 320cv 4973cm3 Coupé MERCEDES-BENZ S-CLASS Coupé (C140) SEC/CL 420 (140.063) (10.1994 -02.1999) 205kw 279cv 4196cm3 Coupé MERCEDES-BENZ S-CLASS Coupé (C140) SEC/CL 600 (140.076) (09.1992 -02.1999) 290kw 394cv 5987cm3 Coupé</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ S-CLASS Coupé (C215) CL 500 (215.375) (03.1999 -03.2006) 225kw 306cv 4966cm3 Coupé MERCEDES-BENZ S-CLASS Coupé (C215) CL 55 AMG (215.373) (10.1999 -03.2006) 265kw 360cv 5439cm3 Coupé MERCEDES-BENZ S-CLASS Coupé (C215) CL 55 AMG Kompressor (215.374) (06.2002 -03.2006) 368kw 500cv 5439cm3 Coupé MERCEDES-BENZ S-CLASS Coupé (C215) CL 600 (215.376) (09.2002 ...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ S-CLASS Coupé (C216) CL 500 (216.371) (06.2006 -12.2013) 285kw 388cv 5461cm3 Coupé MERCEDES-BENZ S-CLASS Coupé (C216) CL 500 4-matic (216.386) (02.2008 -12.2013) 285kw 388cv 5461cm3 Coupé MERCEDES-BENZ S-CLASS Coupé (C216) CL 600 (216.376) (05.2006 -12.2013) 380kw 517cv 5513cm3 Coupé</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ SL (R107) 300 SL (107.041) (09.1985 -08.1989) 132kw 180cv 2960cm3 Cabriolet MERCEDES-BENZ SL (R107) 300 SL (107.041) (09.1985 -08.1989) 138kw 188cv 2960cm3 Cabriolet MERCEDES-BENZ SL (R107) 380 SL (107.045) (09.1980 -08.1985) 150kw 204cv 3839cm3 Cabriolet MERCEDES-BENZ SL (R107) 380 SL (107.045) (09.1980 -08.1985) 160kw 218cv 3818cm3 Cabriolet MERCEDES-BENZ SL ...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>

	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ SL (R129) 280 (129.058) (08.1993 -10.2001) 142kw 193cv 2799cm3 Cabriolet MERCEDES-BENZ SL (R129) 280 (129.059) (05.1998 -10.2001) 150kw 204cv 2799cm3 Cabriolet MERCEDES-BENZ SL (R129) 300 SL (129.060) (03.1989 -08.1993) 140kw 190cv 2960cm3 Cabriolet MERCEDES-BENZ SL (R129) 300 SL-24 (129.061) (03.1989 -07.1993) 170kw 231cv 2960cm3 Cabriolet MERCEDES-BENZ SL (R1...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ SL (R230) 280 (230.454) (03.2008 -01.2012) 170kw 231cv 2996cm3 Cabriolet MERCEDES-BENZ SL (R230) 300 (230.454) (04.2009 -01.2012) 170kw 231cv 2996cm3 Cabriolet MERCEDES-BENZ SL (R230) 350 (230.456) (03.2006 -01.2012) 200kw 272cv 3498cm3 Cabriolet MERCEDES-BENZ SL (R230) 350 (230.458) (04.2008 -01.2012) 232kw 316cv 3498cm3 Cabriolet MERCEDES-BENZ SL (R230) 350 (...)</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ SL Coupé (C107) 380 SLC (107.025) (07.1980 -08.1981) 160kw 218cv 3818cm3 Coupé MERCEDES-BENZ SL Coupé (C107) 450 SLC 5.0 (107.026) (06.1978 -02.1980) 177kw 241cv 4973cm3 Coupé</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ SLK (R170) 200 (170.435) (09.1996 -03.2000) 100kw 136cv 1998cm3 Cabriolet MERCEDES-BENZ SLK (R170) 200 Kompressor (170.444) (03.2000 -04.2004) 120kw 163cv 1998cm3 Cabriolet MERCEDES-BENZ SLK (R170) 200 Kompressor (170.445) (10.1996 -03.2000) 141kw 192cv 1998cm3 Cabriolet MERCEDES-BENZ SLK (R170) 230 Kompressor (170.447) (09.1996 -03.2000) 142kw 193cv 2295cm3 Ca...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ SLK (R171) 200 Kompressor (171.442) (03.2004 -02.2011) 120kw 163cv 1796cm3 Cabriolet MERCEDES-BENZ SLK (R171) 200 Kompressor (171.445) (01.2008 -02.2011) 135kw 184cv 1796cm3 Cabriolet MERCEDES-BENZ SLK (R171) 280 (171.454) (01.2005 -02.2011) 170kw 231cv 2996cm3 Cabriolet MERCEDES-BENZ SLK (R171) 300 (171.454) (04.2009 -02.2011) 170kw 231cv 2996cm3 Cabriolet MER...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ SLK (R172) 250 CDI / d (172.403) (01.2012 -) 150kw 204cv 2143cm3 Cabriolet</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ SPRINTER 2-t Autocarro (B901, B902) 208 CDI (901.671, 902.671,902.672) (04.2000 -05.2006) 60kw 82cv 2148cm3 Autocarro MERCEDES-BENZ SPRINTER 2-t Autocarro (B901, B902) 208 D (901.371, 902.371,902.372) (02.1995 -04.2000) 58kw 79cv 2299cm3 Autocarro MERCEDES-BENZ SPRINTER 2-t Autocarro (B901, B902) 210 D (902.471, 902.472) (03.1997 -04.2000) 75kw 102cv 2874cm3 Au...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ SPRINTER 2-t Caixa (B901, B902) 208 CDI (901.661, 901.662, 902.661, 902.662) (04.2000 -05.2006) 60kw 82cv 2148cm3 Caixa MERCEDES-BENZ SPRINTER 2-t Caixa (B901, B902) 208 D (901.361, 901.362, 902.361, 902.362) (02.1995 -04.2000) 58kw 79cv 2299cm3 Caixa MERCEDES-BENZ SPRINTER 2-t Caixa (B901, B902) 208 D (901.361, 901.362, 902.361, 902.362) (10.1996 -04.2000) 60k...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ SPRINTER 2-t Camião de plataforma/chassis (B901, B902) 208 CDI (901.611, 901.612, 901.621, 902.611, 902.612,...) (04.2000 -05.2006) 60kw 82cv 2148cm3 Camião de plataforma/chassis MERCEDES-BENZ SPRINTER 2-t Camião de plataforma/chassis (B901, B902) 208 D (901.311, 901.312, 901.321, 902.311, 902.312,...) (01.1995 -04.2000) 58kw 79cv 2299cm3 Camião de plataforma/c...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ SPRINTER 3,5-t Autocarro (B906) 310 CDI (906.731, 906.733, 906.735) (03.2009 -12.2013) 70kw 95cv 2143cm3 Autocarro MERCEDES-BENZ SPRINTER 3,5-t Autocarro (B906) 311 CDI (906.731, 906.733, 906.735) (06.2006 -12.2009) 80kw 109cv 2148cm3 Autocarro MERCEDES-BENZ SPRINTER 3,5-t Autocarro (B906) 311 CDI 4x4 (906.731, 906.733, 906.735) (02.2008 -12.2009) 80kw 109cv 21...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ SPRINTER 3,5-t Caixa (B906) 309 CDI (906.631, 906.633, 906.635, 906.637) (06.2006 -12.2009) 65kw 88cv 2148cm3 Caixa MERCEDES-BENZ SPRINTER 3,5-t Caixa (B906) 310 CDI (906.631, 906.633, 906.635, 906.637) (03.2009 -) 70kw 95cv 2143cm3 Caixa MERCEDES-BENZ SPRINTER 3,5-t Caixa (B906) 311 CDI (906.631, 906.633, 906.635, 906.637) (06.2006 -12.2009) 80kw 109cv 2148cm3...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ V-CLASS (638/2) V 200 (638.214, 638.294) (02.1997 -07.2003) 95kw 129cv 1998cm3 Autocarro MERCEDES-BENZ V-CLASS (638/2) V 200 CDI (638.294) (03.1999 -07.2003) 75kw 102cv 2148cm3 Autocarro MERCEDES-BENZ V-CLASS (638/2) V 220 CDI (638.294) (03.1999 -07.2003) 90kw 122cv 2148cm3 MERCEDES-BENZ V-CLASS (638/2) V 230 (638.234, 638.294) (10.1996 -07.2003) 105kw 143cv 22...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ VARIO Caixa (B667, B670, B668) 512 D (667.351, 667.352, 667.353) (09.1996 -12.2010) 90kw 122cv 2874cm3 Caixa MERCEDES-BENZ VARIO Caixa (B667, B670, B668) 612 D (668.351, 668.352, 668.353) (09.1996 -12.2010) 90kw 122cv 2874cm3 Caixa MERCEDES-BENZ VARIO Caixa (B667, B670, B668) 812 D (670.351, 670.352, 670.353) (09.1996 -12.2010) 90 122 2874 Caixa MERCEDES-BENZ V...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ VIANO (W639) 3.2 (639.711, 639.811, 639.813) (09.2003 -) 140kw 190cv 3199cm3 Autocarro MERCEDES-BENZ VIANO (W639) 3.2 (639.713, 639.813, 639.815) (09.2003 -) 160kw 218cv 3199cm3 Autocarro MERCEDES-BENZ VIANO (W639) 3.7 (639.815) (06.2004 -) 170kw 231cv 3724cm3 Autocarro MERCEDES-BENZ VIANO (W639) CDI 2.0 (639.711, 639.713, 639.811, 639.813, 639.815) (09.2003 -)...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ VITO / MIXTO Caixa (W639) 109 CDI (639.601, 639.603, 639.605) (09.2003 -) 65kw 88cv 2148cm3 Caixa MERCEDES-BENZ VITO / MIXTO Caixa (W639) 109 CDI (639.601, 639.603, 639.605) (08.2006 -) 70kw 95cv 2148cm3 Caixa MERCEDES-BENZ VITO / MIXTO Caixa (W639) 110 CDI (639.601, 639.603, 639.605) (09.2010 -) 70kw 95cv 2143cm3 Caixa MERCEDES-BENZ VITO / MIXTO Caixa (W639) 1...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ VITO Autocarro (W638) 108 CDI 2.2 (638.194) (03.1999 -07.2003) 60kw 82cv 2148cm3 Autocarro MERCEDES-BENZ VITO Autocarro (W638) 108 D 2.3 (638.164) (02.1996 -07.2003) 58kw 79cv 2299cm3 Autocarro MERCEDES-BENZ VITO Autocarro (W638) 110 CDI 2.2 (638.194) (03.1999 -07.2003) 75kw 102cv 2148cm3 Autocarro MERCEDES-BENZ VITO Autocarro (W638) 110 TD 2.3 (638.174) (02.19...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>

	<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ VITO Autocarro (W639) 109 CDI (639.701) (09.2003 - 07.2003) 65kw 88cv 2148cm3 Autocarro MERCEDES-BENZ VITO Autocarro (W639) 109 CDI 4x4 (639.701) (09.2007 - 08.2014) 70kw 95cv 2148cm3 Autocarro MERCEDES-BENZ VITO Autocarro (W639) 110 CDI (639.701, 639.703, 639.705) (09.2010-08.2014) 70kw 95cv 2143cm3 Autocarro MERCEDES-BENZ VITO Autocarro (W639) 111 CDI (639.701, 639.70...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 05073837AA</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MERCEDES-BENZ VITO Caixa (W638) 108 CDI 2.2 (638.094) (03.1999 - 07.2003) 60kw 82cv 2148cm3 Caixa MERCEDES-BENZ VITO Caixa (W638) 108 D 2.3 (638.064, 638.068) (03.1997 - 07.2003) 58kw 79cv 2299cm3 Caixa MERCEDES-BENZ VITO Caixa (W638) 110 CDI 2.2 (638.094) (03.1999 - 07.2003) 75kw 102cv 2148cm3 Caixa MERCEDES-BENZ VITO Caixa (W638) 110 D 2.3 (638.074, 638.078) (03.1997 - 07.2003...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 00A 103 113 A</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>VW LT 28-35 II Autocarro (2DB, 2DE, 2DK) 2.3 (05.1996 - 07.2006) 105kw 143cv 2295cm3 Autocarr</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 00A 103 113 A</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>VW LT 28-46 II Caixa (2DA, 2DD, 2DH) 2.3 (05.1996 - 07.2006) 105kw 143cv 2295cm3 Caixa VW LT 28-46 II Camião de plataforma/chassis (2DC, 2DF, 2DG, 2DL 2.3 (06.1996 - 07.2006) 105kw 143cv 2295cm3 Camião de plataforma/chassis</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA 121 II (DB) 1.1 (11.1990 - 10.1993) 40kw 54cv 1138cm3 três volumes MAZDA 121 II (DB) 1.3 16V (DB3PA) (11.1990 - 03.1996) 39kw 53cv 1324cm3 três volumes MAZDA 121 II (DB) 1.3 i 16V (DB3PA) (11.1990 - 03.1996) 53kw 72cv 1324cm3 três volumes</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA 2 (DE_, DH_) 1.4 MZR-CD (01.2008 - 06.2015) 50kw 68cv 1399cm3 Hatchback MAZDA 2 (DE_, DH_) 1.5 (DE5FS) (07.2007 - 06.2015) 76kw 103cv 1498cm3 Hatchback MAZDA 2 (DE_, DH_) 1.5 MZR (DE5FS) (06.2011 - 06.2015) 75kw 102cv 1498cm3 Hatchback MAZDA 2 (DE_, DH_) 1.6 MZ-CD (10.2008 - 06.2015) 66kw 90cv 1560cm3 Hatchback MAZDA 2 (DE_, DH_) 1.6 MZ-CD (06.2011 - 06.2015) 70kw 95cv...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA 3 (BK) 1.6 (BK14) (10.2003 - 06.2009) 77kw 105cv 1598cm3 Hatchback MAZDA 3 (BK) 1.6 DI Turbo (06.2004 - 06.2009) 80kw 109cv 1560cm3 Hatchback MAZDA 3 (BK) 1.6 MZ-CD (06.2006 - 12.2009) 66kw 90cv 1560cm3 Hatchback MAZDA 3 (BK) 2.0 (BKEP) (10.2003 - 12.2009) 110kw 150cv 1999cm3 Hatchback MAZDA 3 (BK) 2.0 MZR-CD (BK14) (07.2006 - 06.2009) 105kw 143cv 1998cm3 Hatchback MAZ...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA 323 C V (BA) 1.3 16V (08.1994 - 09.1998) 54kw 73cv 1324cm3 Coupé MAZDA 323 C V (BA) 1.5 16V (BA11) (08.1994 - 09.1998) 65kw 88cv 1489cm3 Coupé MAZDA 323 C V (BA) 1.8 16V (BA8P) (08.1994 - 09.1998) 84kw 114cv 1840cm3 Coupé</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA 323 F IV (BG) 1.6 (BG6S, BG6P) (04.1991 - 04.1994) 66kw 90cv 1597cm3 Hatchback MAZDA 323 F IV (BG) 1.8 16V (BG8S, BG8P) (09.1989 - 03.1993) 103kw 140cv 1840cm3 Hatchback MAZDA 323 F IV (BG) 1.8 4WD (BG8R) (01.1991 - 04.1994) 76kw 103cv 1840cm3 Hatchback</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA 323 F V (BA) 1.5 16V (BA11) (07.1994 - 09.1998) 65kw 88cv 1489cm3 Hatchback MAZDA 323 F V (BA) 1.8 16V (BA8P) (08.1994 - 09.1998) 84kw 114cv 1840cm3 Hatchback</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA 323 F VI (BJ) 1.4 (BJ3P) (01.2001 - 05.2004) 53kw 72cv 1324cm3 Hatchback MAZDA 323 F VI (BJ) 1.5 16V (BJ5W) (09.1998 - 01.2001) 65kw 88cv 1498cm3 Hatchback MAZDA 323 F VI (BJ) 1.6 (BJ10M) (01.2001 - 05.2004) 70kw 95cv 1598cm3 Hatchback MAZDA 323 F VI (BJ) 1.6 (BJ10M) (01.2001 - 05.2004) 72kw 98cv 1598cm3 Hatchback MAZDA 323 F VI (BJ) 1.9 16V (BJ14) (09.1998 - 01.2001) ...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA 323 III (BF) 1.3 (BF103) (08.1985 - 05.1989) 44kw 60cv 1296cm3 três volumes MAZDA 323 III (BF) 1.4 (BF103) (04.1987 - 07.1989) 44kw 60cv 1324cm3 três volumes MAZDA 323 III (BF) 1.5 (BF105) (09.1987 - 10.1989) 54kw 73cv 1498cm3 três volumes MAZDA 323 III (BF) 1.5 (BF5S) (08.1985 - 05.1989) 55kw 75cv 1490cm3 três volumes MAZDA 323 III (BF) 1.5 i (BF5S) (08.1985 - 05....</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA 323 P V (BA) 1.3 16V (10.1996 - 09.1998) 54kw 73cv 1324cm3 Hatchback MAZDA 323 P V (BA) 1.5 16V (10.1996 - 09.1998) 65kw 88cv 1489cm3 Hatchback</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA 323 P V (BA) 2.0 D (10.1996 - 09.1998) 52kw 71cv 1998cm3 Hatchback MAZDA 323 S IV (BG) 1.3 (BG3P) (09.1989 - 06.1991) 49kw 67cv 1324cm3 três volumes MAZDA 323 S IV (BG) 1.3 16V (BG3P) (04.1991 - 07.1994) 54kw 73cv 1324cm3 três volumes MAZDA 323 S IV (BG) 1.6 (BG6S) (06.1989 - 03.1991) 64kw 87cv 1597cm3 três volumes MAZDA 323 S IV (BG) 1.6 (BG6S) (09.1989 - 06.1991) ...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA 323 S V (BA) 1.3 16V (08.1994 - 09.1998) 54kw 73cv 1324cm3 três volumes MAZDA 323 S V (BA) 1.5 16V (BA11) (08.1994 - 09.1998) 65kw 88cv 1489cm3 três volumes MAZDA 323 S V (BA) 1.7 TD (05.1994 - 09.1998) 60kw 82cv 1686cm3 três volumes MAZDA 323 S V (BA) 1.8 16V (BA11) (08.1994 - 09.1998) 84kw 114cv 1840cm3 três volumes MAZDA 323 S V (BA) 2.0 D (10.1996 - 09.1998) 52...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA 323 S VI (BJ) 1.3 (BJ3P) (01.2001 - 05.2004) 53kw 72cv 1324cm3 três volumes MAZDA 323 S VI (BJ) 1.3 16V (BJ3P) (09.1998 - 01.2001) 54kw 73cv 1324cm3 três volumes MAZDA 323 S VI (BJ) 1.5 16V (BJ5P) (09.1998 - 01.2001) 65kw 88cv 1498cm3 três volumes MAZDA 323 S VI (BJ) 1.6 (BJ10M) (01.2001 - 05.2004) 70kw 95cv 1598cm3 três volumes MAZDA 323 S VI (BJ) 1.6 (BJ10M) (01....</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>

 <p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA 6 Combi (GH) 1.8 MZR (02.2008 - 07.2013) 88kw 120cv 1798cm3 Combi MAZDA 6 Combi (GH) 2.0 MZR (GHEFW) (12.2007 - 07.2013) 108kw 147cv 1999cm3 Combi MAZDA 6 Combi (GH) 2.0 MZR (GHEFW) (01.2010 - 07.2013) 114kw 155cv 1999cm3 Combi MAZDA 6 Combi (GH) 2.0 MZR-CD (GH14) (12.2007 - 12.2010) 103kw 140cv 1998cm3 Combi MAZDA 6 Combi (GH) 2.2 D (GH10) (01.2010 - 07.2013) 95kw 129...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>	 <p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA 6 Hatchback (GG) 1.8 (08.2002 - 08.2007) 88kw 120cv 1798cm3 Hatchback MAZDA 6 Hatchback (GG) 2.0 (GEGE) (08.2002 - 08.2007) 104kw 141cv 1999cm3 Hatchback MAZDA 6 Hatchback (GG) 2.0 (GGES) (03.2005 - 08.2007) 108kw 147cv 1999cm3 Hatchback MAZDA 6 Hatchback (GG) 2.0 DI (GG14) (08.2002 - 08.2007) 89kw 121cv 1998cm3 Hatchback MAZDA 6 Hatchback (GG) 2.0 DI (GG14) (08.2002 - ...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
 <p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA 6 Station Wagon (GY) 1.8 (08.2002 - 08.2007) 88kw 120cv 1798cm3 Combi MAZDA 6 Station Wagon (GY) 2.0 (GYEW) (08.2002 - 08.2007) 104kw 141cv 1999cm3 Combi MAZDA 6 Station Wagon (GY) 2.0 (GYEW) (03.2005 - 08.2007) 108kw 147cv 1999cm3 Combi MAZDA 6 Station Wagon (GY) 2.0 DI (GY19) (08.2002 - 08.2007) 89kw 121cv 1998cm3 Combi MAZDA 6 Station Wagon (GY) 2.0 DI (GY19) (08.20... ..</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>	 <p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA 6 três volumes (GG) 1.8 (08.2002 - 08.2007) 88kw 120cv 1798cm3 três volumes MAZDA 6 três volumes (GG) 2.0 (GGEF) (06.2002 - 08.2007) 104kw 141cv 1999cm3 três volumes MAZDA 6 três volumes (GG) 2.0 (GGEF) (03.2005 - 08.2007) 108kw 147cv 1999cm3 três volumes MAZDA 6 três volumes (GG) 2.0 DI (GG14) (08.2002 - 08.2007) 89kw 121cv 1998cm3 três volumes MAZDA 6 três volumes (GG) 2.0 DI (GG14) (08.2002 - 08.2007) 89kw 121cv 1998cm3 três volumes MAZDA 6 três volumes (GG) 2.0 DI (GG14) (08.20... ..</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
 <p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA 626 II (GC) 1.6 (GC1061) (11.1982 - 06.1987) 59kw 80cv 1587cm3 três volumes MAZDA 626 II (GC) 2.0 (GC1) (10.1986 - 01.1990) 68kw 92cv 1998cm3 três volumes MAZDA 626 II (GC) 2.0 (GC10E1) (03.1983 - 09.1987) 74kw 101cv 1998cm3 três volumes MAZDA 626 II (GC) 2.0 (GC10E1) (01.1986 - 09.1987) 88kw 120cv 1998cm3 três volumes MAZDA 626 II (GC) 2.0 D (GC10F1) (01.1983 - 0... ..</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>	 <p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA 626 III (GD) 1.6 (GD106) (06.1987 - 05.1992) 60kw 82cv 1587cm3 três volumes MAZDA 626 III (GD) 1.8 (08.1989 - 05.1992) 69kw 94cv 1789cm3 três volumes MAZDA 626 III (GD) 1.8 (GD8P) (11.1987 - 05.1992) 65kw 88cv 1789cm3 três volumes MAZDA 626 III (GD) 2.0 (GDEP) (09.1987 - 10.1990) 66kw 90cv 1998cm3 três volumes MAZDA 626 III (GD) 2.0 12V (GDEP) (09.1987 - 05.1992) 7... ..</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
 <p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA 626 IV (GE) 1.8 i (05.1994 - 06.1997) 78kw 106cv 1840cm3 três volumes MAZDA 626 IV (GE) 1.8 i (GE8P) (08.1994 - 04.1997) 66kw 90cv 1840cm3 três volumes MAZDA 626 IV (GE) 1.8 i (GE8P) (08.1991 - 04.1997) 77kw 105cv 1840cm3 três volumes MAZDA 626 IV (GE) 2.0 D (05.1994 - 06.1997) 56kw 76cv 1998cm3 três volumes MAZDA 626 IV (GE) 2.0 D GLX Complex (GEFP) (10.1992 - 04... ..</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>	 <p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA 626 V (GF) 1.8 (GF8P) (12.1999 - 10.2002) 74kw 100cv 1840cm3 três volumes MAZDA 626 V (GF) 1.9 (12.1999 - 10.2002) 74kw 100cv 1840cm3 três volumes MAZDA 626 V (GF) 2.0 (GFER) (05.1997 - 10.2002) 85kw 115cv 1991cm3 três volumes MAZDA 626 V (GF) 2.0 (GFER) (04.1998 - 10.2002) 100kw 136cv 1991cm3 três volumes MAZDA 626 V Hatchback (GF) 1.8 (GF8P) (05.1997 - 12.1999) 6... ..</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
 <p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA 929 III (HC) 2.0 (HCEP) (06.1987 - 05.1989) 85kw 115cv 1998cm3 três volumes MAZDA 929 III (HC) 3.0 (HCSS) (06.1987 - 06.1991) 140kw 190cv 2954cm3 três volumes</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>	 <p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA B-SERIE (UF) 2.2 D (01.1985 - 11.1989) 46kw 63cv 2184cm3 Pick-up MAZDA B-SERIE (UF) 2.2 D (UFY0) (01.1985 - 03.1996) 47kw 64cv 2184cm3 Pick-up MAZDA B-SERIE (UF) 2.2 12V 4WD (UFY0) (01.1990 - 06.1999) 90kw 122 2606cm3 Pick-up MAZDA B-SERIE (UN) 2.2 (11.1999 - 08.2002) 68kw 92cv 2184cm3 Pick-up MAZDA B-SERIE (UN) 2.5 D (06.1999 - 11.2006) 57kw 78cv 2499cm3 Pick-up MAZDA... ..</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
 <p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA BT-50 Camião de plataforma/chassis (CD, UN) 2.5 CDVi(UNY0W3) (12.2006 -) 105kw 143cv 2500cm3 Camião de plataforma/chassis MAZDA BT-50 Pick-up (CD, UN) 2.5 MRZ-CD (UNY0W3) (08.2006 - 06.2013) 105kw 143cv 2499cm3 Pick-up</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>	 <p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA CX-3 (DK) 1.5 SKYACTIV-D (DK2WS, DK5FW) 02.2015 - 01.2018) 77kw 105cv 1499cm3 SUV MAZDA CX-3 (DK) 1.5 SKYACTIV-D AWD (DK4WS, DK5AW) 02.2015 - 01.2018) 77kw 105cv 1499cm3 SUV MAZDA CX-3 (DK) 2.0 SKYACTIV-G (DK5V, DK6W) 05.2015 -) 88kw 120cv 1998cm3 SUV MAZDA CX-3 (DK) 2.0 SKYACTIV-G AWD (DK4W7) 05.2015 -) 110kw 150cv 1998cm3 SUV</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
 <p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA CX-5 (KE, GH) 2.0 (KEEFW) (11.2011 - 02.2017) 121kw 165cv 1998cm3 SUV MAZDA CX-5 (KE, GH) 2.0 AWD (KEEAW) (11.2011 - 02.2017) 118kw 160cv 1998cm3 SUV MAZDA CX-5 (KE, GH) 2.2 D (04.2012 - 02.2017) 129kw 175cv 2191cm3 SUV MAZDA CX-5 (KE, GH) 2.2 D (KE2FW) (04.2012 - 02.2017) 110kw 150cv 2191cm3 SUV MAZDA CX-5 (KE, GH) 2.2 D AWD (KE102) (04.2012 - 02.2017) 129kw 175cv 219... ..</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>	 <p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA CX-7 (ER) 2.2 MZR-CD AWD (ER10A) (01.2012 - 03.2013) 120kw 163cv 2184cm3 SUV MAZDA CX-7 (ER) 2.2 MZR-CD AWD (ER10A) (07.2009 - 03.2013) 127kw 173cv 2184cm3 SUV MAZDA CX-7 (ER) 2.3 MZR DISI Turbo AWD (ER3P) (10.2007 - 08.2009) 190kw 258cv 2261cm3 SUV MAZDA CX-7 (ER) 2.3 MZR DISI Turbo AWD (ER3P) (06.2009 - 03.2013) 191kw 260cv 2261cm3 SUV</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
 <p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA CX-9 (TB) 3.5 (09.2006 - 12.2007) 193kw 263cv 3496cm3 SUV MAZDA CX-9 (TB) 3.5 AWD (01.2007 -) 193kw 263cc 3496cm3 SUV MAZDA CX-9 (TB) 3.7 (01.2007 -) 204kw 277cv 3726cm3 SUV MAZDA CX-9 (TB) 3.7 AWD (TB10A) (01.2007 -) 204kw 277cv 3726cm3 SUV</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>	 <p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA MX-3 (EC) 1.6 (05.1991 - 10.1993) 66kw 90cv 1597cm3 Coupé MAZDA MX-3 (EC) 1.6 i (11.1993 - 09.1998) 79kw 107cv 1597cm3 Coupé MAZDA MX-3 (EC) 1.6 i (11.1993 - 09.1998) 81kw 110cv 1598cm3 Coupé MAZDA MX-3 (EC) 1.8 i V6 (ECP5A) (01.1994 - 10.1997) 95kw 129cv 1845cm3 Coupé MAZDA MX-3 (EC) 1.8 i V6 (ECP5A) (01.1992 - 01.1994) 98kw 133cv 1845cm3 Coupé</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>

	<p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA MX-5 I (NA) 1.6 (NA6C) (01.1995 - 04.1998) 66kw 90cv 1598cm3 Cabriolet MAZDA MX-5 I (NA) 1.6 (NA6C) (05.1990 - 01.1994) 85kw 115cv 1597cm3 Cabriolet MAZDA MX-5 I (NA) 1.6 Turbo (09.1990 - 12.1992) 110kw 150cv 1597cm3 Cabriolet MAZDA MX-5 I (NA) 1.8 (NA8C) (01.1993 - 04.1998) 96kw 130cv 1840cm3 Cabriolet</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA MX-5 II (NB) 1.6 16V (NB6C) (05.1998 - 10.2005) 81kw 110cv 1597cm3 Cabriolet MAZDA MX-5 II (NB) 1.8 (NB8C) (01.1998 - 07.2002) 103kw 140cv 1839cm3 Cabriolet MAZDA MX-5 II (NB) 1.8 (NB8C) (08.2002 - 10.2005) 107kw 146cv 1839cm3 Cabriolet MAZDA MX-5 II (NB) 1.8 16V (NB8C) (11.2000 - 10.2005) 102kw 139cv 1840cm3 Cabriolet MAZDA MX-5 II (NB) 1.8 16V (NB8C) (05.1998 - 10.20...</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA MX-5 III (NC) 1.8 (NC18) (03.2005 - 12.2014) 93kw 126cv 1798cm3 Cabriolet MAZDA MX-5 III (NC) 2.0 (03.2005 - 12.2007) 127kw 173cv 1999cm3 Cabriolet MAZDA MX-5 III (NC) 2.0 (NC18) (07.2005 - 12.2014) 118kw 160cv 1999cm3 Cabriolet</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA MX-5 IV (ND) 1.5 (ND2E, ND5R) (06.2015 -) 96kw 131cv 1496cm3 Cabriolet MAZDA MX-5 IV (ND) 2.0 (ND2E) (06.2015 -) 118kw 160cv 1998cm3 Cabriolet</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA MX-5 RF Targa (ND) 1.5 (08.2017 -) 96kw 131cv 1496cm3 Targa MAZDA MX-5 RF Targa (ND) 2.0 (ND2E) (12.2016 -) 118kw 160cv 1998cm3 Targa</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA MX-6 (GD) 2.0 (09.1995 - 01.1997) 85kw 116cv 1991cm3 Coupé MAZDA MX-6 (GE) 2.0 (02.1992 - 02.1997) 85kw 115cv 1991cm3 Coupé MAZDA MX-6 (GE) 2.5 24V (02.1993 - 11.1995) 123kw 167cv 2497cm3 Coupé MAZDA MX-6 (GE) 2.5 24V (GE10L) (02.1992 - 09.1997) 121kw 165cv 2497cm3 Coupé MAZDA MX-6 (GE) 2.5 i 24V (GE20L) (08.1994 - 02.1997) 120kw 163cv 2497cm3 Coupé</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA RX-7 II (FC) 1.3 Turbo (FC3S, FC1031) (03.1989 - 12.1991) 147kw 200cv 1308cm3 Coupé MAZDA RX-7 III (FD) 1.3 Twin Turbo (FD3S, FD1031) (07.1992 - 08.2002) 176kw 239cv 1308cm3 Coupé</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA RX-8 (SE, FE) 1.3 (FE103, SE3P) (10.2003 - 06.2012) 141kw 192cv 1308cm3 Coupé MAZDA RX-8 (SE, FE) 1.3 (FE103, SE3P) (10.2003 - 06.2012) 170kw 231cv 1308cm3 Coupé</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA TRIBUTE (EP) 2.3 AWD (EP3W) (04.2004 - 05.2008) 110kw 150cv 2261cm3 SUV MAZDA TRIBUTE (EP) 3.0 V6 24V 4WD (EPFW) (03.2000 - 05.2008) 145kw 197cv 2967cm3 SUV MAZDA TRIBUTE (EP) 3.0 V6 AWD (EPFW) (04.2004 - 05.2008) 149kw 203cv 2967cm3 SUV</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. B001-37-160A - B002-37-160 - B001-37-160A - B002-37-160B</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MAZDA XEDOS 9 (TA) 2.0 24V (08.1993 - 01.2000) 105kw 143cv 1995cm3 três volumes MAZDA XEDOS 9 (TA) 2.3 24V (TA3P) (02.1995 - 01.2000) 155kw 211cv 2255cm3 três volumes MAZDA XEDOS 9 (TA) 2.5 24V (TA5P) (07.1993 - 07.2000) 123kw 167cv 2497cm3 três volumes MAZDA XEDOS 9 (TA) 2.5 V6 (TA5P) (07.2000 - 09.2002) 120kw 163cv 2497cm3 três volumes</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 3880A008 - 3880A009 - MB301590 - MR910032</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MITSUBISHI CARISMA (DA_) 1.6 (DA1A) (07.1995 - 06.2006) 66kw 90cv 1597cm3 Hatchback MITSUBISHI CARISMA (DA_) 1.6 (DA1A) (12.1998 - 06.2006) 70kw 95cv 1597cm3 Hatchback MITSUBISHI CARISMA (DA_) 1.6 (DA1A) (05.1997 - 06.2006) 73kw 99cv 1597cm3 Hatchback MITSUBISHI CARISMA (DA_) 1.9 TD (DA4A) (10.1996 - 09.2000) 66kw 90cv 1870 Hatchback MITSUBISHI CARISMA três volumes (DA_) 1.6 (D...</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 3880A008 - 3880A009 - MB301590 - MR910032</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MITSUBISHI COLT VI (Z3_A, Z2_A) 1.1 LPG 10.2004 - 06.2012) 55kw 75cv 1124 Hatchback MITSUBISHI COLT VI (Z3_A, Z2_A) 1.3 (Z21A) 06.2004 - 06.2012) 70kw 95cv 1332 Hatchback MITSUBISHI COLT VI (Z3_A, Z2_A) 1.3 Flexfuel (Z35A) 10.2008 - 06.2012) 70kw 95cv 1332 Hatchback MITSUBISHI COLT VI (Z3_A, Z2_A) 1.3 LPG (Z33A) 06.2004 - 06.2012) 70kw 95cv 1332cm3 Hatchback MITSUBISHI COLT VI (...)</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 3880A008 - 3880A009 - MB301590 - MR910032</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MITSUBISHI GRANDIS (NA_W) 2.0 Di-D (NA8W) (09.2005 - 03.2010) 100kw 136cv 1968cm3 Veículo multiuso MITSUBISHI GRANDIS (NA_W) 2.0 Di-D (NA8W) (02.2007 - 03.2010) 103kw 140cv 1968cm3 Veículo multiuso MITSUBISHI GRANDIS (NA_W) 2.4 MIVEC (NA4W) (04.2004 - 12.2011) 121kw 165cv 2378cm3 Veículo multiuso MITSUBISHI GRANDIS (NA_W) 2.4 MIVEC (NA4W) (04.2004 - 12.2011) 121kw 165cv 2378cm3...</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 3880A008 - 3880A009 - MB301590 - MR910032</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MITSUBISHI L 300 III Autocarro (P0_W, P1_W, P2_W, P3_W) 2.0 4WD (P23W, P03W, P13W) (12.1986 - 05.2004) 65kw 88cv 1997cm3 Autocarro MITSUBISHI L 300 III Autocarro (P0_W, P1_W, P2_W, P3_W) 2.0 4WD (P23W, P03W, P13W) (11.1986 - 05.2004) 66kw 90cv 1997cm3 Autocarro MITSUBISHI L 300 III Autocarro (P0_W, P1_W, P2_W, P3_W) 2.4 4WD (P24W) (11.1986 - 12.1990) 80kw 109cv 2351cm3 Autocar...</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 3880A008 - 3880A009 - MB301590 - MR910032</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MITSUBISHI L200 / TRITON (KA_T, KB_T) 2.5 Di-D (KA4T) 04.2010 - 12.2015) 94kw 128cv 2477cm3 Pick-up MITSUBISHI L200 / TRITON (KA_T, KB_T) 2.5 Di-D (KA4T) 11.2005 - 12.2015) 100kw 136cv 2477cm3 Pick-up MITSUBISHI L200 / TRITON (KA_T, KB_T) 2.5 Di-D (KA4T) 08.2007 - 12.2015) 123kw 167cv 2477cm3 Pick-up MITSUBISHI L200 / TRITON (KA_T, KB_T) 2.5 Di-D 4WD (KB4T) 11.2005 - 12.2015) 10...</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 3880A008 - 3880A009 - MB301590 - MR910032</p> <p><i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MITSUBISHI LANCER VII (CS_A, CT_A) EVO IX (CT9A) (01.2005 - 09.2007) 206kw 280cv 1997cm3 três volumes MITSUBISHI LANCER VII (CS_A, CT_A) EVO IX (CT9A) (08.2005 - 09.2006) 213kw 290cv 1997cm3 três volumes MITSUBISHI LANCER VII (CS_A, CT_A) EVO VIII (CT9A) (04.2003 - 03.2005) 206kw 280cv 1997cm3 três volumes MITSUBISHI LANCER VII (CS_A, CT_A) EVO VIII - 260 (CT9A) (03.2004 - 07...</p> <p>d46x14mm      M38x1,5mm 1f-20mm</p>










	<p><b>KMB84057</b> NO. 3880A008 - 3880A009 - MB301590 - MR910032 <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>mitsubishi LANCER VIII (CY_A, CZ_A) 1.6 MIVEC (05.2010 -) 86kw 117cv 1590cm3 três volumes MITSUBISHI LANCER VIII (CY_A, CZ_A) 2.0 i 4WD (CZ4A) (03.2007 -) 113kw 154cv 1998cm3 três volumes MITSUBISHI LANCER VIII (CY_A, CZ_A) EVO X (CZ4A) (06.2008 -12.2015) 217kw 295cv 1998cm3 três volumes</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 3880A008 - 3880A009 - MB301590 - MR910032 <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MITSUBISHI MIRAGE / SPACE STAR VI Hatchback (A0_A) 1.2 (A03A) (01.2012 -) 57kw 78cv 1193cm3 Hatchback MITSUBISHI MIRAGE / SPACE STAR VI Hatchback (A0_A) 1.2 (A03A) (10.2012 -) 59kw 80cv 1193cm3 Hatchback MITSUBISHI MIRAGE VI três volumes (A1_A) 1.2 (A13A) (10.2013 -) 59kw 80cv 1193cm3 três volumes</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 3880A008 - 3880A009 - MB301590 - MR910032 <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MITSUBISHI OUTLANDER I (CU_W) 2.0 (CU2W) (05.2003 -10.2006) 100kw 136cv 1997cm3 SUV MITSUBISHI OUTLANDER I (CU_W) 2.0 4WD (CU2W) (05.2003 -10.2006) 100kw 136cv 1997cm3 SUV MITSUBISHI OUTLANDER I (CU_W) 2.0 Turbo 4WD (CU2W) (04.2004 -10.2006) 148kw 201cv 1997cm3 SUV MITSUBISHI OUTLANDER I (CU_W) 2.0 Turbo-R 4WD (CU2W) (01.2002 -10.2006) 177kw 241cv 1997cm3 SUV MITSUBISHI OUTL...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 3880A008 - 3880A009 - MB301590 - MR910032 <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MITSUBISHI PAJERO I (L04_G, L14_G) 2.3 TD (L043G, L048G) 12.1982 -04.1986 62kw 84cv 2346cm3 Veículo todo-terreno fechado MITSUBISHI PAJERO I (L04_G, L14_G) 2.5 TD (L044G, L049G) 04.1987 -12.1991 64kw 87cv 2477cm3 Veículo todo-terreno fechado MITSUBISHI PAJERO I (L04_G, L14_G) 2.5 TD (L044G, L049G) 11.1989 -11.1990 70kw 95cv 2477cm3 Veículo todo-terreno fechado MITSUBISHI ...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 3880A008 - 3880A009 - MB301590 - MR910032 <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MITSUBISHI PAJERO II (V3_W, V2_W, V4_W) 2.5 TD 4WD (V24C, V24W) (12.1990 -10.1999) 73kw 99cv 2477cm3 Veículo todo-terreno fechado MITSUBISHI PAJERO II (V3_W, V2_W, V4_W) 2.5 TDiC (V44W, V24W) (03.1991 -08.1999) 73kw 99cv 2477cm3 Veículo todo-terreno fechado MITSUBISHI PAJERO II Canvas Top (V2_W, V4_W) 2.5 TD 4WD (V24C, V24W) (12.1990 -04.2000) 73kw 99cv 2477cm3 Veículo to...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 3880A008 - 3880A009 - MB301590 - MR910032 <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MITSUBISHI PAJERO III (V7_W, V6_W) 2.5 TDi (V64W) (04.2000 -12.2006) 73kw 99cv 2477cm3 Veículo todo-terreno fechado MITSUBISHI PAJERO III (V7_W, V6_W) 2.5 TDi (V64W, V74W) (09.2001 -12.2006) 85kw 115cv 2477cm3 Veículo todo-terreno fechado MITSUBISHI PAJERO III (V7_W, V6_W) 3.2 Di-D (V68W) (04.2000 -12.2006) 118kw 160cv 3200cm3 Veículo todo-terreno fechado MITSUBISHI PAJER...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 3880A008 - 3880A009 - MB301590 - MR910032 <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MITSUBISHI PAJERO IV (V8_W, V9_W) 3.5 V6 4WD (09.2009 -) 139kw 189cv 3497cm3 SUV MITSUBISHI PAJERO IV (V8_W, V9_W) 3.5 V6 4WD (09.2009 -) 139kw 189cv 3497cm3 SUV</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 3880A008 - 3880A009 - MB301590 - MR910032 <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MITSUBISHI SPACE STAR Veículo multiuso (DG_A) 1.3 16V (DG1A) (09.2000 -12.2004) 60kw 82cv 1299cm3 Veículo multiuso MITSUBISHI SPACE STAR Veículo multiuso (DG_A) 1.3 16V (DG1A) (12.1998 -12.2004) 61kw 83cv 1299cm3 Veículo multiuso MITSUBISHI SPACE STAR Veículo multiuso (DG_A) 1.3 16V (DG1A) (06.1998 -12.2004) 63kw 86cv 1299cm3 Veículo multiuso MITSUBISHI SPACE STAR Veí...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 3880A008 - 3880A009 - MB301590 - MR910032 <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>MITSUBISHI SPORT WAGON I (K7_, K9_) 2.5 TD (K94W) (11.1998 -) 73kw 99cv 2477cm3 Veículo todo-terreno fechado MITSUBISHI SPORT WAGON I (K7_, K9_) 2.5 TD (K94W) (08.2003 -) 98kw 133cv 2477cm3 Veículo todo-terreno fechado MITSUBISHI SPORT WAGON I (K7_, K9_) 2.5 TD (K94W, K74T) (07.2002 -) 85kw 115cv 2477cm3 Veículo todo-terreno fechado</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104 <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>TOYOTA 4 RUNNER IV (_N21_) 4.0 (GRN210) (11.2002 -07.2009) 183kw 249cv 3956cm3 SUV TOYOTA 4 RUNNER IV (_N21_) 4.0 4WD (GRN215) (01.2003 -12.2009) 183kw 249cv 3956cm3 SUV TOYOTA 4 RUNNER IV (_N21_) 4.7 4WD (UZN215_) (08.2002 -09.2006) 175kw 238cv 4663cm3 SUV</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104 <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>TOYOTA AURIS (_E15_) 1.8 (ZRE152_) (02.2009 -09.2012) 108kw 147cv 1798cm3 Hatchback</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104 <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>TOYOTA AVENSIS (_T22_) 1.6 VVT-i (ZZT220_) 10.2000 -02.2003) 81kw 110cv 1598cm3 três volumes TOYOTA AVENSIS (_T22_) 1.6 i (AT220_) 09.1997 -10.2000) 74kw 101cv 1587cm3 três volumes TOYOTA AVENSIS (_T22_) 1.6 i (AT220_) 10.1997 -06.2000) 81kw 110cv 1587cm3 três volumes TOYOTA AVENSIS (_T22_) 1.8 VVT-i (ZZT221_) 10.2000 -02.2003) 95kw 129cv 1794cm3 três volumes TOYOTA AVEN...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104 <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>TOYOTA CAMRY (_V1_) 2.2 (SXV10_) (06.1991 -07.1996) 100kw 136cv 2164cm3 três volumes TOYOTA CAMRY (_V2_) 2.0 4WD (SV25_) (08.1988 -05.1991) 94kw 128cv 1998cm3 três volumes TOYOTA CAMRY (_V2_) 2.2 (SXV20) (08.1997 -09.2002) 93kw 126cv 2164cm3 três volumes TOYOTA CAMRY (_V2_) 2.2 (SXV20_) (08.1996 -11.2001) 96kw 131cv 2164cm3 três volumes TOYOTA CAMRY (_V2_) 3.0 24V (MCV20)...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104 <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>TOYOTA CARINA E VI (_T19_) 1.6 (AT190) (12.1993 -09.1997) 73kw 99cv 1587cm3 Hatchback TOYOTA CARINA E VI (_T19_) 1.6 (AT190) (12.1993 -09.1997) 85kw 116cv 1587cm3 Hatchback TOYOTA CARINA E VI (_T19_) 1.6 16V (AT190_) (10.1995 -09.1997) 78kw 106cv 1587cm3 Hatchback TOYOTA CARINA E VI (_T19_) 1.6 GLI (AT190) (04.1992 -09.1997) 79kw 107cv 1587cm3 Hatchback TOYOTA CARINA E VI (...)</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104 <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>TOYOTA CARINA I (TA1_) 1.6 (TA12_, TA14_) (12.1970 -03.1978) 58kw 79cv 1588cm3 três volumes TOYOTA CARINA I (TA1_) 1.6 (TA14_) (02.1976 -03.1978) 55kw 75cv 1588cm3 três volumes TOYOTA CARINA I (TA1_) 1.6 (TA14_) (10.1975 -03.1978) 63kw 86cv 1588cm3 três volumes</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104 <i>KIT TAMPÃO BLOCO DO MOTOR</i></p> <p>TOYOTA CARINA II (TA4_, TA6_) 1.6 (TA40, TA60) (01.1978 -09.1983) 55kw 75cv 1588cm3 três volumes TOYOTA CARINA II (TA4_, TA6_) 1.6 (TA40_) (08.1977 -07.1981) 63kw 86cv 1588cm3 três volumes TOYOTA CARINA II (TA4_, TA6_) 1.8 (TA62_) (01.1978 -05.1983) 57kw 78cv 1770cm3 três volumes TOYOTA CARINA II (TA4_, TA6_) 1.8 (TA62_) (01.1982 -09.1983) 63kw 86cv 1770cm3 três volumes ...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>

	<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA CARINA III Combi (_A6_) 1.6 (TA60_) (03.1981 -01.1982) 54kw 73cv 1588cm3 Combi TOYOTA CARINA III Combi (_A6_) 1.6 (TA60_) (08.1981 -09.1983) 55kw 75cv 1588cm3 Combi TOYOTA CARINA III Combi (_A6_) 1.8 (TA62_) (08.1982 -12.1982) 57kw 78cv 1770cm3 Combi TOYOTA CARINA III Combi (_A6_) 1.8 D (CA60, CA67) (04.1982 -09.1983) 48kw 65cv 1839cm3 Combi</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA CELICA (_A4_) 1.6 ST (TA40_) (08.1977 -07.1981) 63kw 86cv 1588cm3 Hatchback TOYOTA CELICA (_A4_) 2.0 GT (RA40_, RA40) (08.1977 -07.1981) 90kw 122cv 1968cm3 Hatchback TOYOTA CELICA (_A4_) 2.0 XT (RA40) (01.1980 -07.1981) 65kw 88cv 1968cm3 Hatchback TOYOTA CELICA (_A4_) 2.0 XT (RA40) (08.1977 -07.1981) 66kw 90cv 1968cm3 Hatchback TOYOTA CELICA (_A6_) 2.0 XT (RA61) (02.1...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA COROLLA (KE_, TE_) 1.2 (KE20, KE25, KE30) (08.1974 -12.1980) 40kw 54cv 1166cm3 três volumes TOYOTA COROLLA (KE_, TE_) 1.2 (KE30_, KE20, KE25) (10.1972 -07.1979) 43kw 58cv 1166cm3 três volumes TOYOTA COROLLA (_E10_) 1.3 XLI (EE101_) (09.1995 -04.1997) 55kw 75cv 1332cm3 três volumes TOYOTA COROLLA (_E10_) 1.3 XLI 16V (EE101) (07.1992 -09.1995) 65kw 88cv 1332cm3 três...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA CORONA (RT1_) 2.0 (RT104) (01.1976 -05.1979) 65kw 88cv 1968cm3 três volumes TOYOTA CORONA (_T1_) 1.8 (TT1_) (10.1979 -01.1981) 63kw 86cv 1770cm3 três volumes TOYOTA CORONA Combi (RT118) 2.0 (RT118) (09.1975 -05.1979) 65kw 88cv 1968cm3 Combi TOYOTA CORONA CELICA (_A4_) 2.0 XT (RA40) (08.1977 -07.1981) (11.1989 -02.1992) 85kw 116cv 1838cm3 três volumes TOYOTA CORONA ...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA CRESSIDA Station Wagon (_X3_) 2.0 (RX35) (12.1977 -03.1981) 66kw 90cv 1968cm3 Combi TOYOTA CRESSIDA Station Wagon (_X3_) 2.0 (RX35_) (12.1977 -03.1981) 65kw 88cv 1968cm3 Combi TOYOTA CRESSIDA Station Wagon (_X6_) 2.0 (RX60_) (02.1981 -03.1985) 77kw 105cv 1972cm3 Combi TOYOTA CRESSIDA Station Wagon (_X6_) 2.2 D (LX60_) (09.1980 -04.1985) 49kw 67cv 2173cm3 Combi TOYOTA ...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA ECHO três volumes (_P1_) 1.5 (NCP12_) (08.1999 -12.2005) 81kw 110cv 1497cm3 três volumes</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA FJ CRUISER (GSJ1_) 4.0 4WD (GSJ15_) (01.2006 -01.2018) 178kw 242cv 3956cm3 SUV</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA HIACE II Autocarro (_H11_, _H2_, _H3_, _H4_) 1.6 (RH20, RH30) (02.1977 -11.1982) 49kw 67cv 1588cm3 Autocarro TOYOTA HIACE II Autocarro (_H11_, _H2_, _H3_, _H4_) 2.2 D (LH20, LH30) (09.1979-10.1982) 49kw 67cv 2188cm3 Autocarro TOYOTA HIACE II Caixa (_H11_, _H2_, _H3_, _H4_) 1.6 (RH30) (02.1977 -03.1983) 49kw 67cv 1588cm3 Caixa TOYOTA HIACE II Caixa (_H11_, _H2_, _H3_, _H4_)...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA HIACE III Autocarro (_H5_, _H6_, _H7_, _H8_, _H9_) 1.8 (YH50, YH60) (03.1983 - 07.1989) 58kw 79cv 1812cm3 Autocarro TOYOTA HIACE III Autocarro (_H5_, _H6_, _H7_, _H8_, _H9_) 2.2 D (LH50, LH60) (12.1982 -11.1989) 49kw 67cv 2188cm3 Autocarro TOYOTA HIACE III Autocarro (_H5_, _H6_, _H7_, _H8_, _H9_) 2.4 D (LH51, LH61, LH66) (04.1984 -08.1989) 55kw 75cv 2446cm3 Autocarro TOY...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA HIACE IV Autocarro (_H1_) 2.4 D (LH100, LH110, LH104, LH114) (08.1989 -12.2004) 57kw 78cv 2446cm3 Autocarro</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA HILUX III Pick-up (_N3_, _N4_) 2.2 D (LN40, LN30) (01.1979 -07.1983) 49kw 67cv 2188cm3 Pick-up</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA HILUX IV Pick-up (_N5_, _N6_) 2.0 (YN57, YN60) 08.1983 -07.1988) 58kw 88cv 1998cm3 Pick-up TOYOTA HILUX IV Pick-up (_N5_, _N6_) 2.2 D (LN50, LN55) 08.1983 -08.1984) 49kw 67cv 2188cm3 Pick-up TOYOTA HILUX IV Pick-up (_N5_, _N6_) 2.4 D (LN51_, LN56) 09.1984 -07.1988) 55kw 75cv 2446cm3 Pick-up TOYOTA HILUX IV Pick-up (_N5_, _N6_) 2.4 D (LN51_, LN60_, LN56) 01.1984 -07.19...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA HILUX V Pick-up (_N_, KZN1_, VZN1_) 1.8 (YN85, YN90) (09.1988 -06.1998) 61kw 83cv 1812cm3 Pick-up TOYOTA HILUX V Pick-up (_N_, KZN1_, VZN1_) 2.4 D (LN5_, LN85, LN90) (10.1988 -07.1997) 55kw 75cv 2446cm3 Pick-up TOYOTA HILUX V Pick-up (_N_, KZN1_, VZN1_) 2.4 D (LN85, LN90) (10.1991 -07.1997) 59kw 80cv 2446cm3 Pick-up TOYOTA HILUX V Pick-up (_N_, KZN1_, VZN1_) 2.4 D (LN...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA HILUX VI Pick-up (_N1_) 2.4 D (LN145, LN150) (08.1997 -07.2005) 58kw 79 2446 Pick-up TOYOTA HILUX VI Pick-up (_N1_) 2.4 D (LN150, LN145) (08.1997 -04.2005) 55kw 75 2446 Pick-up TOYOTA HILUX VI Pick-up (_N1_) 2.4 4WD (RZN14_, RZN16_, RZN19_) (08.1997 -10.2005) 103kw 140cv 2438cm3 Pick-up TOYOTA HILUX VI Pick-up (_N1_) 2.5 D-4D (KDN145, KDN150) (11.2001 -07.2005) 65kw...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA HILUX VII Pick-up (_N1_, _N2_, _N3_) 2.5 D 4WD (KUN25) (03.2005 -05.2015) 75kw 102cv 2494cm3 Pick-up TOYOTA HILUX VII Pick-up (_N1_, _N2_, _N3_) 2.5 D-4D (KUN115) (08.2005 -10.2006) 65kw 88cv 2494cm3 Pick-up TOYOTA HILUX VII Pick-up (_N1_, _N2_, _N3_) 2.5 D-4D (KUN15, KUN35) (01.2010 -05.2015) 106kw 144cv 2494cm3 Pick-up TOYOTA HILUX VII Pick-up (_N1_, _N2_, _N3_) 2.5 ...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA HILUX VIII Pick-up (_N1_) 2.4 D (GUN112_, GUN122_, GUN135_, GUN120_) (05.2015 -) 110kw 150cv 2393cm3 Pick-up TOYOTA HILUX VIII Pick-up (_N1_) 2.4 D (GUN135) (10.2018 -) 125kw 170cv 2393cm3 Pick-up TOYOTA HILUX VIII Pick-up (_N1_) 2.4 D 4WD (GUN125) (10.2018 -) 125kw 170cv 2393cm3 Pick-up TOYOTA HILUX VIII Pick-up (_N1_) 2.4 D 4WD (GUN125_) (05.2015 -) 110kw 150cv 2393c...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>

	<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA LAND CRUISER (_J7_) 2.4 TD (LJ70) (01.1990 -05.1993) 66kw 90cv 2446cm3 Veículo todo-terreno fechado TOYOTA LAND CRUISER (_J7_) 2.4 TD (LJ70_, LJ73_, LJ70RV) (10.1985 -05.1990) 63kw 86cv 2446cm3 Veículo todo-terreno fechado TOYOTA LAND CRUISER (_J7_) 3.0 TD (KZJ70_, KZJ73_, KZJ77_, KZJ78) (05.1993 -05.1996) 92kw 125cv 2982cm3 Veículo todo-terreno fechado TOYOTA LAND...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA LAND CRUISER Hardtop (_J7_) 3.0 TD (KZJ70_) (05.1993 -05.1996) 92kw 125cv 2982cm3 Veículo todo terreno aberto TOYOTA LAND CRUISER Hardtop (_J7_) 4.2 D (HZJ70, HZJ73) (01.1990 -08.2001) 123kw 167cv 4164cm3 Veículo todo terreno aberto</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA LAND CRUISER PRADO (_J12_) 3.0 D-4D (KDJ120, KDJ125) (09.2002 -08.2009) 120kw 163cv 2982cm3 Veículo todo-terreno fechado TOYOTA LAND CRUISER PRADO (_J12_) 3.0 D-4D (KDJ120, KDJ125) (07.2004 -08.2009) 122kw 166cv 2982cm3 Veículo todo-terreno fechado TOYOTA LAND CRUISER PRADO (_J12_) 3.0 D-4D (KDJ120, KDJ125, KDJ121) (09.2002 -12.2010) 127kw 173cv 2982cm3 Veículo todo...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA LITEACE Autocarro (_R2_) 2.0 D (CR21LG) (01.1992 -05.1994) 53kw 72cv 1974cm3 Autocarro TOYOTA LITEACE Autocarro (_R2_) 2.2 (YR22LG) (01.1992 -01.1995) 72kw 98cv 2237cm3 Autocarro TOYOTA LITEACE Caixa (_M2_) 1.3 (KM20) (10.1979 -10.1986) 42kw 57cv 1290cm3 Caixa TOYOTA LITEACE Caixa (_M3_, _M4_) 1.5 (KM31_V, KM36_V) (05.1986 -09.1991) 51kw 69cv 1486cm3 Caixa TOYOTA LITE...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA RAV 4 I (_A1_) 2.0 (09.1997 -09.2000) 95kw 129cv 1998cm3 SUV TOYOTA RAV 4 I (_A1_) 2.0 (SXA15G, SXA16_) (06.1997 -09.1999) 99kw 135cv 1998cm3 SUV TOYOTA RAV 4 I (_A1_) 2.0 4WD (SXA10, SXA11) (07.1996 -06.2000) 94kw 128cv 1998cm3 SUV TOYOTA RAV 4 I (_A1_) 2.0 4WD (SXA10, SXA11) (06.1994 -06.2000) 95kw 129cv 1998cm3 SUV TOYOTA RAV 4 I Cabrio (_A1_) 2.0 4WD (SXA11) (12.1...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA RAV 4 II (_A2_) 1.8 (ZCA25_, ZCA26_) (08.2000 -11.2005) 92kw 125cv 1794cm3 SUV TOYOTA RAV 4 II (_A2_) 2.0 (ACA26) (09.2000 -12.2003) 110kw 150cv 1998cm3 SUV TOYOTA RAV 4 II (_A2_) 2.0 4WD (ACA21, ACA20) (05.2000 -11.2005) 110kw 150cv 1998cm3 SUV TOYOTA RAV 4 II (_A2_) 2.0 D 4WD (CLA20_, CLA21_) (05.2001 -11.2005) 85kw 116cv 1995cm3 SUV TOYOTA RAV 4 II (_A2_) 2.4 (ACA2...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA RAV 4 III (_A3_) 2.0 (ZSA35_) (12.2008 -06.2013) 116kw 158cv 1987cm3 SUV TOYOTA RAV 4 III (_A3_) 2.0 4WD (ACA30_) (02.2006 -06.2013) 112kw 152cv 1998cm3 SUV TOYOTA RAV 4 III (_A3_) 2.0 4WD (ZSA30_) (12.2008 -06.2013) 116kw 158cv 1987cm3 SUV TOYOTA RAV 4 III (_A3_) 2.2 D (ALA35_) (12.2008 -06.2013) 110kw 150cv 2231cm3 SUV TOYOTA RAV 4 III (_A3_) 2.2 D 4WD (ALA30_) (02...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA RAV 4 IV (_A4_) 2.0 4WD (ZSA44_) (12.2012 -) 111kw 151cv 1987cm3 SUV TOYOTA RAV 4 IV (_A4_) 2.0 4WD (ZSA44_) (04.2015 -) 112kw 151cv 1987cm3 SUV TOYOTA RAV 4 IV (_A4_) 2.0 D (ALA40_) (12.2012 -11.2018) 91kw 124cv 1998cm3 SUV TOYOTA RAV 4 IV (_A4_) 2.0 D (VWA42_) (10.2015 -11.2018) 105kw 143cv 1995cm3 SUV TOYOTA RAV 4 IV (_A4_) 2.0 D 4WD (ALA41_) (01.2013 -11.2018) 91k...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA RAV 4 V (_A5_, _H5_) 2.0 (MXAA52) (12.2018 -) 129kw 175cv 1987cm3 SUV TOYOTA RAV 4 V (_A5_, _H5_) 2.0 AWD (MXAA54) (12.2018 -) 129kw 175cv 1987cm3 SUV TOYOTA RAV 4 V (_A5_, _H5_) 2.0 VVTi (MXAA52) (12.2018 -) 110kw 150cv 1987cm3 SUV TOYOTA RAV 4 V (_A5_, _H5_) 2.0 VVTi (MXAA52) (12.2018 -) 127kw 173cv 1987cm3 SUV TOYOTA RAV 4 V (_A5_, _H5_) 2.5 VVTi AWD (AXAA54) (12.2...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA STARLET (KP6_) 1.0 (KP60) (02.1978 -09.1984) 33kw 45cv 993cm3 Hatchback TOYOTA STARLET (_P7_) 1.0 (EP70L, EP70R) (10.1984 -12.1989) 40kw 54cv 999cm3 Hatchback TOYOTA STARLET (_P7_) 1.3 (EP71L, EP71R) (10.1984 -12.1989) 55kw 75cv 1295cm3 Hatchback TOYOTA STARLET (_P7_) 1.5 D (NP70L, NP70R) (12.1986 -12.1989) 40kw 54cv 1453cm3 Hatchback TOYOTA STARLET (_P8_) 1.0 (EP80_)...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA VERSO (_R2_) 1.6 (ZGR20_) (04.2009 -08.2018) 97kw 132cv 2238cm3 Veículo multiuso TOYOTA VERSO (_R2_) 1.6 D-4D (WAR20_) (11.2013 -08.2018) 82kw 112cv 1598cm3 Veículo multiuso TOYOTA VERSO (_R2_) 1.8 (ZGR21_) (04.2009 -08.2018) 108kw 147cv 1798cm3 Veículo multiuso TOYOTA VERSO (_R2_) 2.0 D-4D (AUR20_) (11.2012 -08.2018) 91kw 124cv 1998cm3 Veículo multiuso TOYOTA VER...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>TOYOTA YARIS (_P13_) 1.0 (KSP130_) (12.2010 -) 51kw 69cv 998cm3 Hatchback TOYOTA YARIS (_P13_) 1.3 (NSP130_) (09.2011 -) 73kw 99cv 1329cm3 Hatchback TOYOTA YARIS (_P13_) 1.4 D (NLP130_) (09.2011 -) 66kw 90cv 1364cm3 Hatchback TOYOTA YARIS (_P13_) 1.5 Hybrid (NHP130_) (04.2015 -) 74kw 101cv 1497cm3 Hatchback TOYOTA YARIS (_P13_) 1.5 Hybrid (NHP130_) (03.2012 -) 74kw 101cv 149...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>SSANGYONG KORANDO (K5, K9) 2.2 D (12.1988 -12.1996) 50kw 68cv 2238cm3 Veículo todo-terreno fechado SSANGYONG KORANDO (KJ) 2.0 (05.1997 -10.2002) 94kw 128cv 1998cm3 Veículo todo-terreno fechado SSANGYONG KORANDO (KJ) 2.3 (05.1997 -02.2000) 103kw 140cv 2295cm3 Veículo todo-terreno fechado SSANGYONG KORANDO (KJ) 2.3 (01.1999 -11.2006) 105kw 143cv 2295cm3 Veículo todo-te...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>SSANGYONG MUSSO (FJ) 2.0 (10.1996 -05.2005) 93kw 126cv 1998cm3 Veículo todo-terreno fechado SSANGYONG MUSSO (FJ) 2.3 (10.1996 -11.2002) 103kw 140cv 2295cm3 Veículo todo-terreno fechado SSANGYONG MUSSO (FJ) 2.3 (04.2003 -08.2006) 110kw 150cv 2295cm3 Veículo todo-terreno fechado SSANGYONG MUSSO (FJ) 2.3 D (10.1995 -04.1999) 59kw 80cv 2299cm3 Veículo todo-terreno fechad...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 90942-01021 - 90942-01059 - 90942-01082 - 90942-01104</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>SSANGYONG REXTON / REXTON II (GAB_) 2.3 RX230 4x4 (05.2002 -08.2006) 110kw 150cv 2295cm3 SUV SSANGYONG REXTON / REXTON II (GAB_) 2.7 D 4x4 (06.2006 -) 137kw 186cv 2696cm3 SUV SSANGYONG REXTON / REXTON II (GAB_) 2.7 Xdi (08.2004 -) 120kw 163cv 2696cm3 SUV SSANGYONG REXTON / REXTON II (GAB_) 2.7 Xdi (03.2005 -08.2006) 121kw 165cv 2696cm3 SUV SSANGYONG REXTON / REXTON II (GAB_...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 08002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI ACCENT I (X-3) 1.3 (10.1994 -01.2000) 44kw 60cv 1341cm3 Hatchback HYUNDAI ACCENT I (X-3) 1.3 (10.1994 -01.2000) 55kw 75cv 1341cm3 Hatchback HYUNDAI ACCENT I (X-3) 1.3i 12V (10.1994 -01.2000) 62kw 84cv 1341cm3 Hatchback HYUNDAI ACCENT I (X-3) 1.5 i 12V (10.1994 -01.2000) 65kw 88cv 1495cm3 Hatchback HYUNDAI ACCENT I (X-3) 1.5 i 16V (12.1995 -01.2000) 73kw 99cv 14...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>

	<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI ACCENT II (LC) 1.3 (01.2000 - 11.2005) 55kw 75cv 1341cm3 Hatchback HYUNDAI ACCENT II (LC) 1.3 (08.2002 - 11.2005) 62kw 84cv 1341cm3 Hatchback HYUNDAI ACCENT II (LC) 1.3 (01.2000 - 11.2005) 63kw 86cv 1341cm3 Hatchback HYUNDAI ACCENT II (LC) 1.5 (01.2000 - 11.2005) 66kw 90cv 1495cm3 Hatchback HYUNDAI ACCENT II (LC) 1.5 (01.2000 - 10.2002) 68kw 92cv 1495cm3 Hatchback HY...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI ACCENT III (MC) 1.4 GL (11.2005 - 11.2010) 71kw 97cv 1399cm3 Hatchback HYUNDAI ACCENT III (MC) 1.5 CRDI GLS (11.2005 - 11.2010) 81kw 110cv 1493cm3 Hatchback HYUNDAI ACCENT III (MC) 1.6 GLS (11.2005 - 11.2010) 82kw 112cv 1599cm3 Hatchback HYUNDAI ACCENT III três volumes (MC) 1.4 GL (11.2005 - 11.2010) 71kw 97cv 1399cm3 três volumes HYUNDAI ACCENT III três volumes (...)</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI ACCENT IV três volumes (RB) 1.6 (11.2010 -) 90kw 122cv 1591cm3 três volumes HYUNDAI ACCENT IV três volumes (RB) 1.6 (11.2010 -) 91kw 123cv 1591cm3 três volumes HYUNDAI ACCENT IV três volumes (RB) 1.6 CRDI (04.2011 -) 100kw 136cv 1582cm3 três volumes HYUNDAI ACCENT IV três volumes (RB) 1.6 GDI (11.2010 -) 103kw 140cv 1591cm3 três volumes HYUNDAI ACCENT V três...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI ATOS (MX) 1.0 i (02.1998 - 12.2000) 40kw 54cv 999cm3 Hatchback HYUNDAI ATOS (MX) 1.0 i (02.1998 - 03.2002) 41kw 56cv 999cm3 Hatchback HYUNDAI ATOS (MX) 1.0 i (03.2001 - 07.2003) 43kw 58cv 999cm3 Hatchback HYUNDAI ATOS (MX) 1.1 (08.2003 - 12.2008) 43kw 58cv 1086cm3 Hatchback HYUNDAI ATOS (MX) 1.1 (06.2003 - 12.2010) 45kw 61cv 1086cm3 Hatchback HYUNDAI ATOS (MX) 1.1 (0...)</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI COUPE I (RD) 2.0 16V (08.1996 - 04.2002) 102kw 139cv 1975cm3 Coupé</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI COUPE II (GK) 1.6 16V (03.2002 - 08.2009) 77kw 105cv 1599cm3 Coupé HYUNDAI COUPE II (GK) 1.6 16V (03.2002 - 08.2009) 79kw 107cv 1599cm3 Coupé HYUNDAI COUPE II (GK) 2.0 (08.2001 - 08.2009) 100kw 136cv 1975cm3 Coupé HYUNDAI COUPE II (GK) 2.0 (03.2002 - 08.2009) 102kw 139cv 1975cm3 Coupé HYUNDAI COUPE II (GK) 2.0 GLS (02.2003 - 08.2009) 105kw 143cv 1975cm3 Coupé HY...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI ELANTRA III (XD) 1.6 (06.2000 - 07.2006) 79kw 107cv 1599cm3 Hatchback HYUNDAI ELANTRA III (XD) 1.6 (09.2003 - 07.2006) 82kw 112cv 1599cm3 Hatchback HYUNDAI ELANTRA III (XD) 1.6 (06.2000 - 07.2006) 66kw 90cv 1599cm3 Hatchback HYUNDAI ELANTRA III (XD) 1.6 (05.2003 - 07.2006) 77kw 105cv 1599cm3 Hatchback HYUNDAI ELANTRA III (XD) 1.8 (06.2000 - 07.2006) 97kw 132cv 1795cm...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI ELANTRA IV três volumes (HD) 1.6 CRDi (11.2005 - 12.2011) 85kw 116cv 1582cm3 três volumes HYUNDAI ELANTRA IV três volumes (HD) 2.0 CVVT (06.2006 - 05.2010) 103kw 140cv 1975cm3 três volumes</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI ELANTRA V três volumes (MD, UD) 1.6 (06.2011 - 12.2015) 97kw 132cv 1591cm3 três volumes HYUNDAI ELANTRA V três volumes (MD, UD) 1.6 CRDi (02.2011 - 12.2015) 94kw 128cv 1582cm3 três volumes HYUNDAI ELANTRA V três volumes (MD, UD) 1.8 (09.2010 -) 110kw 150cv 1797cm3 três volumes</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI ELANTRA VI três volumes (AD, ADA) 1.6 (02.2016 -) 94kw 128cv 1591cm3 três volumes HYUNDAI ELANTRA VI três volumes (AD, ADA) 1.6 D (02.2016 -) 100kw 136cv 1582cm3 três volumes HYUNDAI ELANTRA VI três volumes (AD, ADA) 2.0 (10.2015 -) 112kw 152cv 1999cm3 três volumes</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI GALLOPER II (JK-01) 2.5 Tci D 08.1998 - 12.2003 77kw 105cv 2476cm3 Veículo todo-terreno fechado HYUNDAI GALLOPER II (JK-01) 2.5 TD 08.1998 - 12.2003 65kw 88cv 2476cm3 Veículo todo-terreno fechado HYUNDAI GALLOPER II (JK-01) 2.5 TD intercooler 08.1998 - 12.2003 73kw 99cv 2476cm3 Veículo todo-terreno fechado HYUNDAI GALLOPER II (JK-01) 3.0 V6 08.1998 - 12.2003 104kw...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI GETZ (TB) 1.1 (09.2005 - 06.2009) 49kw 67cv 1086cm3 Hatchback HYUNDAI GETZ (TB) 1.3 (09.2003 - 09.2005) 63kw 85cv 1341cm3 Hatchback HYUNDAI GETZ (TB) 1.3 i (09.2002 - 03.2004) 60kw 82cv 1341cm3 Hatchback HYUNDAI GETZ (TB) 1.4 i (08.2005 - 12.2010) 71kw 97cv 1399cm3 Hatchback HYUNDAI GETZ (TB) 1.5 CRDI (03.2003 - 09.2005) 60kw 82cv 1493cm3 Hatchback HYUNDAI GETZ (TB) ...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI H-1 / STAREX Autocarro (A1) 2.4 (06.1997 - 04.2004) 82kw 112cv 2351cm3 Autocarro HYUNDAI H-1 / STAREX Autocarro (A1) 2.4 4WD (02.1998 - 04.2004) 82kw 112cv 2351cm3 Autocarro HYUNDAI H-1 / STAREX Autocarro (A1) 2.5 CRDi (06.2006 - 12.2007) 81kw 110cv 2497cm3 Autocarro HYUNDAI H-1 / STAREX Autocarro (A1) 2.5 CRDi (12.2002 - 09.2007) 103kw 140cv 2497cm3 Autocarro HYUNDAI...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI H100 Autocarro (P) 2.4 01.1997 - 03.2000) 84kw 114cv 2351cm3 Autocarro HYUNDAI H100 Autocarro (P) 2.4 07.1993 - 03.2000) 90kw 122cv 2351cm3 Autocarro HYUNDAI H100 Autocarro (P) 2.5 D 12.1994 - 03.2000) 57kw 78cv 2476cm3 Autocarro HYUNDAI H100 Autocarro (P) 2.5 TD 07.1993 - 03.2000) 59kw 80cv 2476cm3 Autocarro HYUNDAI H100 Caixa 2.5 D 12.1994 - 03.2000) 57kw 78cv 2476...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI KAUAI (OS, OSE, OSI) 1.0 T-GDi (07.2017 -) 88kw 120cv 998cm3 SUV HYUNDAI KAUAI (OS, OSE, OSI) 1.6 CRDi (08.2018 -) 85kw 116cv 1598cm3 SUV HYUNDAI KAUAI (OS, OSE, OSI) 1.6 CRDi e-VGT (08.2018 -) 100kw 136cv 1598cm3 SUV HYUNDAI KAUAI (OS, OSE, OSI) 1.6 CRDi e-VGT AWD (08.2018 -) 100kw 136cv 1598cm3 SUV HYUNDAI KAUAI (OS, OSE, OSI) 1.6 T-GDi (07.2017 -) 130kw 177cv 1591...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI MATRIX (FC) 1.5 CRDi (10.2001 - 08.2010) 60kw 82cv 1493cm3 Veículo multiuso HYUNDAI MATRIX (FC) 1.5 CRDi (12.2004 - 08.2010) 75kw 102cv 1493cm3 Veículo multiuso HYUNDAI MATRIX (FC) 1.5 CRDi VGT (08.2005 - 08.2010) 81kw 110cv 1493cm3 Veículo multiuso HYUNDAI MATRIX (FC) 1.6 (06.2001 - 08.2010) 76kw 103cv 1599cm3 Veículo multiuso HYUNDAI MATRIX (FC) 1.8 (06.2001 - ...)</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>

	<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI PONY (X-2) 1.3 (10.1989 - 01.1995) 43kw 58cv 1298cm3 Hatchback HYUNDAI PONY (X-2) 1.3 (10.1989 - 01.1995) 49kw 67cv 1298cm3 Hatchback HYUNDAI PONY (X-2) 1.5 (10.1989 - 01.1995) 53kw 72cv 1468cm3 Hatchback HYUNDAI PONY (X-2) 1.5 i (10.1989 - 01.1995) 61kw 83cv 1468cm3 Hatchback HYUNDAI PONY (X-2) 1.5 i (10.1989 - 01.1995) 62kw 84cv 1468cm3 Hatchback HYUNDAI PONY / EXC...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI SANTA FE IV (TM, TMA) 2.0 CRDi (07.2018 - 07.2020) 110kw 150cv 1995cm3 SUV HYUNDAI SANTA FE IV (TM, TMA) 2.0 CRDi (02.2018 - 07.2020) 137kw 186cv 1995cm3 SUV HYUNDAI SANTA FE IV (TM, TMA) 2.0 CRDi AWD (07.2018 - 07.2020) 110kw 150cv 1995cm3 SUV HYUNDAI SANTA FE IV (TM, TMA) 2.0 CRDi AWD (02.2018 - 07.2020) 137kw 186cv 1995cm3 SUV HYUNDAI SANTA FE IV (TM, TMA) 2.2 CRD...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI SANTA FE I (SM) 2.0 (08.2001 - 03.2006) 99kw 135cv 1997cm3 SUV HYUNDAI SANTA FE I (SM) 2.0 CRDi (08.2001 - 03.2006) 83kw 113cv 1991cm3 SUV HYUNDAI SANTA FE I (SM) 2.0 CRDi 4x4 (04.2001 - 03.2006) 83kw 113cv 1991cm3 SUV HYUNDAI SANTA FE I (SM) 2.0 CRDi 4x4 (08.2003 - 03.2006) 92kw 125cv 1991cm3 SUV HYUNDAI SANTA FE I (SM) 2.0 CRDi Tracção integral (11.2003 - 02...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI SANTA FE II (CM) 2.0 CRDi (12.2010 - 12.2012) 110kw 150cv 1995cm3 SUV HYUNDAI SANTA FE II (CM) 2.0 CRDi 4x4 (03.2006 - 12.2012) 135kw 184cv 1995cm3 SUV HYUNDAI SANTA FE II (CM) 2.2 CRDi (03.2006 - 12.2012) 102kw 139cv 2188cm3 SUV HYUNDAI SANTA FE II (CM) 2.2 CRDi (03.2006 - 12.2009) 114kw 155cv 2188cm3 SUV HYUNDAI SANTA FE II (CM) 2.2 CRDi (01.2009 - 12.2012) 14...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI SANTA FE III (DM, DMA) 2.0 CRDi (09.2012 - ) 110kw 150cv 1995cm3 SUV HYUNDAI SANTA FE III (DM, DMA) 2.0 CRDi (05.2015 - ) 136kw 185cv 1995cm3 SUV HYUNDAI SANTA FE III (DM, DMA) 2.0 CRDi 4WD (09.2012 - ) 110kw 150cv 1995cm3 SUV HYUNDAI SANTA FE III (DM, DMA) 2.2 CRDi (09.2012 - 12.2015) 145kw 197cv 2199cm3 SUV HYUNDAI SANTA FE III (DM, DMA) 2.2 CRDi (10.2015 - ) 147k...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI SONATA II (Y-2) 3.0 i V6 (01.1991 - 10.1993) 107kw 145cv 2972cm3 três volumes HYUNDAI SONATA III (Y-3) 1.8 i (05.1993 - 06.1998) 72kw 98cv 1796cm3 três volumes HYUNDAI SONATA III (Y-3) 2.0 i (08.1996 - 06.1998) 70kw 95cv 1997cm3 três volumes HYUNDAI SONATA III (Y-3) 2.0 i (06.1994 - 08.1996) 77kw 105cv 1997cm3 três volumes HYUNDAI SONATA III (Y-3) 2.0 i 16V (06...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI SONATA IV (EF) 2.4 16V (03.1998 - 10.2001) 105kw 143cv 2351cm3 três volumes HYUNDAI SONATA IV (EF) 2.5 V6 24V (06.1998 - 10.2001) 118kw 160cv 2493cm3 três volumes HYUNDAI SONATA IV (EF) 2.7 V6 (10.2001 - 11.2004) 127kw 173cv 2656cm3 três volumes</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI SONATA V (NF) 2.0 CRDi (02.2006 - 12.2010) 100kw 136cv 1991cm3 três volumes HYUNDAI SONATA V (NF) 2.0 CRDi (02.2006 - 12.2010) 103kw 140cv 1991cm3 três volumes HYUNDAI SONATA V (NF) 2.0 CRDi (03.2009 - 12.2010) 110kw 150cv 1991cm3 três volumes HYUNDAI SONATA V (NF) 2.0 GLSi (07.2008 - 12.2010) 119kw 162cv 1998cm3 três volumes HYUNDAI SONATA V (NF) 2.0 VVTi GLS (0...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI TERRACAN (HP) 2.5 TD (12.2001 - 12.2006) 74kw 101cv 2476cm3 SUV HYUNDAI TERRACAN (HP) 2.5 TD 4WD (12.2001 - 12.2006) 74kw 101cv 2476cm3 Caixa/SUV HYUNDAI TERRACAN (HP) 2.9 CRDi 4WD (12.2001 - 12.2006) 110kw 150cv 2902cm3 SUV HYUNDAI TERRACAN (HP) 2.9 CRDi 4WD (11.2003 - 12.2006) 120kw 163cv 2902cm3 SUV HYUNDAI TERRACAN (HP) 2.9 CRDi 4WD (11.2001 - 12.2006) 110kw 150c...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI TIBURON Coupé 2.0 CVT (10.2006 - 12.2008) 105kw 143cv 1975cm3 Coupé HYUNDAI TIBURON Coupé 2.7 (01.2006 - 12.2008) 123kw 167cv 2656cm3 Coupé</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI TRAJET (FO) 2.0 (01.2004 - 07.2008) 103kw 140cv 1975cm3 Veículo multiuso HYUNDAI TRAJET (FO) 2.0 (03.2001 - 10.2003) 103kw 140cv 1997cm3 Veículo multiuso HYUNDAI TRAJET (FO) 2.0 (03.2000 - 07.2008) 100kw 136cv 1997cm3 Veículo multiuso HYUNDAI TRAJET (FO) 2.0 CRDi (04.2001 - 07.2008) 83kw 113cv 1991cm3 Veículo multiuso HYUNDAI TRAJET (FO) 2.0 CRDi (08.2005 - 07.200...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI TUCSON (JM) 2.0 (08.2004 - ) 104kw 141cv 1975cm3 SUV HYUNDAI TUCSON (JM) 2.0 CRDi (08.2004 - 03.2010) 83kw 113cv 1991cm3 SUV HYUNDAI TUCSON (JM) 2.0 CRDi (01.2007 - 03.2010) 88kw 120cv 1991cm3 SUV HYUNDAI TUCSON (JM) 2.0 CRDi (01.2006 - 03.2010) 100kw 136cv 1991cm3 SUV HYUNDAI TUCSON (JM) 2.0 CRDi (01.2006 - 03.2010) 103kw 140cv 1991cm3 SUV HYUNDAI TUCSON (JM) 2.0 CRD...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI VELOSTER (FS) 1.6 GDI (03.2011 - 12.2017) 103kw 140cv 1591cm3 Coupé HYUNDAI VELOSTER (FS) 1.6 MPI (04.2011 - 12.2017) 97kw 132cv 1591cm3 Coupé HYUNDAI VELOSTER (FS) 1.6 T-GDI (10.2012 - 12.2017) 137kw 186cv 1591cm3 Coupé</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI i10 I (PA) 1.0 (01.2011 - 12.2017) 51kw 69cv 998cm3 Hatchback HYUNDAI i10 I (PA) 1.1 (12.2007 - 12.2013) 48kw 65cv 1086cm3 Hatchback HYUNDAI i10 I (PA) 1.1 (01.2008 - 12.2013) 49kw 67cv 1086cm3 Hatchback HYUNDAI i10 I (PA) 1.1 (11.2008 - 12.2013) 50kw 68cv 1086cm3 Hatchback HYUNDAI i10 I (PA) 1.1 (04.2011 - 12.2013) 51kw 69cv 1086cm3 Hatchback HYUNDAI i10 I (PA) 1.1 ...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI i10 II (BA, IA) 1.0 (08.2013 - ) 49kw 67cv 998cm3 Hatchback HYUNDAI i10 II (BA, IA) 1.0 LPG (02.2014 - ) 49kw 67cv 998cm3 Hatchback HYUNDAI i10 II (BA, IA) 1.0 LPG (07.2014 - 08.2016) 51kw 69cv 998cm3 Hatchback HYUNDAI i10 II (BA, IA) 1.2 (12.2013 - ) 64kw 87cv 1248cm3 Hatchback</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI i20 ACTIVE (IB, GB) 1.0 T-GDI (09.2015 - ) 74kw 101cv 998cm3 Hatchback HYUNDAI i20 ACTIVE (IB, GB) 1.0 T-GDI (09.2015 - ) 88kw 120cv 998cm3 Hatchback HYUNDAI i20 ACTIVE (IB, GB) 1.4 (09.2015 - ) 74kw 101cv 1368cm3 Hatchback HYUNDAI i20 ACTIVE (IB, GB) 1.4 CRDi (09.2015 - ) 66kw 90cv 1396cm3 Hatchback HYUNDAI i20 I (PB, PBT) 1.1 CRDi (03.2012 - 12.2015) 55kw 75cv 1120cm3 ...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>

	<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI i20 II (GB, IB) 1.0 T-GDI (01.2016 -) 74kw 101cv 998cm3 Hatchback HYUNDAI i20 II (GB, IB) 1.0 T-GDI (01.2016 -) 88kw 120cv 998cm3 Hatchback HYUNDAI i20 II (GB, IB) 1.1 CRDi (11.2014 -) 55kw 75cv 1120cm3 Hatchback HYUNDAI i20 II (GB, IB) 1.2 (11.2014 -) 55kw 75cv 1248cm3 Hatchback HYUNDAI i20 II (GB, IB) 1.2 (11.2014 -) 62kw 84cv 1248cm3 Hatchback HYUNDAI i20 II (GB, ...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI i30 (FD) 1.6 (10.2007 - 11.2011) 85kw 116cv 1591cm3 Hatchback HYUNDAI i30 (FD) 1.6 (10.2007 - 11.2011) 90kw 122cv 1591cm3 Hatchback HYUNDAI i30 (FD) 1.6 (02.2008 - 11.2011) 93kw 126cv 1591cm3 Hatchback HYUNDAI i30 (FD) 1.6 CRDi (10.2007 - 11.2011) 66kw 90cv 1582cm3 Hatchback HYUNDAI i30 (FD) 1.6 CRDi (10.2007 - 11.2011) 85kw 116cv 1582cm3 Hatchback HYUNDAI i30 (FD) 2...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI i30 Combi (FD) 1.4 (10.2007 - 06.2012) 77kw 105cv 1396cm3 Combi HYUNDAI i30 Combi (FD) 1.4 (11.2009 - 06.2012) 80kw 109cv 1396cm3 Combi HYUNDAI i30 Combi (FD) 1.6 (02.2008 - 06.2012) 85kw 116cv 1591cm3 Combi HYUNDAI i30 Combi (FD) 1.6 (02.2008 - 06.2012) 90kw 122cv 1591cm3 Combi HYUNDAI i30 Combi (FD) 1.6 (02.2008 - 06.2012) 93kw 126cv 1591cm3 Combi HYUNDAI i30 Combi...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI i40 I (VF) 1.7 CRDi 03.2012 - 05.2019 85 116 1685 três volumes HYUNDAI i40 I (VF) 1.7 CRDi 03.2012 - 05.2019 100kw 136cv 1685cm3 três volumes HYUNDAI i40 I (VF) 2.0 CVVT (03.2012 - 05.2019) 130kw 177cv 1999cm3 três volumes HYUNDAI i40 I (VF) 2.0 CVVT (03.2012 - 05.2019) 121kw 165cv 1999cm3 três volumes HYUNDAI i40 I CW (VF) 1.6 GDI (07.2011 - 05.2019) 99kw 135cv ...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI ix20 (JC) 1.4 (11.2010 - 07.2019) 66kw 90cv 1396cm3 Hatchback HYUNDAI ix20 (JC) 1.4 CRDi (06.2011 - 07.2019) 57kw 78cv 1396cm3 Hatchback HYUNDAI ix20 (JC) 1.4 CRDi (11.2010 - 07.2019) 66kw 90cv 1396cm3 Hatchback HYUNDAI ix20 (JC) 1.6 (11.2010 - 07.2019) 92kw 125cv 1591cm3 Hatchback HYUNDAI ix20 (JC) 1.6 CRDi (06.2011 - 07.2019) 85kw 116cv 1582cm3 Hatchback HYUNDAI ix...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI ix35 (LM, EL, ELH) 1.6 (11.2010 -) 99kw 135cv 1591cm3 SUV HYUNDAI ix35 (LM, EL, ELH) 1.7 CRDi (11.2010 -) 85kw 116cv 1685cm3 SUV HYUNDAI ix35 (LM, EL, ELH) 2.0 (01.2010 - 07.2013) 120kw 163cv 1998cm3 SUV HYUNDAI ix35 (LM, EL, ELH) 2.0 4WD (01.2010 -) 120kw 163cv 1998cm3 SUV HYUNDAI ix35 (LM, EL, ELH) 2.0 4WD (09.2014 - 06.2015) 116kw 158cv 1999cm3 SUV HYUNDAI ix35 (L...</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>
	<p><b>KMB84057</b> NO. 0B002-37160 - 52950-14100 - 52950-14120 - 52950-14140 - 52950-1G000</p> <p><b>KIT TAMPÃO BLOCO DO MOTOR</b></p> <p>HYUNDAI ix55 3.0 V6 CRDi 4WD (09.2008 - 12.2011) 176kw 239cv 2959cm3 SUV HYUNDAI ix55 3.0 V6 CRDi 4WD (09.2011 - 12.2012) 184kw 250cv 2959cm3 SUV HYUNDAI ix55 3.8 V6 (01.2011 -) 194kw 264cv 3778cm3 SUV HYUNDAI ix55 3.8 V6 4WD (01.2011 -) 194kw 264cv 3778cm3 SUV</p> <p>d46x14mm M38x1,5mm 1f-20mm</p>		